



Lowell BF 029-2(14)

Regional Concerns Meeting

VT Route 100– Bridge #234 over the East Branch of Missisquoi River

July 9, 2019

Introductions

Laura Stone, P.E.


VTrans Scoping Engineer

Carolyn Cota, P.E.

VTrans Project Manager

Purpose of Meeting

- Provide an understanding of our approach to the project
- Provide an overview of project constraints
- Discuss our selected alternative
- Provide an opportunity to ask questions and voice concerns



Location Map

Bridge 234
Project Location




East Branch Missisquoi River

Meeting Overview

- VTrans Project Development Process
- Project Overview
 - Existing Conditions
 - Alternatives Considered
 - Selected Alternative
- Maintenance of Traffic
- Schedule
- Summary
- Questions


VTrans Project Development Process



**Accelerated
Bridge
Program**
VTRANS


Who are you representing?

- A. Municipal Official
- B. Resident of Lowell
- C. Resident of
Neighboring Town
- D. Emergency Services
- E. Local Business
- F. Independent
Organization
- G. Press
- H. Other




How often do you use this segment of VT Route 100?

- A. Daily
- B. Weekly
- C. Monthly
- D. Rarely
- E. Never




How often do you walk over the bridge?

- A. Daily
- B. Weekly
- C. Monthly
- D. Rarely
- E. Never




How often do you bike over the bridge?

- A. Daily
- B. Weekly
- C. Monthly
- D. Rarely
- E. Never



What is your reason for attending this meeting?


- A. Specific concern
- B. General Interest
- C. Live in close vicinity
- D. Other



Project Overview

- Existing Conditions
- Alternatives Considered
- Selected Alternative

Description of Terms Used



**Accelerated
Bridge
Program**
VTRANS



Looking North over Bridge 234

Existing Conditions – Bridge #234

- Roadway Classification – Minor Arterial
- Bridge Type – 43' Long Reinforced Concrete T-Beam Bridge
- Ownership – State of Vermont
- Constructed in 1929, Reconstructed (Widened) in 1948

Looking South over Bridge 234



Existing Conditions – Bridge #234

- 11'¼' Existing Typical Section
 - Meets the minimum standard for safety and service
 - Does not meet the minimum shared-use standard of 5-feet
- 30-Degree skew

Existing Conditions – Bridge #234

- Bridge 234 is structurally deficient
- Reinforced Concrete Deck
 - Cracks, leaks, and heavy stains in beam bays 1, 2, and 3
 - Leakage is prevalent along the older section of the deck, with chloride inclusion
- There are 7 concrete T beams - Beams 4 and 5 are butted up next to each other at the widening
 - Heavy deterioration along their lower portions due to years of leakage through the joint between them.
 - Concrete along beam bottoms is spalled away and tension bars are exposed, but with minor loss. Some stirrups have rusted away and there is loss of concrete around the bars.
- Abutments have minor pop outs, cracks and leaks. There is a settlement crack through the upstream end at the south abutment from wingwall rotation.
- The bridge does not meet the minimum standard for hydraulics.

Condition Ratings



Existing Conditions - Bridge #234

- | | |
|-------------------------|------------------|
| ■ Deck Rating | 5 (Fair) |
| ■ Superstructure Rating | 4 (Poor) |
| ■ Substructure Rating | 6 (Satisfactory) |

Deck Condition



Existing Conditions - Bridge #234

- Saturation
- Rust Staining



Western Abutment

Existing Conditions - Bridge #234

- Gravel Bar



Eastern Abutment

Existing Conditions - Bridge #234

- Debris

Scour Issues



Existing Conditions - Bridge #234

Looking Upstream from Bridge 234



Existing Conditions - Bridge #234


- Waterway is confined on the upstream side of the bridge

Resources – Looking Downstream



Existing Conditions - Bridge #234

- Northern Long Eared Bat Habitat
- Wildlife Habitat
- Utilities

A photograph showing the downstream fascia of a concrete bridge. The concrete is heavily deteriorated, with numerous horizontal and vertical cracks and significant spalling, especially along the bottom edge. A metal guardrail with vertical posts is mounted on top of the concrete wall. The background shows a line of trees under a clear blue sky.


Downstream Fascia

Existing Conditions - Bridge #234

- Cracks and spalls

Existing Conditions

PION, BRUCE W. & LAURINE K.



Design Criteria and Considerations

- Average Daily Traffic: 2,900 veh/day
- Design Hourly Volume: 340 veh/hr
- % Trucks: 12.7
- Design Speed: 50 mph
- Aerial Utilities

Alternatives Considered – Bridge #234

- No Action

- Additional maintenance required within 10 years

- Minor Rehabilitation

- Superstructure and Substructure Patching
- 11'¼' typical
- 15 year design life

- Superstructure Replacement

- Abutment Patching
- 40 year design life
- Substandard hydraulically


- Full Bridge Replacement On Alignment

- Maintain horizontal alignment
- Raise vertical alignment by approx. 1 foot to meet minimum hydraulic standard
- 75 year design life


Selected Alternative - Bridge #234

- Full Bridge Replacement
 - 11'/5' typical
 - Span length of approximately 50'
 - Vertical grade raised approximately 1' to meet minimum hydraulics
 - 75 year design life
 - Right of Way Needed
 - Aerial Utility Relocation


Proposed Typical Section



Proposed Layout



Proposed Profile



What Will the New Bridge Look Like?



Proposed Example - Bridge #234

- Integral Abutment with Shallow Superstructure (Slab Bridge Shown)
- Flush Mounted Box Beam Railing

Maintenance of Traffic Options Considered

- Offsite Detour
- Phased Construction
- Temporary Bridge


Selected Method of Traffic Maintenance



Temporary Bridge

- Downstream
- One-Lane Temporary Bridge
- Signal required for One Lane option

Downstream Temp Bridge Layout



Preliminary Project Schedule


- Construction Start – 2022
 - Total Cost Estimate: \$1,995,000

Project Summary

- Full Bridge Replacement with Traffic Maintained on a Temporary Bridge
 - 11'5' typical
 - Span length of approximately 50'
 - Vertical grade raised approximately 1' to meet minimum hydraulics
 - 75 year design life
 - Right of Way Needed
 - Aerial Utility Relocation


Which would you be most concerned about?

- A. Construction delays on VT Route 100
- B. Temporary Bridge Impacts
- C. Bridge Aesthetics
- D. Environmental Impacts
- E. Recreational Impacts
- F. Business Impacts
- G. Other
- H. Not really concerned




Which design aspect is the most important to you?

- A. Shoulder width/bicycle accommodations
- B. Aesthetics - Bridge Railing
- C. Construction year
- D. Construction Duration
- E. Cost
- F. Other



Did you find this presentation to be?


- A. Too technical in nature
- B. Too simplified
- C. Just about right
- D. Not much use at all



Do you find the selected scope of work satisfactory?

A. Yes

B. No



For more information:

- <https://outside.vermont.gov/agency/vtrans/external/Projects/Structures/12B592>



Lowell BF 029-2(14) Questions and Comments

VT Route 100– Bridge #234 over the East Branch of Missisquoi River

July 9, 2019