

ROUTINE PERFORMANCE CHECK REPORT



DataMaster DMT: 100156
Location: FAIR HAVEN PD
Calibration Date: 03/10/2017
Certification Date: 03/10/2017
Installation Date: 03/13/2017
RPC Date: 02/17/2018
Supervisor Name: DALE H KERBER

Diagnostic Results

VERSIONS
DMT: 2.03
PIC: 2.08
Modem: 2.6
Questions: 2.1

TEMPERATURES

Sample Chamber = 48.9°C
Breath Tube = 45.2°C
Digital Sim = 34.0°C

SETTINGS

Lamp Voltage = 1.64 V
Cooler Voltage = 1.71 V
Bias Voltage = 80 V
Chopper Freq = 539 Hz

PUMP INFO

Flow Rate = 5.564 L/M

DETECTOR INFO

PUMP	ON	OFF
MAX(V)	0.0925	0.0970
MIN(V)	0.0909	0.0951

FILTER INFO

Filter	Value	Zero
Filter 1	0.095	true
Filter 2	0.371	true
Filter 3	1.052	true

CALIBRATION CHECK

Xq = 0.097 0.71%

Routine Performance Check Passed

Accuracy and Precision Check


Concentration	= 0.100 g/210L
Lot #	= 17-24-100
Range	= 0.095 - 0.105
Average	= 0.099 g/210L
Std Dev	= 0.0005

RF Detection Test

Passed

Sample Acceptance Test

Passed



Performed by

Dale Kerber

Date

02/17/2018

Reviewed by

[Signature]

Date

2/20/18

DMT Serial Number #100156

Page 1 of 1

02/17/2018 3:53 PM

1 of 3 RCP

ROUTINE PERFORMANCE CHECK REPORT

DataMaster DMT: 100156
Location: FAIR HAVEN PD
Calibration Date: 03/10/2017
Certification Date: 03/10/2017
Installation Date: 03/13/2017
RPC Date: 02/11/2018
Supervisor Name: DALE H KERBER



Diagnostic Results

VERSIONS
DMT: 2.03
PIC: 2.08
Modem: 2.6
Questions: 2.1

TEMPERATURES

Sample Chamber = 48.8°C
Breath Tube = 45.0°C
Digital Sim = 34.0°C

SETTINGS

Lamp Voltage = 1.64 V
Cooler Voltage = 1.71 V
Bias Voltage = 80 V
Chopper Freq = 537 Hz

PUMP INFO

Flow Rate = 5.428 L/M

DETECTOR INFO

PUMP	ON	OFF
MAX(V)	0.0965	0.0998
MIN(V)	0.0935	0.0978

FILTER INFO

Filter 1	0.098	Zero = true
Filter 2	0.374	Zero = true
Filter 3	1.058	Zero = true

CALIBRATION CHECK

Xq = 0.097 0.80%

Routine Performance Check Failed

Accuracy and Precision Check

Concentration	= 0.100 g/210L
Lot #	= 17-24-100
Range	= 0.095 - 0.105
Average	= 0.000 g/210L
Std Dev	= 0.0000
Average out of range	

Performed by



Date

02/11/2018

Reviewed by

Date

Re: February RPC

Driscoll, Rob

Tue 2/13/2018 10:38 AM

Sent Items

To: Kerber, Dale <Dale.Kerber@vermont.gov>;

Thanks Dale,

The instrument should have placed itself out of service until a passing RPC is completed.

Regards,
Rob

Robert Driscoll
Vermont Forensic Laboratory
45 State Drive
Waterbury, VT 05671
Electronics Technician
Rob.Driscoll@Vermont.gov
Desk: (802) 241-5817
Cell: (802) 585-0123

From: Kerber, Dale
Sent: Tuesday, February 13, 2018 10:28:34 AM
To: Driscoll, Rob
Subject: RE: February RPC

I pulled a brain malfunction and forgot to plug the simulator solution back into the unit. Once I started seeing the mistake I let the machine fail the check. I have plugged it back in and will be doing the check later as I ran out of time. Should I put the machine of of service until then?

Sent from [Mail](#) for Windows 10

From: [Driscoll, Rob](#)
Sent: Monday, February 12, 2018 9:22 AM
To: [Kerber, Dale](#)
Subject: February RPC

Dale,

I noticed that you had a failed RPC attempt on 2/11/18. I do not see a passing RPC following the failed attempt. What was the cause for the fail? It appears the average concentration came out to 0.00?

Regards,

100156

3 of 3 RD