STATE OF VERMONT AGENCY OF TRANSPORTATION

Scoping Report

FOR FERRISBURGH BF 019-4(35)

US ROUTE 7, BRIDGE 139 OVER LEWIS CREEK

May 8, 2024



Table of Contents

Та	able of Contents	2
ı.	Site Information	4
	Need	4
	Traffic	4
	Design Criteria	5
	Inspection Report Summary	5
	Hydraulics	6
	Utilities	6
	Right Of Way	7
	Environmental and Cultural Resources	7
	Biological:	7
	Archeological:	8
	Historic:	
	Hazardous Materials:	
	Stormwater:	
	Landscape Clearance	
II.	•	
	. Local Concerns	
	7. Operations Concerns	
٧.	Maintenance of Traffic	9
	Option 1: Off-Site Detour	10
	Option 2: Phased Construction	10
	Option 3: Temporary Bridge	11
VI	. Alternatives Discussion	12
	No Action	12
	Deck Rehabilitation	12
	Deck Replacement	13
	Superstructure Replacement	14
VI	II. Alternatives Summary	15
VI	III. Cost Matrix	16
IX.	Conclusion	17
x.	Appendices	18
	Appendix A: Town Map	19
	Appendix B: Bridge Inspection Report	21

Appendix C: Preliminary Hydraulics Memo	39
Appendix D: Preliminary Geotechnical Memo	42
Appendix E: Resource ID Completion Memo	53
Appendix F: Natural Resources Memo	55
Appendix G: Archeology Memo	87
Appendix H: Historic Memo	107
Appendix I: Environmental Specialist Resource ID	109
Appendix J: Hazardous Sites Map	111
Appendix K: Stormwater Resource ID	113
Appendix L: Landscape Clearance Resource ID	115
Appendix M: Utilities Resource ID	118
Appendix N: Local Input Questionnaire	120
Appendix O: Operations Input Questionnaire (blank)	126
Appendix P: Crash Data	129
Appendix Q: Detour Maps	132
Appendix R: Plans	138

I. Site Information

Bridge 139 is a State-owned bridge located on US Route 7 in the Town of Ferrisburgh approximately 4.9 miles north of the junction with VT Route 22A. The existing conditions were gathered from a combination of a Site Visit, the Inspection Report, the Route Log and the existing Survey. See correspondence in the Appendix for more detailed information.

Roadway Classification Principal Arterial (National Highway System)
Bridge Type Three Span Continuous Rolled Beam Bridge

Bridge Length 286 feet Year Built 1957

Ownership State of Vermont

Need

Bridge 139 carries US Route 7 across Lewis Creek. The following is a list of deficiencies of Bridge 139 and US Route 7 in this location:

- 1. The reinforced concrete deck is in fair condition with a few areas of spalling that extend the full width of the bays and penetrate up to and beyond the first layer of reinforcing steel. There is also moderate to heavy saturation throughout the deck with efflorescence, varying sized delaminations, and map cracking throughout the fascia.
- 2. The steel girder superstructure is in satisfactory condition with areas of rust scale at the beam ends and scattered small locations along the flanges with minor pitting and section loss.
- 3. The reinforced concrete substructure is in good condition with scattered shrinkage cracks throughout the abutment end walls with light staining and minor saturation.
- 4. The shoulder widths on the bridge are substandard.

Traffic

A traffic study of this site was performed by the Vermont Agency of Transportation. The traffic volumes are projected for the years 2028 and 2048.

TRAFFIC DATA	2028	2048
AADT	11,833	12,981
DHV	1,316	1,444
%T	9.6	12.6
%D	50	50
ADTT	1,527	2,189
Flexible ESALS:	2028~2048	2028~2068
riexidie ESALS:	11,290,000	23,872,000

Design Criteria

The design standards for this bridge project are the Vermont State Standards, dated October 22, 1997. Minimum standards are based on an ADT of 12,981, a DHV of 1,444, and a design speed of 50 mph for a Principal Arterial.

Design Criteria	Source	Existing Condition	Minimum Standard	Comment
Approach Lane and Shoulder Widths	VSS Table 3.3	8'/12'/12'/8' (40')	8'/12'/12'/8' (40')	
Bridge Lane and Shoulder Widths	VSS Table 3.3	3'/12'/12'/3' (30')	10'/12'/10' (44')	Substandard shoulder widths
Clear Zone Distance	VSS Table 3.4	No Issues Noted	24' fill / 12' cut	
Banking	VSS Section 3.13	0.8% - 4%	8% (max)	
Speed	VSS Section 3.3	50 mph (Posted)	50 mph (design)	
Horizontal Alignment	AASHTO Green book Table 3-10b	R = 5,730'	R _{min} = 2,720' @ 4%	
Vertical Grade	VSS Table 3.5	2.31%	4% for level terrain	
K Values for Vertical Curves	AASHTO Table 3-37	$K_{crest} = 164$	84 crest / 96 sag	
Vertical Clearance	VSS Section 3.8	No Issues Noted	16'-3" (min)	
Stopping Sight Distance	AASHTO Table 3-37	267'	425'	
Bicycle/Pedestrian Criteria	VSS Table 3.7	3' shoulder on bridge	5' paved shoulders	Substandard
Hydraulics	VTrans Hydraulics Unit	Existing available freeboard: 21.8ft @ 2% AEP 20.8ft @ 1% AEP	Meets minimum BFW and at least 1ft freeboard at 1% AEP	
Bridge Railing	Structures Design Manual Section 13	Curb mounted three rail aluminum railing	TL-4	Not Crash Tested
Structural Capacity	Structures Design Manual, Ch. 3.4.1	Not Deficient	Design Live Load: HL- 93	

Inspection Report Summary

Deck Rating 5 Fair

Superstructure Rating 6 Satisfactory

Substructure Rating 7 Good Channel Rating 8 Very Good

From the Bridge Inspection Reports:

05/10/2023 – Deck: Moderate to heavy saturation throughout with efflorescence, varying sized delaminations, and small areas of rust staining. There are a few areas of spalling that extend the full width of the bays and penetrate up to and beyond the first layer of reinforcing. Bays 3 and 4 have large areas of timber form work in place along spans 1 and 2. Deck curb in poor condition, voided spall and failed patched areas, and exposed reinforcing. Deck Fascia has map cracking throughout with varying amounts of efflorescence staining and scattered small delaminations. Superstructure: Rust scale at the beam ends and scattered small locations along the flanges with minor pitting/section loss. Substructure: Scattered shrinkage cracks with light staining and minor saturation. Continued saturation and deterioration throughout the deck, a deck replacement project should be considered see maintenance report. ~JW

05/06/2021 – Deck: Moderate to heavy saturation throughout w/ efflorescence-stained cracking, varying sized delaminations, small areas of rust staining, and a few spalls that penetrate to the first

layer of reinforcing. Bays 3 and 4 have large areas of timber form work in place along spans 1 and 2. Curbing - Deep voided spalls and failed patched areas w/ exposed reinforcing along the granite facing throughout. The abutment 1 curb ends are spalled out w/ exposed reinforcing leaving the old sliding steel plates undermined and unsupported. Stringers have rust scale at the beam ends and scattered small locations along the flanges w/ minor pitting/section loss. Bearings have rust scale throughout the abutment 1 bearings w/ minor pitting/section loss. End walls and abutment seat/stems have scattered shrinkage cracks w/ light staining and minor saturation. Due to the widespread saturation and deterioration throughout the deck it should be considered for replacement. The soffit has visible moderate to heavy saturation throughout w/ scattered spalls and delaminations. The curbs also continue to spall out with deep voids and exposed reinforcing along the granite facing. ~JW/SP

05/29/2019 – Bridge is in satisfactory shape. The substandard and damaged aluminum and concrete bridge rail system needs full upgrading. This particular rail type has all but been eliminated elsewhere, as it is not adequate. Rail replacement may even add some additional horizontal clearance depending on the type used. The deck, which has had some localized distress in span #2 and subsequent shoring, should be considered for rehabilitation or perhaps the option of full replacement in 20 years or so. Note: The formwork in span #2, was thought to have been a response to areas of full depth failure but turned out to have been installed to address only delamination's and some spalling. Prior deck replacement recommendations were based on assumed holes; though distress was not as severe as once thought. The expansion joint at the south abutment leaks and there is curb distress allowing for heavy leakage, along with damage to the curb plating, which is a target for plow wing impact. The curb plating needs removal and the curb repaired. ~ MJ/SP

Hydraulics

Lewis Creek flows beneath Bridge 139. The existing bridge span appears to meet state stream equilibrium standards for bankfull width based on the 200 ft clear span of the existing bridge. For reference, the Phase II Stream Geomorphic Assessment completed by the Agency of Natural Resources reported a bankfull width of approximately 84 ft through this section of Lewis Creek. There is approximately 21.8 ft and 20.8 ft of freeboard at the 2% AEP and 1% AEP, respectively. The existing structure does meet current standards of the VTrans Hydraulic Manual and appears to meet state stream equilibrium standards for bankfull width.

During the preliminary hydraulic assessment, it was discovered from bridge inspection photos that there may be bank erosion occurring at the abutments. A stone fill size was provided in the hydraulics memo (see Appendix C) for any necessary bank and abutment armoring.

Utilities

The existing utilities are shown on the Existing Conditions Layout Sheet, and are as follows:

Aerial:

- Comcast
- Consolidated Communications
- Firstlight Fiber
- Green Mountain Power
- Waitsfield Champlain Valley Telecom

Underground:

• Consolidated Communications

Municipal:

• There are no Municipal utilities within the project limits.

The aerial utilities in the project area are located over 230 feet west of the bridge and will not be in conflict with project work. Consolidated has a buried Fiber line in a 4" PVC conduit which hangs off the west side of the bridge which will likely need to be relocated.

Right Of Way

The existing Right-of-Way (ROW) is plotted on the Existing Conditions Layout Sheet. There is ample State-Owned Right-of-Way on either side of US Route 7. It is assumed that additional rights will not be needed for construction.

Environmental and Cultural Resources

The environmental resources present at this project are shown on the Existing Conditions Layout Sheet, and are as follows:

Biological:

VTrans Environmental hired the consultant, VHB, to perform a natural resource evaluation at this site. For additional information on all natural resources, see the Existing Conditions Layout Sheet and the Natural Resources Memo in Appendix F.

Wetlands/Watercourse

There were four Class II wetland complexes delineated within the project study area when the field survey was completed by the consultant. Two of the larger wetland complexes are located along the banks of Lewis Creek directly underneath the bridge around the abutments.

Lewis Creek passes under US Route 7 through Bridge 139. Additionally, the consultant identified a perennial unnamed tributary to the south of Lewis Creek which passes under US Route 7 via a culvert.

Rare, Threatened, and Endangered Species

There were no state listed Rare, Threatened, and Endangered Species present at Bridge 139.

The project was submitted to the US Fish and Wildlife Service (USFWS) via the online Information for Planning and Consultation (IpaC) webtool, and an Official Species List was generated on October 13, 2023, to identify federally listed species within the project area. Federally listed species that have the potential to occur in the project area include the monarch butterfly (*Danaus 7lexippus*) and northern long-eared bat (*Myotis septentrionalis*).

Wildlife Habitat

Through field visits done as part of the resource identification process, it was determined that Bridge 139 does not impede the passage of aquatic organisms, and also provides a terrestrial travel opportunity for wildlife movement under the bridge within the riparian zone along the edge of Lewis Creek. The US Route 7 corridor was found to be a fragmenting feature effecting habitat

connectivity in the area. Further fragmentation would not be anticipated from this project unless a temporary bridge was required to be installed off alignment.

Archeological:

The VTrans Archeologist conducted a site visit on August 29th, 2023 to assess the archaeological sensitivity of the project area. The field visit determined that areas outside the US Route 7 roadway prism and footprint of disturbance from the construction of Bridge 139 should be considered sensitive for precontact archaeological resources. Unless these archaeologically sensitive areas can be avoided by project developments, further field investigations will be required.

Historic:

Bridge 139 is likely not historic as it is a common steel girder interstate bridge constructed around the 1950s.

Hazardous Materials:

No hazardous waste sites were identified within the proposed project area.

Stormwater:


A stormwater resource ID was performed for this project and based on a review of available mapping and project photos. It appears that there are no drainage structures within the project area. Depending on the extent of the project limits and roadway approach work, improvements to the drainage from the roadway leading to either side of the bridge should be considered. And, to the extent that drainage work is conducted as part of this project, it is encouraged that it be aligned with the VTrans Phosphorus Control Highway Drainage Management Standards, as this may allow future credit toward achieving phosphorus reduction goals required by the Agency's TS4 permit.

Landscape Clearance

A landscape resource ID was performed for this project and recommendations included 1) minimizing riparian buffer disturbance and tree clearing, 2) maintaining and improving wide shoulders for bike access as this project is located within a high use/priority bicycle route, and 3) if found in the project area, develop a plan for managing invasive species. A riparian planting plan should be developed for any disturbed riparian areas on this project.

II. Safety

There have been 91 crashes along US Route 7 in Ferrisburgh in the last six-year period. 17 of those crashes were within 1 mile of the project area. The structure is not located within a designated high crash location section based on the High Crash Location Report 2012-2016.



III. Local Concerns

A local concerns questionnaire was sent to the Town of Ferrisburgh. The town responded to the questionnaire and provided input on bike and pedestrian usage of the current bridge and corridor as well as RTE species occurrences in the project area. A copy of the questionnaire can be found in Appendix N.

IV. Operations Concerns

An Operations questionnaire was sent to the VTrans maintenance District 5. The district did not respond to the questionnaire. There is a copy of the blank questionnaire in Appendix O.

V. Maintenance of Traffic

The Vermont Agency of Transportation has created an Accelerated Bridge Program, which focuses on faster delivery of construction plans, permitting, and Right of Way, as well as faster construction of projects in the field. One practice that helps in this endeavor is closing bridges for portions of the construction period, rather than providing temporary bridges. In addition to saving money, the intention is to minimize the closure period with faster construction techniques and incentives to contractors to complete projects early. The Agency will consider the closure option on most projects

where rapid reconstruction or rehabilitation is feasible. The use of prefabricated elements in new bridges will also expedite construction schedules. This can apply to decks, superstructures, and substructures. Accelerated Construction should provide enhanced safety for the workers and the travelling public while maintaining project quality. The following options have been considered:

Option 1: Off-Site Detour

This option would close the bridge and reroute traffic onto an official, signed State detour. There is one regional detour that could be used if the bridge is closed during construction. The potential State-signed detour is as follows:

1. US Route 7, to VT Route 17 to VT Route 116, to VT Route 2A, to Interstate I-89, to Route 189, back to US Route 7 (60.1 miles end-to-end).

This likely would be signed and used as a truck detour for through truck traffic.

A separate detour utilizing Federal Aid Secondary (FAS) roads could be signed as a passenger car detour route. Local traffic would likely utilize either the below FAS detour route via Monkton Road, or local bypass routes available in the area. The passenger car detour route located along FAS routes is as follows:

1. US Route 7, to Monkton Road, to Hollow Road, to Old Hollow Road, back to US Route 7 (18.5 miles end-to-end).

There are many local bypass routes available in the area that will likely see an increase in traffic from local passenger cars if US Route 7 is closed during construction. Local bypass routes are not signed detours but may experience higher traffic volumes during a road closure. The two most likely local bypass routes are as follows:

- 1. US Route 7, to Dakin Road, to Four Winds Road, to Old Hollow Road, back to US Route 7 (4.2 miles end-to-end).
- 2. US Route 7, to Greenbush Road, to Stage Road, back to US Route 7 (5.5 miles end-to-end).

A map of the detour routes can be found in Appendix Q.

Advantages: This option would have minimal impacts to natural and cultural resources located up and downstream of the structure. This option reduces the time and cost of the project both at the development stage and construction. This is the safest traffic control option since the traveling public is removed from the construction site. There are many detour routes available for both vehicular traffic including a regional detour, a FAS detour route, and multiple paved local bypass routes.

Disadvantages: Traffic flow would not be maintained through the project corridor during construction.

Option 2: Phased Construction

Phased construction is the maintenance of one lane of traffic on the existing bridge while working on the other lane. The project begins with traffic being constricted to one lane, while work is done on the other. After completion of improvements to the first lane, traffic is switched to the completed lane and work proceeds on the second lane. Traffic flow is constant, although delayed due to slower speeds in the work zone. This allows keeping the road open during construction, while having minimal impacts to adjacent property owners and environmental resources.

While the time required to develop a phased construction project would remain the same, the time required to complete a phased construction project increases because some of the construction tasks have to be performed multiple times. In addition to the increased design and construction costs mentioned above, the costs also increase for phased construction because of the inconvenience of working around traffic and the effort involved in coordinating the joints between the phases. Another negative aspect of phased construction is the decreased safety of the workers and vehicular traffic, which is caused by increasing the proximity and extending the duration that workers and moving vehicles are operating in the same confined space. Phased construction is usually considered when the benefits include reduced impacts to natural and cultural resources and decreased costs and development time by not requiring the purchase of additional ROW.

With phased construction, one side of each bridge deck would be constructed while traffic on US Route 7 is reduced from 2-lanes to 1-lane. Based on traffic volumes through this section of US Route 7, two lanes of traffic would be required to be maintained with this maintenance of traffic option. Unfortunately, maintaining two lanes of traffic would not be feasible based on the existing bridge geometry and beam configuration. One lane of traffic could be maintained by using a traffic signal, but would cause major traffic delays and backups on US Route 7 during peak hours.

Advantages: Traffic flow would be maintained through the project corridor during construction. Also, this option would have minimal impacts to adjacent properties and environmental and cultural resources. Right-of-Way would not be required for this maintenance of traffic option. Phasing the work allows the work to proceed one lane at a time without the expense of a temporary bridge and without the inconvenience of a closure and detour.

Disadvantages: Compared to a closure and detour or a temporary bridge scenario, it takes longer and costs more to construct, rehabilitate, or repair a bridge project in phases because some of the construction tasks have to be performed multiple times and cannot be performed concurrently. Additional permit requirements may come into play. The safety risks for both workers and travelers are also increased due to the close proximity to each other. Some structural qualities, such as joints, demand more coordination time and may suffer in quality as well. Two lanes of traffic flow would not be able to be maintained with this option based on existing bridge geometry.

Option 3: Temporary Bridge

Based on the length between stop bars for placement of a temporary bridge and the traffic volumes along US Route 7 at this location, a temporary bridge would need to have two lanes to accommodate two-way traffic.

From a constructability standpoint, a temporary bridge could be placed either east or west of the existing structure and roadway corridor. A temporary bridge on either side of the road would require major tree clearing efforts, buried utility relocation, and would impact natural and cultural resources on either side of the bridge.

Additional costs would be incurred to construct a temporary bridge, including the cost of fill for the approaches and the bridge itself, installation and removal of the temporary bridge and approaches, and restoration of the disturbed area.

If a temporary bridge is chosen as the preferred method of traffic control, based on the traffic volumes, it should be a two-lane bridge. See the Temporary Bridge Layout Sheets in Appendix R.

Advantages: Traffic flow can be maintained along the US Route 7 corridor.

Disadvantages: This option would require a potential utility relocation and would have adverse impacts to natural and cultural resources. There would be decreased safety for the workers and to vehicular traffic, because of cars driving near the construction site, and construction vehicles entering and exiting the construction site. This traffic control option would be more costly and time consuming than an offsite detour.

VI. Alternatives Discussion

This project was identified by Asset Management as a good candidate for bridge deck replacement. The objective of this scoping process is to apply a cost-effective treatment at the proper time to preserve and extend the useful life of the bridge. Preventative maintenance provides the biggest benefit for the smallest level of investment. By either repairing or replacing the bridge deck or superstructure, the service life of the superstructure and substructure can be maximized by protecting them from exposure to the elements that have caused the deck to deteriorate to its current condition. Therefore, the alternatives analysis was limited to the bridge deck and superstructure exclusively.

No Action

This alternative is not recommended. The bridge is declining in structural condition and will continue to deteriorate if no action is taken. The bridge deck has large areas of heavy saturation, efflorescence staining, and areas of delamination and spalling that extend the full width of the bays and penetrate beyond the first layer of reinforcing. The superstructure has rust scale at the beam ends and scattered section loss along the beam flanges. In the interest of safety to the traveling public, the No Action alternative is not recommended. No cost estimate has been provided for this alternative since there are no immediate costs.

Deck Rehabilitation

The existing deck of Bridge 139 is rated as a 5, or "fair" condition. The superstructure, referring to the steel beams, is rated a 6 ("satisfactory"), and the existing substructure is rated a 7 ("good"). Deck patching would include removal of loose and deteriorating concrete, cleaning and possibly supplementing reinforcing steel, application of patching materials to cracks and areas of section loss, and paving on the bridge and for a short distance on each approach to the bridge. Some characteristics of deck patching are as follows:

• Patching tends to accelerate the deterioration of the existing concrete that is in contact with the patching material, and thus offers a widely variable service life often 15 years or less.

- Much of the work would take place underneath the bridge with efforts required to avoid contamination of Lewis Creek.
- In approximately 15 years, the condition of the bridge would be similar to its current condition and major work would be required again.
- The bridge does not meet the minimum standard width with a 12'/3' typical section. The existing 3-foot-wide shoulders do not meet the minimum standard for shared-use by bicycles and pedestrians.

The disadvantages seem to outweigh the benefits to this short-term fix. Deck rehabilitation alone will not be considered further.

Deck Replacement

This alternative would involve removing the existing deck in its entirety and placing a new wider deck on the existing steel beams. In addition to replacing the bridge deck and bridge railing, some repair work on the curtain walls between the wingwall and concrete repair made to the pier caps would be required. Work to be included for a deck replacement project includes:

- There is rust scale at the beam ends and scattered small locations along the beam flanges with minor section loss. The beams should be inspected and cleaned as needed, and the failing joints replaced.
- There is rust scale throughout the abutment 1 bearings with minor section loss. Bearings should be inspected and replaced as needed.
- There are scattered shrinkage cracks with minor saturation in the abutment end walls. Silane should be applied to all exposed substructure concrete as part of the project.
- A new composite deck with the typical section of 5'-12'-12'-5' would be constructed.

The existing substructure is in good condition, and it is reasonable to assume that it can safely carry anticipated traffic loads for an additional 40 years.

The existing deck geometry does not meet the minimum standard for bridge roadway width of 40-feet as set forth in the Vermont State Standards. A new deck on the existing beams should ideally be wide enough to meet minimum standards but would not be possible based on the existing geometry of the outer girders and available overhang. A more feasible bridge deck width would improve the existing bridge width to 34-feet with a 5'-12'-12'-5' typical section, which meets the minimum shared-use standard. The bridge deck width will be decided and finalized in the design phase of this project.

Advantages: This alternative would address the structural concerns of the bridge and extend the life of the existing structure an additional 40 years. This alternative will protect the superstructure for years to come from exposure to the elements. This option would also have minimal impacts to adjacent properties and resources.

Disadvantages: The new deck would have a design life greater than that of the remaining substructures and the bridge typical, while improved, would still not be up to design standards.

Maintenance of Traffic: Traffic could be maintained on an offsite detour, a temporary bridge, or with phased construction.

Superstructure Replacement

A superstructure replacement would include a new deck, beams, and bridge railing. The new superstructure would be a new steel beam bridge, similar to the existing superstructure. Substructure repairs and modifications to accommodate the new superstructure would be as follows:

- There are scattered shrinkage cracks with minor saturation in the abutment end walls. Silane should be applied to all exposed substructure concrete as part of the project.
- The existing bridge seats would be cut down and new bridge seats and wingwalls would be poured to accommodate the new, wider superstructure.
- A new deck with a typical section of 5'-12'-12'-5' would be constructed.

The existing substructure is in satisfactory condition, and it is reasonable to assume that with the repairs listed above, the existing substructure can safely carry anticipated traffic loads for an additional 40 years.

The existing 3-foot-wide shoulders do not meet the minimum standard. A new superstructure should be constructed to a minimum rail-to-rail width of 34-feet; 12-foot lanes, with 5-foot shoulders. It should be evaluated in design if the existing substructures could accommodate a wider width to match the existing roadway corridor width more closely. This could be achieved by increasing the number of beams from six to seven.

Advantages: This alternative would address the structural concerns of the bridge and extend the life of the existing structure an additional 40 years. This alternative will protect the superstructure for years to come from exposure to the elements which have deteriorated the deck. This option would also have minimal impacts to adjacent properties and resources. This option would eliminate future maintenance concerns for the beams.

Disadvantages: The new superstructure would have a design life greater than that of the remaining substructures and the bridge typical, while improved, may still not be up to design standards.

Maintenance of Traffic: Traffic could be maintained on an offsite detour, a temporary bridge, or with phased construction.

VII. Alternatives Summary

Based on the existing site conditions and bridge condition there are several viable alternatives:

- Alternative 1: Deck Rehabilitation with Traffic Maintained via Temporary Lane Closures
- Alternative 2a: Deck Replacement with Traffic Maintained on an Offsite Detour
- Alternative 2b: Deck Replacement with Traffic Maintained via Phased Construction
- Alternative 2c: Deck Replacement with Traffic Maintained on a Temporary Bridge
- Alternative 3a: Superstructure Replacement with Traffic Maintained on an Offsite Detour
- Alternative 3b: Superstructure Replacement with Traffic Maintained via Phased Construction
- Alternative 3c: Superstructure Replacement with Traffic Maintained on a Temporary Bridge

A cost evaluation for each of the alternatives is shown below.

VIII. Cost Matrix¹

			Alternative 1		Alternative 2			Alternative 3		
	Ferrisburgh BF 019-4(35)	Do Nothing	Deck Rehabilitation		Deck Replacement		Superstructure Replacement			
			a. Temporary Lane Closures	a. Offsite Detour	b. Phased Construction	c. Temporary Bridge	a. Offsite Detour	b. Phased Construction	c. Temporary Bridge	
	Bridge Cost	\$0	\$787,700	\$913,300	\$1,050,300	\$913,300	\$4,254,700	\$4,892,900	\$4,254,700	
	Removal of Structure	\$0	\$0	\$834,000	\$959,100	\$834,000	\$834,000	\$959,100	\$834,000	
	Roadway	\$0	\$110,000	\$450,000	\$647,000	\$450,000	\$513,000	\$737,000	\$513,000	
	Maintenance of Traffic	\$0	\$85,490	\$348,300	\$734,100	\$1,154,040	\$348,300	\$734,100	\$1,154,040	
	Construction Costs	\$0	\$983,190	\$2,545,600	\$3,390,500	\$3,351,340	\$5,950,000	\$7,323,100	\$6,755,740	
COOT	Construction Engineering & Contingencies	\$0	\$294,957	\$636,400	\$847,625	\$837,835	\$892,500	\$1,098,465	\$1,013,361	
COST	Accelerated Premium	\$0	\$0	\$178,192	\$0	\$0	\$416,500	\$0	\$0	
	Total Construction Costs w CEC	\$0	\$1,278,147	\$3,360,192	\$4,238,125	\$4,189,175	\$7,259,000	\$8,421,565	\$7,769,101	
	Preliminary Engineering	\$0	\$294,957	\$254,560	\$271,240	\$268,107	\$892,500	\$1,098,465	\$1,013,361	
	Right of Way	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	
	Total Project Costs	\$0	\$1,573,104	\$3,614,752	\$4,509,365	\$4,457,282	\$8,151,500	\$9,520,030	\$8,782,462	
	Annualized Costs	\$0	\$104,874	\$90,369	\$112,734	\$111,432	\$203,788	\$238,001	\$219,562	
TOWN SHARE				No Town Share						
TOWN %				No Town Snar	e					
	Project Development Duration	NA	2 years	2 years	2 years	2 years	2 years	2 years	2 years	
SCHEDULEING	Construction Duration	NA	3 months	4 months	8 months	8 months	4 months	8 months	8 months	
	Closure Duration (If Applicable)	NA	NA	30 days	NA	NA	45 days	NA	NA	
	Typical Section - Roadway (feet)	40	40	40	40	40	40	40	40	
	Typical Section - Bridge (feet)	3'/12'/12'/3' (30)	3'/12'/12'/3' (30)		5'/12'/12'/5' (34')			51/121/121/51 (341)		
	Geometric Design Criteria	Substandard Width	Substandard Width		Substandard Width		Substandard Width			
	Traffic Safety	No Change	No Change	Improved	Improved	Improved	Improved	Improved	Improved	
ENGINEERING	Alignment Change	No Change	No Change	No Change	No Change	No Change	No Change	No Change	No Change	
ENGINEERING	Bicycle Access	No Change	No Change	Improved	Improved	Improved	Improved	Improved	Improved	
	Pedestrian Access	No Change	No Change	No Change	No Change	No Change	No Change	No Change	No Change	
	Hydraulics	No Change	No Change	No Change	No Change	No Change	No Change	No Change	No Change	
	Utilities	No Change	No Change	Likely require	es underground utili	ty relocation	Likely requi	res underground util	ity relocation	
	ROW Acquisition	No	No	No	No	No	No	No	No	
OTHER	Road Closure	No	No	Yes	No	No	Yes	No	No	
	Design Life	10	15	40	40	40	40	40	40	

¹ Costs are estimates only, used for comparison purposes.

IX. Conclusion

Our recommendation is **Alternative 2a**; to replace the existing deck using a maximum 30-day closure and offsite detour.

Structure:

This alternative includes replacing the deck with a new precast or cast-in-place concrete deck using a maximum 30-day bridge closure and offsite detour. A deck replacement will also include new bridge railing, membrane, and pavement. Additionally, shear studs will be welded to the existing beams for a composite deck. Providing a continuous deck should be evaluated in design to eliminate the joints over the piers. During design, accelerated bridge construction will be investigated to reduce the 30-day closure duration.

Bank armoring should also be included as part of this project in order to mitigate the observed erosion at the abutment banks.

The new deck will match the existing geometry in regard to vertical and horizontal alignment. By increasing the deck overhang, the existing 3-foot-wide shoulders can be increased to 5-feet. While this does not meet the minimum standard of 8-feet, a 5-foot shoulder meets the minimum shared use standards.

Traffic Control:

The recommended method of traffic control is to close the bridge for 30 days and maintain traffic on an offsite detour. There are many available local bypass and FAS detour routes for vehicular traffic to use during the bridge closure. It is recommended that the State-signed truck detour utilize VT Route 17 to VT Route 116, VT Route 2A, Interstate I-89, and Route 189, back to US Route 7. There are numerous local bypass routes located around the bridge site that are expected to be used by passenger cars. During design, VTrans will evaluate those routes for signal timing modifications and the addition of signals at key intersections.

There are 9.6% trucks, and the separate truck route on VT Route 116 is recommended for through truck traffic. This will require a robust public outreach effort to the trucking community.


US Route 7 through the project area is classified as a heavily used bicycle route and accommodations for bicycle traffic should be considered in design.

Due to the narrow geometry of the bridge, maintaining two-way traffic via phased construction is not a feasible option. A two-lane temporary bridge constructed on either side of the existing bridge would have major impacts to natural and cultural resources and is the most expensive option.

X. Appendices

- Appendix A: Town Map
- Appendix B: Bridge Inspection Report
- Appendix C: Preliminary Hydraulics Memo
- Appendix D: Preliminary Geotechnical Information
- Appendix E: Resource Identification Completion Memo
- Appendix F: Natural Resources Memo
- Appendix G: Archeology Memo
- Appendix H: Historic Memo
- Appendix I: Environmental Specialist Resource ID
- Appendix J: Hazardous Sites Map
- Appendix K: Stormwater Resource ID
- Appendix L: Landscape Clearance Resource ID
- Appendix M: Utilities Resource ID
- Appendix N: Local Input
- Appendix O: Operations Input
- Appendix P: Crash Data
- Appendix Q: Detour Map
- Appendix R: Plans

Appendix A: Town Map



This map was funded in part through grants from the Federal Highway Administration, U.S. Department of Transportation. The representation of the authors expressed herein do not necessarily state or reflect those of the U.S. Department of Transportation.

Appendix B: Bridge Inspection Report






Town: 78 - FERRISBURGH


District 5, 1 - ADDISON County

Owner: 1 - State Highway Agency

Maintenance Responsibility: 1 - State Highway Agency







44.24823, -73.22920





US 00007 ML over LEWIS CREEK

IDENTIFIC	ATION
(1) State Names	50 - Vermont
(8) Structure Number	200019013901052
(5) Inventory Route	1
(2) Highway Agency District	5 - District 5
(3) County Code	1 - ADDISON
(4) Place Code	26275
(6) Features Intersected	LEWIS CREEK
(7) Facility Carried	US 00007 ML
(9) Location	4.9 MI N JCT. VT.22A
(11) Mile Point (12) Base Highway Network	116.715 mi Yes
(13) LRS Inventory Rte & Subrte	0010000007
(16) Latitude	44.2482305555556
(17) Longitude	-73.2291972222222
(98) Border Bridge State Code	10.220101222222
(99) Border Bridge Structure No.	
STRUCTURE TYPE	AND MATERIAL
(43) Main Structure Type	42
Material	4 - Steel continuous
Туре	2 - Stringer/Multi-beam or girder
(44) Approach Structure Type	00
Material	0 - Other
Type	0 - Other
(45) No. of Spans in Main Unit	3
(46) No. of Approach Spans	0
(107) Deck Structure Type	1 - Concrete Cast-in-Place
(108) Wearing Surface/Protective Syste Type of Wearing Surface	
Type of Wearing Surface Type of Membrane	6 - Bituminous 2 - Preformed Fabric
Type of Membrane Type of Deck Protection	0 - None
AGE AND S	
(27) Year Built	1957
(106) Year Reconstructed	0
(42) Type of Service	15
On	1 - Highway
Under	5 - Waterway
(28) Lane	
On	2
Under	0
(29) Average Daily Traffic	11900
(30) Year of ADT	2018
(109) Truck ADT	10 %
(19) Bypass, Detour Length	20 mi
GEOMETRI (48) Length of Maximum Span	100 ft
(49) Structure Length	286 ft
(50) Curb or Sidewalk Width	200 11
(00) 0000 00 00000000000000000000000000	Left 1.5 ft
	Right 1.5 ft
(51) Bridge Roadway Width Curb to Cur	
(52) Deck Width Out to Out	35.4 ft
(32) Approach Roadway Width (W/Shou	
(33) Bridge Median	0 - No median
(34) Skew	45 Deg
(35) Structure Flared	0 - No flare
(10) Inventory Route Min Vert Clear	99.99 ft
(47) Inventory Route Total Horiz Clear	30 ft
(53) Min Vert Clear Over Bridge Rdwy	99.99 ft
(54) Min Vert Underclear	0 ft
Ref: (55) Min Lat Underclear RT	0 ft
Ref:	
(56) Min Lat Underclear LT	0 ft
NAVIGATIO	
(38) Navigation Control (111) Pier Protection	0 - No navigation control on w
(39) Navigation Vertical Clearance	0 ft
(116) Vert-Lift Bridge Nav Min Vert Clea	
(40) Navigation Horizontal Clearance	0 ft
1.0, . arigation monizontal oldarance	011

(112) NBIS Bridge Length	ICATION Y
(104) Highway System	
(26) Functional Class	2 - Rural Principal Arterial
(100) Defense Highway	1 - The inventory route is or
(101) Parallel Structure	N - No parallel structure exis
(102) Direction of Traffic	2 - way traffic
(103) Temporary Structure	,
(105) Federal Lands Highways	0 - N/A
(110) Designated National Network	0 - The inventory route is no
(20) Toll	3 - On free road. The structu
(21) Maintain	1 - State Highway Agency
(22) Owner	1 - State Highway Agency
(37) Historical Significance	5 - Bridge is not eligible for
	OITION
(58) Deck	
· ,	5
(59) Superstructure	6
(60) Substructure	7
(61) Channel & Channel Protection	3
(62) Culverts	N. AND ROSERVIC
	AND POSTING
(31) Design Load	4 - M 18 / H 20
(63) Operating Rating Method	1
(64) Operating Rating	
Туре	1 - Load Factor(LF)
Rating	55
(65) Inventory Rating Method	1 - Load Factor(LF)
(66) Inventory Rating	
Туре	9
Rating	g 33
(70) Bridge Posting	5 - Equal to or above legal loads
(41) Structure Open/Posted/Closed	A - Open, no restriction
APPR	AISAL
(67) Structural Evaluation	6
(68) Deck Geometry	4
(69) Clearances, Vertical/Horizontal	N
(71) Waterway Adequacy	3
(72) Approach Roadway Alignment	3
(36A) Bridge Railings	0 - Inspected feature does not meet
(36B) Transitions	0 - Inspected feature does not meet
(36C) Approach Guardrail	Inspected feature meets current
(36D) Approach Guardrail Ends	Inspected feature meets current
(113) Scour Critical Bridges	8 - Bridge foundations determined
·	-
	PROVEMENTS
(75) Type of Work	35 - Bridge rehabilitation bed
(76) Length of Structure Improvement	
(94) Bridge Improvement Cost (Multip	
(95) Roadway Improvement Cost (Mu	
(96) Total Project Cost (Multiply value	
(97) Year of Improvement Cost Estim	ate 2020
(114) Future ADT	12495
(115) Year of Future ADT	2028
INCDEC	TIONS *
(90) Inspection Date	05/10/2023
(91) Frequency	Davis From (Man)
(92) Critical Feature Inspection	Done Freq. (Mon) Date
A: Fracture Critical Detail	No
B: Underwater Inspection	No
C: Other Special Inspection	
* The inspection date and frequence	y information in this box contains information. Please refer to the







Deck

ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
12	Reinforced Concrete Deck	SF	10124	0	7974	2100	50
1080	Delamination/Spall/Patched Area	SF	2150	0	2000	100	50
1120	Efflorescence/Rust Staining	SF	7974	0	5974	2000	0
510	Wearing Surfaces	SF	8580	8580	0	0	0
301	Pourable Joint Seal	LF	42	42	0	0	0
303	Assembly Joint with Seal	LF	35	18	17	0	0
2360	Adjacent Deck or Header	LF	17	0	17	0	0
330	Metal Bridge Railing	LF	572	286	114	172	0
7000	Damage	LF	286	0	114	172	0
804	Concrete Fascia	LF	572	0	372	200	0
1080	Delamination/Spall/Patched Area	LF	72	0	72	0	0
1120	Efflorescence/Rust Staining	LF	500	0	300	200	0

58 - Deck (5 - FAIR CONDITION - all primary structural elements are sound but may have minor section loss, cracking, spalling or scour.)

Moderate to heavy saturation throughout with efflorescence, varying sized delams, and small areas of rust staining. There are a few areas of spalling that extend the full width of the bays and penetrate up to and beyond the first layer of reinforcing. Bays 3 and 4 have large areas of timber form work in place along spans 1 and 2.

200 - Existing Wearing Surface Depth (3")

A21 - Deck Wearing Surface Condition (1 - Very Good)

A24 - Deck Curb Condition (5 - Poor)

Deep voided spalls and failed patched areas with exposed reinforcing along the granite facing throughout. The abutment 1 curb ends hare spalled out with exposed reinforcing leaving the old sliding steel plates undermined and unsupported.

A36 - Deck Joint Trough Condition (1 - Very Good)

A38 - Deck Drain Condition (5 - Poor)

The deck drains have completely rotted out. the Vermont joints galvanized down spout drain is in good condition.

A39 - Deck Fascia Condition (3 - Satisfactory)

Map cracking throughout with varying amounts of efflorescence staining and scattered small delams. The fascia soffits have moderate to heavy saturation with efflorescence and scattered rust staining. The upstream soffit has scattered lineal spalls with exposed reinforcing as well.

B.C.05 Bridge Railing Condition Rating (FAIR - Some moderate defects; strength and performance of the component are not affected.)

Aluminum tube steel rail is in good condition. The concrete pedestals have large delamed areas with rust staining and spalls with exposed reinforcing throughout. Sections of the upstream rail has had repairs with new pedestals installed at the abutment ends and near mid span with W beam rail added

B.C.08 Bridge Joints Condition Rating (VERY GOOD - Some inherent defects.)



US 00007 ML over LEWIS CREEK



APPROACH

72 - Approach Roadway Alignment (8 - Equal to present desirable criteria)

A13 - Approach Rail Condition (1 - Very Good)

AGENCY OF TRANSPORTATION

A16 - Approach Post Condition (1 - Very Good)





Superstructure

ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
107	Steel Open Girder/Beam	LF	1716	1458	172	86	0
1000	Corrosion	LF	258	0	172	86	0
515	Steel Protective Coating	SF	14872	11010	2970	744	148
3420	Peeling/Bubbling/Cracking	LF	3862	0	2970	744	148
311	Movable Bearing	EA	12	0	6	6	0
1000	Corrosion	EA	12	0	6	6	0
313	Fixed Bearing	EA	12	6	4	2	0
1000	Corrosion	EA	6	0	4	2	0

59 - Superstructure (6 - SATISFACTORY CONDITION - structural elements show some minor deterioration.) Rust scale at the beam ends and scattered small locations along the flanges with minor pitting/section loss.

A55 - Lateral Bracing Condition (1 - Very Good)

B.C.07 Bridge Bearings Condition Rating (GOOD - Some minor defects.)

Rust scale throughout the abutment 1 bearings with minor pitting/section loss.

B.C.14 NSTM Inspection Condition (NOT APPLICABLE - Component does not exist.)





Substructure

ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
205	Reinforced Concrete Column	EA	6	6	0	0	0
215	Reinforced Concrete Abutment	LF	100	80	20	0	0
1120	Efflorescence/Rust Staining	LF	20	0	20	0	0
234	Reinforced Concrete Pier Cap	LF	100	100	0	0	0

60 - Substructure (7 - GOOD CONDITION - some minor problems.)

Scattered shrinkage cracks with light staining and minor saturation.

A71 - Abutment End Walls Condition (3 - Good)

Scattered shrinkage cracks with light staining and minor saturation.

A81 - Pier Seat/Cap Condition (2 - Very Good)

A83 - Pier Shaft Condition (2 - Very Good)

A85 - Pier Columns Condition (2 - Very Good)

A86 - Pier Footings Condition (2 - Very Good)

CHANNEL

61 - Channel Condition (8 - Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition.)


GENERAL OBSERVATION

Continued saturation and deterioration throughout the deck, a deck replacement project should be considered see maintenance report.



District: 5, County: 1

ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
12	Reinforced Concrete Deck	SF	10124	0	7974	2100	50
1080	Delamination/Spall/Patched Area	SF	2150	0	2000	100	50
1120	Efflorescence/Rust Staining	SF	7974	0	5974	2000	0
510	Wearing Surfaces	SF	8580	8580	0	0	0
107	Steel Open Girder/Beam	LF	1716	1458	172	86	0
1000	Corrosion	LF	258	0	172	86	0
515	Steel Protective Coating	SF	14872	11010	2970	744	148
3420	Peeling/Bubbling/Cracking	LF	3862	0	2970	744	148
205	Reinforced Concrete Column	EA	6	6	0	0	0
215	Reinforced Concrete Abutment	LF	100	80	20	0	0
1120	Efflorescence/Rust Staining	LF	20	0	20	0	0
234	Reinforced Concrete Pier Cap	LF	100	100	0	0	0
301	Pourable Joint Seal	LF	42	42	0	0	0
303	Assembly Joint with Seal	LF	35	18	17	0	0
2360	Adjacent Deck or Header	LF	17	0	17	0	0
311	Movable Bearing	EA	12	0	6	6	0
1000	Corrosion	EA	12	0	6	6	0
313	Fixed Bearing	EA	12	6	4	2	0
1000	Corrosion	EA	6	0	4	2	0
330	Metal Bridge Railing	LF	572	286	114	172	0
7000	Damage	LF	286	0	114	172	0
804	Concrete Fascia	LF	572	0	372	200	0
1080	Delamination/Spall/Patched Area	LF	72	0	72	0	0
1120	Efflorescence/Rust Staining	LF	500	0	300	200	0



US 00007 ML over LEWIS CREEK




Team Lead: Justin White, Inspection Date: 05/10/2023


Channel Profile

Waterway Flow: West to East Top of Water: 32ft at upstream station 7


Origin: Fascia beams Bottom of Beam:


Station	Distance	Downstream	Upstream
Abutment 2 + 70ft	0	33.6	30.7
2	18	33.3	
2	20		32.6
3	38	35.6	
3	40		35.5
4	58	36	
4	60		35.8
5	78	36	
5	80		34.8
6	98	35.5	
6	100		33.8
7	118		32.3
7	118	33	
8	138		27.7
8	138	27.3	





US 00007 ML over LEWIS CREEK





AGENCY OF TRANSPORTATION

36 [⊥]



Route US7 /
Structure #00139 / (Routine)

US 00007 ML over LEWIS CREEK





South approach North approach





Downstream curb Downstream curb







Guardrail pedestals




Guardrail pedestals



Upstream repaired rail



Abutment 1 joint









Abutment 1 downstream curb/joint end




Abutment 1 upstream curb/joint end



Abutment 2 joint



Downstream fascia










Span 1 Upstream fascia





Spalls Span 1 bays 1 and 3

Span 2



US 00007 ML over LEWIS CREEK





Spall span 2 bay 3

Span 3






Abutment 1 bearings

Pier 2





Team Lead: Justin White, Inspection Date: 05/10/2023





Abutment 1





Team Lead: Justin White, Inspection Date: 05/10/2023

Maintenance Needs

Date Reported: 05/10/2023

AGENCY OF TRANSPORTATION

Priority:Status:OpenType of Work:8 - Deck - Deck replacementComponent:Deck

Deficiency Description

Moderate to heavy saturation throughout with efflorescence, varying sized delams, and small areas of rust staining. There are a few areas of spalling that extend the full width of the bays and penetrate up to and beyond the first layer of reinforcing. Bays 3 and 4 have large areas of timber form work in place along spans 1 and 2.

Remarks

A deck replacement project should be considered.



Spalls Span 1 bays 1 and 3



Spall span 2 bay 3

Appendix C: Preliminary Hydraulics Memo



State of Vermont Structures and Hydraulics Section Barre City Place 219 North Main Street, Barre, VT 05641

vtrans.vermont.gov

[phone] 802-595-6493

Agency of Transportation

TO: Laura Stone, Structures Scoping Project Manager

CC: Patrick Ross, Hydraulics Engineer

FROM: Madeline Glow, Hydraulics Project Engineer

DATE: April 16, 2024

SUBJECT: Ferrisburgh BF 019-4(35), pin#22B390: Preliminary Hydraulics Memo

Site Location: Ferrisburgh, US-7 (300 feet north of Lewis Creek Dr), BR 139 over Lewis Creek

Coordinates: 44.24823, -73.22920

We have completed our hydraulic study for the above referenced site, and offer the following for your use:

ANR Coordination/ Bankfull Width

A site visit to measure bankfull width was not completed because the existing bridge is most likely going to be rehabilitated. For reference, the Phase II Stream Geomorphic Assessment completed by the Agency of Natural Resources reported a bankfull width of approximately 84 ft through this section of Lewis Creek. If the scope of this project changes and a new structure is proposed, further coordination with ANR will be necessary to confirm a minimum clear span that meets equilibrium standards.

Design Flows

US Route 7 is a Principal Arterial corresponding to a hydraulic design flow and scour/countermeasure design flow of 2% AEP (Q50) and 1% AEP (Q100), respectively.

Existing Conditions

- Steel Girder Bridge
- 200 feet +/- hydraulic clear span with a minimum low chord elevation of 148.87 feet.
- There is approximately 21.8 ft and 20.8 ft of freeboard at the 2% AEP and 1% AEP, respectively.
- The existing structure does meet current standards of the VTrans Hydraulic Manual and appears to meet state stream equilibrium standards for bankfull width.

FEMA & FHARC

This project is within the FEMA Special Flood Hazard Area without Base Flood Elevations (Zone A). Any replacement or temporary structure option that encroaches the existing floodplain will trigger the Flood Hazard Area & River Corridor Rule (FHA&RC) General Permit at a minimum and further coordination with the hydraulics unit may be needed. This analysis did not include any temporary impacts associated with construction fill and/or a temporary bridge.



Stone Fill

Stone Fill, Type II should be used for any necessary bank and abutment armoring and to protect any disturbed channel banks or roadway slopes. Please coordinate with the hydraulics unit regarding stone fill limits and extents during preliminary design.

Additional Comments

If the scope of this project changes in ways that would affect the low chord elevation or abutment locations, please notify the Hydraulics section so we can adjust our analysis. Please contact us with any questions.



Appendix D: Preliminary Geotechnical Memo



Geotechnical Scoping Report Data Form

General Project Information

Project Name:	Ferrisburgh BF 019-4(35)							
Project Pin #	22B390							
Requestor Name:	Laura Stone, P.E., Scoping Engineer							
Prepared By:	E. Thomas, AOT Geologist							
Date:	11/14/2023							
Location	Town		Route			Mile Marke	r	
Information of Structure:	Ferrisburgh US-7 6.2							
Structure Type:	Bridge	Structure	ID #:	Bridge #139	Conceptu Treatmen		Deck	
General	The struct	The structure consists of a continuous steel multi-beam/girder that extends over						
Project	Lewis Cree	Lewis Creek in the Town of Ferrisburgh on US-7. The conceptual treatment stated by						
Description:	Structures	s is a deck re	eplaceme	ent.				

Geological Information

Surficial Map Description:	Alluvium
Bedrock Map Description:	Iberville Fm. Shale/Siltstone. Dark-gray shale with thin discontinuous beds of cross-bedded and graded dolomitic siltstone.

Record Plan Information

Are there Record Plans?	Yes ⊠ No □
Record Plans ID #	<u>57s652</u>
Historical Plan Notes:	The length of the bridge is indicated to be 283.54 ft. The bridge foundation consists of two abutments and two piers. Abutment 1 and Pier 1 are located at the north end of the bridge while Pier 2 and Abutment 2 are located at the south end of the bridge. 13 borings total were collected in the record plans. 3 borings were conducted for Abutment 1, 3 borings for Pier 1, 4 borings for Pier 2, and 3 borings for Abutment 2. The plans indicate that the abutment foundations consist of piles, while the piers suggest spread footings.

Bedrock Depth Information

Are there Historical		Yes ⊠ No □ Unknown □						
Borings?								
Historical	Project	e from # of Borings		Top of	Rock Type			
Boring	Name	Project (ft)			Bedrock		
Information:						Elevation (ft)		4
	Ferrisburgh	0 – this i	s the		13	107.9 to	Not stated	
	F72 (7)	original				101.8	in logs.	
		construc	tion.					
Link to Historic	al Boring	M:\	M:\Projects\22b390\Structures\Record Plans					
Information:	_							
Is there any be	drock depth inf	formation	from	Yes ⊠	No □ Unk	nown 🗆		
well data near	the project are	a?						
Well Data	Well Report #	‡	Bedrock Depth (ft)			Distance from Project (ft)		
Information:								
	399		104		350			
23021			73			381		
	56460							
	56468	75				530		

VTrans Geotechnical Engineering Scoping Data Form Ferrisburgh BF 019-4(35)

Are Bedrock Outcrops Present at the	Yes □ No ⊠
Site?	
Bedrock Depth General Comments:	Depth of bedrock encountered as stated in boring logs
	found ranges between 6 ft to 15 ft.

General Site Conditions

Site Visit Conducted?	Yes □ No ⊠
Date of Site Visit:	N/A
Are there Overhead Utilities at the Site?	Yes □ No ⊠
Are there environmental Hazards Present at the Site?	Yes □ No ⊠
Information regarding found Environmental Hazards:	N/A
Site Condition Notes:	Due to the quality of the photos available of the project site, existing information, and the conceptual treatment type stated as deck removal, a site visit was not conducted.

Note that representative site photos are provided in Appendix A.

Recommendations

Are Borings Needed in the Scoping Phase?	Yes □ No ⊠
Subsurface Investigation Recommendations:	Based on the information reviewed during this investigation, this structure appears to be a good candidate for a deck replacement assuming the loads from the replacement deck are similar in magnitude to the existing loads. If a replacement deck will increase the loading on the existing foundation, a detailed geotechnical assessment of the subsurface conditions beneath the abutments and piers may be required to assess their capacity to support the increased loads. It is assumed a minimum of two borings would be taken and if shallow bedrock is encountered then rock cores would be taken to assess the quality

VTrans Geotechnical Engineering Scoping Data Form Ferrisburgh BF 019-4(35)

	and classification of the bedrock. Additional methods would also be recommended to
	profile the bedrock surface.
Foundation & Structure Type	The Geotechnical Engineering Section can
Recommendations:	assist in performing an assessment of the
	existing abutments if the proposed
	replacement of the deck increases the
	loading. A detailed geotechnical assessment
	may be required to assess the capacity of the
	abutments to support the increased loading
	and check for any potential stability issues.

The information provided is utilized from the databases and references noted in the Reference Section below. This form has been completed to the best of staff and reviewer knowledge.

Please reach out to us if you have any questions or concerns.

Staff Name & Title: **ETT**

Ethan Thomas, AOT Geologist	Ethan.Thomas@vermont.gov (802) 595-6752
-----------------------------	---

Reviewer Name & Title: END

Eric Denardo, P.E.	Geotechnical Engineer
--------------------	-----------------------

References:

Doll, C. G., 1970, Surficial Geologic Map of Vermont, Vermont Geological Survey, Montpelier, VT.

Ratcliffe, N. M., Stanley, R. S., Gale, M. H., Thompson, P. J., Walsh, G. J., 2011, Bedrock Geologic Map of Vermont, Vermont Geological Survey, Montpelier, VT.

Vermont Agency of Natural Resources Department of Environmental Conservation, Natural Resources Atlas, www.anr.vermont.gov/maps/nr-atlas%20, accessed 11/08/2023.

APPENDIX A



Appendix A 1: Approach of Bridge #138. The view is to the north.



Appendix A 2: Abutment 1. Note some undermining of the left side of the abutment.



Appendix A 3: View of Pier 2.



Appendix A 4: View of Pier 1.



Appendix A 5: View of Abutment 2.

Appendix E: Resource ID Completion Memo



OFFICE MEMORANDUM

AOT - PDB - ENVIRONMENTAL SECTION

RESOURCE IDENTIFICATION COMPLETION MEMO

TO: Laura Stone, Project Manager

FROM: Julie Ann Held, Environmental Specialist

DATE: March 27, 2024

Project: Ferrisburgh BF 019-4(35)

ENVIRONMENTAL RESOURCES:

Archaeological Resources:	_X Yes	No	See Archaeological Resource ID Memo
Historic Resources:	Yes <u>X</u>	No	See Historic Resource ID Memo
Wetlands:	<u>X</u> Yes	No	See Natural Resource ID Memo
Aquatic Organism Passage:	Yes <u>X</u>	No	See Natural Resource ID Memo
Agricultural Soils:	Yes <u>X</u>	No	See Natural Resource ID Memo
Wildlife Habitat:	<u>X</u> Yes	No	See Natural Resource ID Memo
Endangered Species:	_X Yes	No	See Natural Resource ID Memo
Stormwater Considerations:	_X_Yes	No	See Stormwater Resource ID Memo
Landscape Considerations:	_X_Yes	No	See Landscape Resource ID Memo
6(f) Properties:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Hazardous Waste:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Contaminated Soils:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Wild Scenic Rivers:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Act 250 Permits:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
FEMA Floodplains:	_X_Yes	No	See Environmental Specialist Resource ID Memo
Flood Hazard Area:	_X_Yes	No	See Environmental Specialist Resource ID Memo
River Corridor:	<u>X</u> Yes	No	See Environmental Specialist Resource ID Memo
Protected Lands:	_X Yes	No	See Environmental Specialist Resource ID Memo
US Coast Guard:	Yes	No	See Environmental Specialist Resource ID Memo
Lakes and Ponds:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Scenic Highway/ Byway:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Environmental Justice:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo
Other:	Yes <u>X</u>	No	See Environmental Specialist Resource ID Memo

cc:

Project File

Appendix F: Natural Resources Memo



To: Ferrisburgh BF 019-4(35)

Date: December 7, 2023

Memorandum

. . ojest i ...e

Project #: 58916.06

From: Mitch Jackman;

Re: Natural Resources Assessment

On behalf of the Vermont Agency of Transportation ("VTrans"), VHB prepared this memorandum to summarize the results of a natural resources desktop assessment, wetlands and waters field delineation, protected bat potential roost tree ("PRT") survey and rare, threatened and endangered ("RTE") plants survey (together, "natural resources assessments") conducted for the proposed Ferrisburgh BF 019-4(35) project ("Project") located in Ferrisburgh, Vermont at the crossing of Lewis Creek. The Project would occur within the VTrans right-of-way ("ROW") along US Route 7 ("US-7").

Assessments focused on an approximately 6.7-acre area generally centered on the ("Study Area"). The Study Area was established to include the footprint of Project activities plus accessible lands within a 50-foot setback from the Project's limits of disturbance ("LOD") in order to identify state-regulated Class II wetland buffers that may extend into the Study Area associated with wetlands located beyond the LOD and potential (as yet undesigned) erosion prevention and sediment contract ("EPSC") measures (see Natural Resources Map, **Attachment 1**).

The natural resources assessment for the Project included reviews of public and privileged databases and field surveys and was designed to include an evaluation for the presence/absence, and potential impacts to streams, wetlands, and RTE plant species, including bats, and assess the presence of non-native invasive plant species ("NNIS"). This memorandum was written to inform the planning, design, and permitting (if needed) of the Project.

EXISTING CONDITIONS

The Study Area is located within the Champlain Valley Biophysical Region of Vermont, which is characterized by relatively warm temperatures and lower precipitation than other regions of Vermont, and also relatively fertile clay and silt derived soils. Lewis Creek runs generally east to west through the Study Area and under a Bridge 139, a three-span continuous steel girder bridge with a reinforced concrete deck and reinforced concrete abutments and columns (2), constructed in 1957. In addition to the Lewis Creek (watershed HUC:04300108502), the Vermont Hydrography Dataset ("VHD") mapped an unnamed perennial stream to the south and flowing generally northwest towards Lewis Creek in the Study Area that passes under US-7 via a culvert. The Study Area also contains one wetland feature in the southwest portion that is included in the Vermont Significant Wetland Inventory ("VSWI") as mapped by the Vermont Department of Environmental Conservation ("DEC").

The Natural Resources Conservation Service ("NRCS") has mapped the dominant soils within the Study Area as Winooski very fine sandy loam (Wo) and Hadley very fine sandy loam (Hh, NRCS, 2022). On-site elevations range from approximately 160 to 200 feet above mean sea level.

Within the Study Area, existing conditions are influenced by the presence of the US-7 corridor and also includes naturalized forest edge and forested conditions beyond the limits of the mowed and maintained road shoulders Numerous non-native invasive plant species ("NNIS") are present within the Study Area as described below. The

Ferrisburgh BF 019-4(35) Ref: 58916.06 Page 2 of 7 November 1, 2023



surrounding landscape is a mix of forest blocks, agricultural lands, and rural residential development as well as the US-7 travel corridor and intersecting town roads.

Representative photographs of the on-site conditions and identified natural resources are included in Attachment 2.

METHODOLOGY AND ASSESSMENT RESULTS

Waters

VHB Environmental Scientists conducted stream delineation and assessment work within the Study Area on October 9, 2023 to map stream channels and jurisdictional ditches. Stream determinations and Ordinary High Water ("OHW") width assessments follow guidance provided in the United States Army Corps of Engineers ("USACE") Regulatory Guidance Letter: Subject-Ordinary High Water Identification. When applicable, stream delineations are conducted pursuant to the 2005 Vermont Agency of Natural Resources ("ANR") Guidance for Agency Act 250 and Section 248 Comments Regarding Riparian Buffers ("ANR Riparian Buffer Guidance"), including flagging Stream Top of Bank ("TOB") and Top of Slope ("TOS"). Stream OHW, TOB, and TOS are flagged on larger channels (generally streams greater than six feet wide) and stream centerline ("SC") is flagged for smaller channels (less than six feet wide). Streams are identified in the field with blue flagging, and features are mapped in the field using GPS-enabled and sub-meter capable mobile mapping technology. Flagging is hung where there is woody vegetation and it would not detract from land-use, such as agriculture. Stream identifiers include the year, stream delineation type (OHW, TOS, TOB, JD or SC), and stream ID number. Stream flow regimes are classified as ephemeral, intermittent, or perennial and are determined based on qualitative observations of instream hydrologic indicators at the time of observation, as well as geomorphic characteristics, and are subject to professional judgment. Riparian buffers are applied to streams and rivers in the natural resource mapping when the project is subject to Act 250, and are consistent with the ANR Riparian Buffer Guidance, which are designated for any natural perennial and intermittent stream channels. Jurisdictional ditches are not considered streams but are mapped and identified when such features are present that serve to connect wetlands or waters or were likely excavated within a wetland.

As shown on **Attachment 1**, ANR maps a River Corridor and the 100-year floodplain associated with the Lewis Creek. During VHB's October 9, 2023 field assessments, the OHW for the Lewis Creek was delineated as 2023-TOB-LC. In addition, VHB delineated 2023-TOB-1 for a perennial unnamed tributary to the south of Lewis Creek which passes under US-7 via a culvert, and applied a 50-foot River Corridor to this waterway in lieu of an ANR-determined one. There was also one intermittent stream channel delineated by VHB and identified as 2023-SC-1, and a non-jurisdictional ditch which is mapped as 2023 NJD-2. Additional details are included in the Wetlands and Waters Summary Table included as **Attachment 3**.

Wetlands

The Vermont Wetland Rules ("VWR") regulate activities within significant wetlands (Class I and Class II wetlands, as defined by the VWR) and their associated 50-foot buffers for Class II wetlands and 100-ft buffer for Class I wetlands (ANR 2023). Additionally, the USACE regulates the discharge of fill or dredging in wetlands under Section 404 of the Clean Water Act.

Ferrisburgh BF 019-4(35) Ref: 58916.06 Page 3 of 7 November 1, 2023



Wetland delineations are made pursuant to applicable methodologies described in the Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region Routine Determination Method ("Regional Supplement"; USACE 2012). Field notes are recorded to document conditions in the wetland including vegetation, soils, and evidence of hydrology, potential wetland functions, wetland classifications, general characteristics of the wetland, any unique qualities observed during the site assessment, along with other considerations relevant to support site findings. Wetland functions are evaluated using the field notes and observations and are based on the functional criteria described in Section 5 of the VWR. Wetlands are identified in the field with pink flagging and are mapped in the field using mobile data collection technology capable of sub-meter accuracy.

VHB Environmental Scientists conducted wetland delineation fieldwork concurrent with stream delineations. In total, VHB delineated four wetlands within the Study Area. On-site wetlands include a mix of Palustrine Forested ("PFO") and Palustrine Emergent ("PEM") wetlands (Cowardin *et al.*, 1979). Of the four delineated wetlands, all features were assessed by VHB to qualify as a Class II wetland, based in part on the landscape position and observed function of each wetland individually and also that the wetlands in the Study Area and as mapped by the VSWI are contributing to a cumulative overall function of riparian wetland habitats to the Lewis Creek. Additional details on these wetlands can be found in the Wetlands and Waters Summary Table (**Attachment 3**) as well as in the USACE Wetland Determination Data Forms (**Attachment 4**).

Rare, Threatened and Endangered Species

Vermont statute 10 V.S.A. Chapter 123: Protection of Endangered Species applies to both endangered and threatened species. Protected endangered and/or threatened species include those listed under the chapter as well as those protected under the federal Endangered Species Act. The list of Vermont's rare and uncommon species is produced by the Vermont Natural Heritage Inventory ("NHI"), a program within the Vermont Fish & Wildlife Department ("FWD"). Such species are considered by VTrans when reviewing projects for compliance with the National Environmental Policy Act ("NEPA"), by the Natural Resources Board for projects subject to Act 250 jurisdiction, and by the Vermont Agency of Natural Resources ("ANR") when reviewing projects subject to various state regulatory review processes.

To identify the potential occurrence of RTE species and to assess available on-site habitat conditions relative to each, VHB queried the NHI database for the presence of known element occurrences ("EO") of RTE species within and adjacent to the Study Area (see **Attachment 5**). VHB used a 1-mile search radius and found a total of 16 EO records for RTE species. Of the total 16, 11 species are aquatic and five are associated with terrestrial habitats (two bat species and two bird species and one turtle species).

In addition to the NHI database, on October 28, 2023, VHB reviewed the U.S. Fish and Wildlife Service ("USFWS") Information for Planning and Consultation System ("IPaC") database for a list of federally listed Endangered and Threatened species within the Study Area (see **Attachment 7**). From this, the Study Area is within the known range of the monarch butterfly (*Danaus plexippus*), which is a candidate for Federal listing as well as the state and federally endangered northern long-eared bat (*Myotis septentrionalis* or "MYSE"), a forest-dwelling bat. From the NHI database review, there is a known MYSE occurrence within a one-mile radius of the Study Area, where MYSE was captured in a mist-netting survey conducted by the FWD in 2006. In order to assess potential impacts to the species from tree

Ferrisburgh BF 019-4(35) Ref: 58916.06 Page 4 of 7

November 1, 2023



clearing associated with a Project, a Potential Roost Tree ("PRT") survey was conducted in the Study Area as described below.

RTE Plants

On October 9, 2023, VHB Ecologists conducted a general plant survey to document the presence/absence of identifiable RTE plants. A Partial Floristic Inventory of identifiable plants, including those that are rare or NNIS, at the time of survey is included in **Attachment 6**. In general, vegetative cover along the US-7 roadway corridor is regularly mowed/maintained through mowing and includes mixed herbaceous vegetation that is responsive to disturbance (i.e., mowing) and generally weedy. The roadway fill slopes and areas adjacent to the north and south approach to the US-7 bridge were found to be naturalized in vegetation cover and comprised of a shrub-sapling and forested edge. The species composition of woody vegetation onsite is mixed hardwood and softwood species that are common to Vermont and the surrounding landscape of the Champlain Valley and foothills of the Green Mountains. No onsite vegetative communities were identified to meet the definition of a recognized Natural Community per the reference publication Wetland, Woodland, Wildland: A Guide to the Natural Communities of Vermont¹. VHB's field survey found no RTE plant species present in terrestrial portions of the Study Area.

RTE Animals

On October 27, 2023, FWD-approved PRT surveyors assessed the Study Area for PRTs that may be used by MYSE. PRTs were defined as the following, per the FWD's (2017 guidance):

- > a cavity tree exhibiting any form of decay or excavation by primary cavity producers that provides access to the interior of the bole;
- > a tree with cracks or crevices into which bats may roost, including bark furrows;
- > a tree with peeling or exfoliating bark;
- ➤ live shagbark hickory or black locust; and/or
- > a tree with roost features whose total tree height exceeds 10 feet and is at least four inches in Diameter at Breast Height ("DBH").

Representative photographs of PRTs are included in Attachment 2 and are depicted in the Natural Resource Map in Attachment 1. It should be noted that VHB assessment of potential bat habitat is limited to mapping of PRTs, and does not include review of any structures (e.q., bridges) that could provide suitable roost habitat for other protected bats. Further bat surveys could be required if a project in the Study Area would result in tree cutting of PRTs during the summer roosting season. VHB's assessment here does not include detailed presence/absence surveys and is limited to the identification of PRTs for VTrans' consideration during project planning.

¹ Thompson, E.H., Sorenson, E.R., and R.J. Zaino. 2019. Wetland, Woodland, Wildland: A Guide to the Natural Communities of Vermont. Second Edition. Published by Vermont Fish and Wildlife Department, The Nature Conservancy, and Vermont Land Trust. Distributed by Chelsea Green Publishing.

Ferrisburgh BF 019-4(35) Ref: 58916.06 Page 5 of 7 November 1, 2023



Wildlife Habitat Connectivity and Non-Native Invasive Plants

Wildlife Habitat Connectivity

During its October 2023 field delineation and assessments, VHB made observations and assessments of onsite wildlife habitats relevant to habitat connectivity value and function within the Study Area. In general, the Study Area contains two types of habitats: aquatic habitat in perennial streams (Lewis Creek and the unnamed tributary identified by VHB as 2023-TOB-1) and terrestrial habitat. VHB's fieldwork did not include surveys of aquatic habitat, however based on a visual assessment of the existing conditions of Lewis Creek in the Study Area and information from VTrans, the existing bridge crossing of US-7 over Lewis Creek is not impeding the passage of aquatic organisms ("AOP"), and additionally provides a terrestrial travel opportunity for wildlife movement under the bridge within the riparian zone along the edge of Lewis Creek. Terrestrial habitats onsite consist of upland forest, emergent and forested wetland areas, and the open, mowed, maintained roadway corridor of US-7. The road is not enclosed by a fence, walls, or other blockades that would prohibit the movement of wildlife across the road, and so travel across US-7 is possible.

As US-7 is a relatively heavily traveled State highway, wildlife crossing of US-7 between adjacent habitats presents safety considerations for the traveling public and for wildlife. There are forest blocks to both the east and west of the Study Area which are interspersed with rural residential and rural sub-division type development along Loven Lane (west) and Lewis Creek Road (east). The Ferrisburgh town center is located approximately 3.1 miles to the south, with North Ferrisburgh approximately 0.7 mile to the north at the intersection of Old Hollow Road and Stage Road. The existing transportation and residential development in close proximity to the Study Area as well as the presence of NNIS are impacting the value of habitats in the Study Area for wildlife habitat connectivity. In the ANR BioFinder, the areas bounding the bridge immediately north and south are considered highest priority for Surface Water and Riparian Areas and Physical Landscape Diversity.

Because the Study Area was limited to the VTrans ROW centered on US-7, the forest blocks that extend to the east and west from the Study Area were not assessed in the field but a remote sensing analysis using aerial photography and database information was used in assessing potential onsite habitats and the role that the Study Area has in habitat connections to and between surrounding areas. VHB finds that the Study Area contains current and ongoing habitat fragmentation resulting from the US-7 road corridor. Further habitat fragmentation from a road project within the Study Area would not be anticipated unless a temporary bridge was required to be installed off alignment. The bridge over Lewis Creek provides AOP habitat for aquatic wildlife and there is terrestrial habitat connectivity under the bridge for passage of mammals, reptiles, and other terrestrial wildlife. The culvert that passes the unnamed tributary 2023-TOB-1 was not examined in detailed by VHB in this assessment. Based on visual observation in the field and a general assessment of streamflow regime and stream channel geomorphology, the culvert may be undersized for meeting AOP habitat connectivity. Representative photographs of observed habitat conditions are presented in **Attachment 2**.

NNIS

Several species of NNIS were noted to occupy onsite naturalized habitats. Per VTrans request, the target NNIS species for VHB's survey were common reed (*Phragmites australis*) and purpose loosestrife (*Lythrum salicaria*). Both common reed and purpose loosestrife were found to be present in the Study Area and their locations are included on the Natural Resources Map in **Attachment 1**. Other NNIS species present onsite include common buckthorn (*Rhamnus cathartica*), garlic mustard (*Alliaria petiolata*), wild parsnip (*Pastinaca sativa*), and Morrow's honeysuckle (*Lonicera*

Ferrisburgh BF 019-4(35) Ref: 58916.06 Page 6 of 7 November 1, 2023



morrowii). Although multiple NNIS species are present, the Study Area is not dominated by their presence. VHB recommends that VTrans to consider measures to avoid spreading NNIS and introducing new NNIS to the Study Area during Project planning and design.

CONCLUSIONS

Based on VHB's database reviews and field assessments described above, there are natural resources present within the Study Area that will need to be considered during detailed future planning and design of Project activities. These resources reported herein include wetlands, Class II Wetland buffers, surface waters (streams), River Corridors, and RTE species (potential roost habitat for MYSE). Depending on VTrans' proposed Project activities within the Study Area, one or more permit authorizations and/or consultation with regulatory agencies could be required: Clean Water Act Section 404 permit, Vermont Wetland Permit, Flood Hazard and River Corridor Protection ("FHARC") permit, Title 19 consultation, and Vermont Endangered and Threatened Species Takings Permit.

ATTACHMENTS

- 1. Natural Resources Map
- 2. Representative Site Photographs
- 3. Summary of Delineated Wetlands and Streams
- 4. USACE Wetland Determination Data Forms
- 5. Elemental Occurrence Table
- 6. Ferrisburgh BF 019-4(35) Partial Floristic Inventory
- 7. USFWS IPaC Official Species List

REFERENCES AND RESOURCES

Cowardin, L.M., Carter, V., Golet, F.C., and E.T. LaRoe. 1979. *Classification of Wetlands and Deepwater Habitat of the United States*. U.S. Fish and Wildlife Service. FWS/OBD-79/31.

Natural Resources Conservation Service (NRCS), United States Department of Agriculture. 2022. Web Soil Survey. Available online at: https://websoilsurvey.nrcs.usda.gov/app/ Last accessed February 2022.

- U.S. Army Corps of Engineers (USACE). 2012. Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeastern Region (Version 2.0), Final Report.
- U.S. Fish and Wildlife Service (USFWS). 2023. Interim Consultation Framework for the Northern Long-eared Bat.

 Effective March 31, 2023. Available online at:

 https://www.fws.gov/sites/default/files/documents/Interim%20Consultation%20Framework 21Mar23.pdf

Vermont Agency of Natural Resources (ANR). 2005. *Guidance for Agency Act 250 and Section 248 Comments Regarding Riparian Buffers*. Effective December 9, 2005.

2017.	Regulatory R	eview Guidance fo	or Protecting	Northern	Long-eared	Bats and	Their Habitat	s. Effective	February
2017.									

Ferrisburgh BF 019-4(35) Ref: 58916.06 Page 7 of 7 November 1, 2023




2021. Tree cutting in Indiana bat range of Vermont during environmental review.	
2023. Vermont Wetland Rules. Department of Environmental Conservation. Effective February 10, 2023.	

Vermont Fish and Wildlife Department. 2017. Regulatory Review Guidance to Protecting Northern Long-Eared Bats and Their Habitats. Available on-line at:

https://vtfishandwildlife.com/sites/fishandwildlife/files/documents/Conserve/RegulatoryReview/Guidelines/Regulatory Review Guidelines for Protecting Northern %20Long-eared Bats and Their Habitats (2-2017).pdf









© VHB

Ferrisburgh BF019-4(35) Project: Representative Photograph Log

PROJECT NUMBER

58916.06

CLIENT

Vermont Agency of Transportation

LOCATION

US Route 7

Ferrisburgh, Vermont



NO. 1 / 10.09.2023

Representative photo of wetland 2023-1



NO. 2 / 10.08.2023

DESCRIPTION

Representative photo of wetland 2023-2



NO. 3 / 10.08.2023

Representative photo of wetland 2023-1



NO. 4 / 10.08.2023

DESCRIPTION

Representative photo of wetland 2023-4



NO. 5 / 10.08.2023

Representative photo of the Lewis Creek, delineated by VHB as 2023-TOB-LC. Photo also shows the non-native invasive species common reed growing adjacent to Lewis Creek



NO. 6 / 10.08.2023

DESCRIPTION

Another view of Lewis Creek taken from under the US Route 7 bridge



NO. 7 / 10.08.2023

Representative photo of the unnamed tributary to Lewis Creek, delineated by VHB as 2023-TOB-1



NO. 8 / 10.08.2023

DESCRIPTION

Representative photo of the nonnative invasive species purple loosestrife growing as a clump near Lewis Creek



NO. 9 / 10.08.2023

Representative photo of the culvert which passes stream 20230TOB-1 under US Route 7



NO. 10 / 10.08.2023

DESCRIPTION

A representative view of a potential roosting tree for bats within the Study Area



Summary of Delineated Wetlands
Client: Vermont Agency of Transportation
Project: Ferrisburgh BF 019-4(35)
Location: Ferrisburgh, Vermont

Prepared By: VHB; October 23, 2023

Delineation Date(s): VHB (M. Jackman) on October 9, 2023

	VHB Delineated Wetlands											
Wetland ID ¹	Delineated Area (Square Feet) ¹	Cowardin Classification ²	Hydrology Indicator	Hydric Soil Indicator			Vermont Wetland	l Rules Classificat				
					Contiguous to a VSWI-mapped Wetland?	Riparian Wetland Contiguous to Stream Channel? (Flow Regime) ³	VWR Section 4.6 Categorical Class II Wetlands ⁴	VWR Section 5 Functional Criteria Presence / Significance		VHB-Proposed VWR	Typical Vegetation	Comments
								Type⁵	VHB-Proposed Significant?	Classification ⁶		
2023-1	2,280	PEM	Surface Water (A1), Drift Deposits (B3), Geomorphic Position (D2), Saturation (A3)	Redox Dark Surface (F6)	No	Yes	No	5.1(L), 5.2(L), 5.10 (L)	Yes	II	Salix nigra., Solidago spp.	Fringe wetland to Lewis Creek, low function as assessed but feature is assumed to contribute to function of collection of fringe wetlands to the surface water
2023-2	496	PEM, PFO	Geomorphic Position (D2), Saturation (A3)	Redox Dark Surface (F6)	No	No	No	5.1(L), 5.2(L)	No	Ш	Solidago spp., Tussilago farfara, Ranunculus spp.	Very small area of emergent wetland conditions at the downgradient end of a non-jurisdictional ditch
2023-3	4,870	PEM	Surface Water (A1), Drift Deposits (B3), Geomorphic Position (D2), Saturation (A3)	Redox Dark Surface (F6)	No	No	No	5.1(L), 5.2(L), 5.10 (L)	Yes	II	Solidago spp., Tussilago farfara	of Lewis Creek under/partially under the span of the US Route 7 bridge; low function as assessed but feature is assumed to contribute to function of collection of fringe wetlands to the surface water; cumulative function of two 2023-3 assumed to also contribute to larger cumulative function of additional fringe wetlands beyond the Study Area.
2023-4	1,130	PEM	Water-Stained Leaves (B9), Saturation (A3), Geomorphic Position (D2)	Redox Dark Surface (F6)	No	No	Yes - contiguous to VSWI	5.1(L), 5.2(L), 5.10 (L)	Yes	II	Lysimachia nummularia, Thuja occidentalis, Ribes lacustre, Ranunculus spp.	Probably continues to larger natural feature outside of Study Area where VSWI is mapped to the west

¹All wetlands field delineated per the Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northeast and North Central Region. U.S. Army Corps of Engineers. 2011; Delineated Wetlands that extend outside the Study Area are denoted with **bold** text.

²Classification follows Cowardin, L.M., Carter, V., Golet, F.C. and E.T. LaRoe. 1979. Classification of Wetlands and Deepwater Habitat of the United States. U.S. Fish and Wildlife Service. FWS/OBD-79/31. 103pp.

³Wetland contiguity to streams as defined in the Vermont ANR (2005) *Guidance for Agency Act 250 and Section 248 Comments Regarding Riparian Buffers* and confirmed if a delineated perennial or intermittent stream channels not typically being subject to ANR Riparian Buffer Guidance). The vegetative assemblage or natural community type is used when determining riparian vegetation function. Flow regime determined based on qualitative observations of instream hydrology indicators and geomorphic characteristic and are subject to professional judgment (P=perennial, I=intermittent, E=ephemeral).

 $^{^4}$ Alpha-numeric codes correspond with Section 4.6 Presumptions of the 2023 Vermont Wetland Rules.

⁵VWR Section 5: Functional Criteria for Evaluating a Wetland's Significance: 5.1=Water Storage for Flood Water and Storm Runoff, 5.2=Surface and Groundwater Protection, 5.3=Fish Habitat, 5.5=Exemplary Wetland Natural Community, 5.6=Rare, Threatened or Endangered Species Habitat, 5.7=Education and Research in Natural Sciences, 5.8=Recreational Value and Economic Benefits, 5.9=Open Space and Aesthetics, 5.10=Erosion Control Through Binding and Stabilizing the Soil. (P)= Present, (H)=High, (L)=Low; Correspond to observed level of functionality.

⁶VHB-Proposed VWR Classification is based on review and application of the VWR, particularly VHB's interpretation of Section 4.6 Presumptions and is subject to final determinations by the ANR-DEC.



Summary of Delineated Streams Project: Ferrisburgh BF 019-4(35) Client: Vermont Agency of Transportation

Location: Ferrisburgh, Vermont

Prepared By: VHB; October 23, 2023

Delineation Date(s): VHB (M. Jackman) on October 9, 2023

	VHB Delineated Streams											
Stream ID	Stream Name	Associated Wetlands	Average Ordinary High Water (OHW) Width (Feet) ¹	Dominant Substrate	Water Depth (Inches)	Bank Height (Feet)	Flow Regime (Ephemeral, Intermittent, or Perennial) ²	ANR-Mapped River Corridor? (Yes/No)	VHB-Proposed River Corridor (Yes/No)	Watershed Size (Square Miles) ³	VWQS Classification (2022) ⁴	Comments
2023-TOB-LC	Lewis Creek	2023-1 and 2023-3	55	cobble, sand	20	4	Perennial	Yes	No	77	В	Lewis Creek crossing under US Route 7; fringe wetlands present; delineation done during high water conditions
2023-TOB-1	None (unnamed tributary to Lewis Creek)	2023-2	18	cobble, sand	6	2	Perennial	No	Yes	0.80	В	Perennial tributary to Lewis Creek, unnamed; flows through culvert under US Route 7
2023-SC-3	None	2023-4	3.0	silt, clay	3	1.0	Intermittent	No	No	<0.25	-	Headcut channel in fine substrate soil downgradient to TOB-1

¹ U.S. Army Corps of Engineers. 2005. *Regulatory Guidance Letter. Subject: Ordinary High Water Mark Identification.* No. 05-05.

(I/vib.com/gbl/pro)(Skurlington/S89166 Ftog 87019-4(25)(subertet/Skurmary of Wetlands and Streams, Ferricburgh 8F

² Stream flow regime determined based on qualitative observations of in stream hydrology indicators and geomorphic characteristic and are subject to professional judgment.

³ Watershed size determined from Vermont Agency of Natural Resources ("ANR") Stream Alteration Regulatory Program mapping and/or watershed delineation tool on ANR Atlas.

⁴From ANR. 2022. Vermont Water Quality Standards (Vt. Code R 12 004 052),.

⁵ List of streams from the ANR. 2016. 303(d) Assessment of the Condition of Vermont Waters. Priority Listing of Vermont Waters. Vermont Department of Environmental Conservation.

⁶ If no ANR mapped river corridor is present, VHB proposed river corridor is applied pursuant to the DEC Flood Hazard Area and River Corridor Protection Procedure (2017), as applicable.



Project Site:	Ferrisburg	th BF019-4(35)		City/County:	Addisor	1		Samp. Date: 10	/9/2023
Applicant/Owner:	Vtrans			· -	State:	Vermont	Sampling Point:	2023	-3-1up
Investigator(s):	VHB (MCJ))		_		nip, Range:	Ferrisburgh		
Landform (hillslope, t		floodplain		Local relief		convex, none):	concave	Slope (%):	0 to 3%
Subregion (LRR or	MLRA):	LRR R	Lat:	44.2480	002	Long:	-73.22904	Datum:	NAD83
Soil Map Unit:		very fine sandy lo						NWI Class:	UPL
	U	,	pical for this time of ye	ea <u>r?</u>	Yes	(If no, e	xplain in Remarks.)		
Are Vegetation, Soi								ircumstances?	Yes
Are Vegetation, Soi	l, or Hydrolo	ogy naturally prob	olematic? <u>No</u>				(If needed,	explain any answe	ers in Remarks.)
			map showing sar	nple point	locatio	ns, transe	cts, important fe	eatures, etc.	
Hydrophytic Vegeta		t?	YES						
Hydric Soil Present	?		NO			Is This	Sample Area Withii	າ a Wetland?	NO
Wetland Hydrology	/ Present?		NO						
Remarks:									
HADBOLOCA									
HYDROLOGY Wetland Hydrology	Indicators						Cacandaniladicate	ars (minimum of t	wa raguirad)
		of one is required.	; check all that apply)				Secondary Indicate Surface Soil C		wo required)
Surface Water	•	Tone is required,		ros (BO)		=			
	. ,		Water-Stained Leave Aguatic Fauna (B13)				Drainage Pati		
High Water Ta			 ' ' '				Moss Trim Lin		
Saturation (A3	•		Marl Deposits (B13)					Vater Table (C2)	
Water Marks			Hydrogen Sulfide Oc		(62)		Crayfish Burn		
Sediment Dep		_	Oxidized Rhizospher		DIS (C3)			sible on Aerial (C9)	
Drift Deposits	. ,	_	Presence of Reduced		(66)			ressed Plants (D1)	
Algal Mat or C			Recent Iron Reduction		(C6)		Geomorphic		
Iron Deposits Inundation Vis			Thin Muck Surface (Shallow Aqui		
		· · ·	Other (Explain in Re	marks)			FAC-Neutral	aphic Relief (D4)	
sparsely vege	tated Concav	re Surface (B8)					FAC-Neutral	rest (D5)	
Field Observations:									
Surface Water Pres	ent?		Depth (inches):						
Water Table Preser			Depth (inches):			Wetland	d Hydrology Present?	_	NO
Saturation Present			Depth (inches):						
Describe Recorded	Data (Strear	n gauge, monitor	ing well, aerial photos,	, previous insp	ections),	ir available:			
Remarks:									
SOIL									
	(Describe to	o the denth need	ed to document the inc	dicator or con-	firm the a	absence of in	ndicators)		
Depth	Matrix	s the depth heed		dox Features					
		%		%	Type ¹	Loc ²	Touturo	Do.	marks
	(moist) R 4/1	100%	Color (moist)		Туре		Texture CLAY LOAM	- Nei	IIIdikS
	Y 4/2	90%	10YR 5/6	10%			CLAY LOAM		
				- ———					
		. — — —						-	
-									
¹ Type: C=Concentration,	, D=Depletion, F	RM=Reduced Matrix,	MS=Masked Sand Grains.				² Location: PL=Pore Linin	ıg, M=Matrix.	
Hydric Soil Indicato	rs:						Indicators for Prob	lematic Hydric So	ils ³ :
Histosol (A1)			Polyvalue Re	elow Surface (S8	R) (I RR R		2 cm Muck (A	A10) (LRR K, L, MLRA	149R)
Histic Epipedo	nn (Δ2)		MLRA 149		, (בונורונ,			Redox (A16) (LRR K,	,
Black Histic (A				urface (S9) (LRR I	R MIRA 1	49R)		Peat or Peat (S3) (LR	
Hydrogen Sulf	-			ky Mineral (F1) (,	430)		(S9) (LRR K, L, M)	, 2, 11,
Stratified Laye	. ,			ed Matrix (F2)	LINIX IX, L)			low Surface (S8) (LRI	D V I)
Depleted Belo		ce (A11)	Depleted Ma					rface (S9) (LRR K, L)	K K, L)
Thick Dark Su		ce (AII)	Redox Dark					ese Masses (F12) (LI	DD V I D\
Sandy Mucky				ark Surface (F7)				odplain Soils (F19) (
			Redox Depre					(TA6) (MLRA 144A,	·
Sandy Gleyed			Kedox Depre	25510115 (F6)					145, 1496)
Sandy Redox (3.				Red Parent N		
Stripped Matr		U.D.A. 4.40D)		dicators of hydro		-		Dark Surface (TF12))
Dark Surface	(57) (LRR R, IVI	ILKA 149B)	wetla	and hydrology n			Other (Explai	n in Remarks)	
Restrictive Layer (if	observed):			dis	turbea or	problematic.			
Type:							Hydri	c Soil Present?	NO
Depth (inches):							,		
Remarks:							•		

		Absolute	Dom.	Indicator			
Tree	Stratum (Plot size: 30' RAD)	% Cover	Sp?	Status	Dominance Test Worksheet:		
1.	Tsuga canadensis	15	X	FACU	# Dominants OBL, FACW, FAC:	7	(A)
	Fraxinus pennsylvanica	15	X	FACW	, , ,		_` ′
	Carpinus caroliniana	15	<u> </u>	FAC	# Dominants across all strata:	13	(B)
4.	•	3		FACU	Johnmants doi 035 dii Stratai		(
5.	Carya cordiformis	3		FAC	% Dominants OBL, FACW, FAC:	54%	(A/B)
6.	Thuja occidentalis	1	· ——	FACW	70 Dominants Obe, FACW, FAC.	34/0	(^,',',',
7.	Thuja occidentalis			TACW	Prevalence Index Worksheet:		
/.		52		l Cover	Total % Cover of:	Multiply D.	
C==1:	ng Stratum (Plot size: 15' RAD)	- 32	= 10ta	Cover		Multiply By	<u>′-</u>
	,	20	v	FA.C	OBL x 1 =		
	Carpinus caroliniana	30	<u> </u>	FAC	FACW 34 x 2 =	68	_
	Thuja occidentalis	15	<u> </u>	FACW	FAC 69 x 3 =	207	
	Acer saccharum	15	X	FACU	FACU 54 x 4 =	216	
4.	Carya cordiformis	3		FAC	UPL 47 x 5 =	235	
5.	Quercus rubra	3		FACU	Sum: <u>204</u> (A)	726	(B)
6.		. —					
7.					Prevalence Index = B/A =	3.56	
		66	= Tota	l Cover	Hydrophytic Vegetation Indicator	rs:	
Shrub	Stratum (Plot size: 15' RAD)				X Dominance Test is > 50%		
1.	Fraxinus pennsylvanica	3	X	FACW	Prevalence Index is <= 3.0		
2.	Carpinus caroliniana	3	Х	FAC	Problematic Hydrophytic \	Vegetation ¹ (e	explain)
3.	Prunus virginiana	3	Х	FACU	Rapid Test for Hydrophytic	c Vegetation	
4.					Morphological Adaptation	ıs	
5.					¹ Indicators of hydric soil and wetland hydr		
6.					unless disturbed or problematic.	rology must be p	resent,
7.		-	· ——		Definitions of Vegetation Strata:		
		9	= Tota	Cover			
Herh	Stratum (Plot size: 5' RAD)				Tree - Woody plants, excluding woody vi	ines, approximat	tely 20ft
	Waldsteinia fragarioides	32	Х	UPL	(6m) or more in height and 3in (7.6cm) or		
	Acer platanoides	15	- X	UPL	breast height (DBH).		
	Parthenocissus quinquefolia	15	_ <u></u>				
3. 4.	Toxicodendron radicans	15	_ <u>^</u>	FACU FAC	Conling Westerless and discussed	4	
	Toxicodendron radicans			FAC	Sapling - Woody plants, excluding wood 20ft (6m) or more in height and less than		
5.						(,	
6.		· 					
7.			·				
8.					Shrub - Woody plants, excluding woody 20ft (1 to 6m) in height.	vines, approxim	nately 3 to
9.					Zort (1 to om) in neight.		
10.		. —					
11.					Herb - All herbaceous (non-woody) plan		
12.					vines, regardless of size. Includes woody provines, less than approximately 3ft (1m) in		oody
		77	= Tota	l Cover	tines, less than approximately sit (1111) in		
Wood	dy Vines (Plot size: 15' RAD)						
1.							
2.		- '-			Woody vine - All woody vines, regardl	ess of height.	
3.							
4.					Hydrophytic	_	
5.					Vegetation		
		-	= Tota	Cover	Present?	YES	
		•					_
Remarl	ks: (If observed, list morphological adaptations below).				1		
ciiial l	to. (III observed, list morphological adaptations below).						

WETLAND DETERMINATION DATA FORM - Northcentral and Northeast Region

2023-3-1wet

Project Site:	Ferrisburg	h BF019-4(35)		City/County:	Addison	1		Samp. Date: 10	0/9/2023
Applicant/Ow	ner: Vtrans			,,,	State:	Vermont	Sampling Point		3-3-1wet
Investigator(s)): VHB (MCJ)			Section	n, Townsh	nip, Range:	Ferrisburgh		
Landform (hills	slope, terrace, etc.):	floodplain		Local relief	(concave, c	onvex, none):	concave	Slope (%):	0 to 3%
Subregion (LR	RR or MLRA):	LRR R	Lat:	44.247952		Long:	-73.228733	Datum:	NAD83
Soil Map Unit:	Winooski	very fine sandy l	oam					NWI Class:	PEM, PSS
Are climatic/h	nydrologic condition	ons on the site type	pical for this time of yea	ir?	Yes	(If no, e	xplain in Remarks.)	_	
Are Vegetation	n, Soil, or Hydrolo	gy significantly d	isturbed? No				Normal (Circumstances?	Yes
Are Vegetation	n, Soil, or Hydrolo	gy naturally prob	olematic? No				(If needed,	explain any answe	ers in Remarks.)
			map showing sam	ple point lo	ocations	s, transec	ts, important fea	atures, etc.	
, , ,	egetation Present	:?	YES						
Hydric Soil Pre	esent?	_	YES			Is This	Sample Area With	in a Wetland?	YES
Wetland Hydr Remarks:	rology Present?		YES						
nemarks.									
HYDROLOG	 GY								
	rology Indicators:						Secondary Indicato	ors (minimum of t	wo required)
•		one is required;	check all that apply)				Surface Soil (
	Water (A1)	· · ·	Water-Stained Leave	es (B9)		-	X Drainage Pat		
	ater Table (A2)	_	Aquatic Fauna (B13)				Moss Trim Li		
Saturati		_	Marl Deposits (B13)					Water Table (C2)	
	Marks (B1)	_	Hydrogen Sulfide Oc				Crayfish Burn		
	ent Deposits (B2)	_	Oxidized Rhizospher		ots (C3)			isible on Aerial (C9)	
	eposits (B3)	_	Presence of Reduce		(55)			tressed Plants (D1)	
	lat or Crust (B4)	_	Recent Iron Reduction	. ,	(C6)			Position (D2)	
	posits (B5)	_	Thin Muck Surface ((CO)		Shallow Aqui		
			·	-					
	tion Visible on Aeria	· · · · —	Other (Explain in Re	ilidi KS)				aphic Relief (D4)	
sparsely	y Vegetated Concave	e Surrace (B8)					FAC-Neutral	Test (D5)	
Field Observat	tions:								
Surface Water	r Present?	Х	Depth (inches):	<1"					
Water Table P	Present?	X	Depth (inches):	surface		Wetlan	d Hydrology Present	?	YES
Saturation Pre		X	Depth (inches): ing well, aerial photos, p	5411455	-+: a\ :f				
Remarks:									
SOIL									
Profile Descrip	' '	the depth needs	ed to document the indi		m the abs	ence of indi	cators.)		
Depth	Matrix		Re	dox Features					
(in) (Color (moist)	%	Color (moist)	%	Type ¹	Loc²	Texture	Re	emarks
0-5	10YR 2/3	1					SILT LOAM		
5-12	10YR 5/1	0.9	10YR 5/3	0.1			MUCKY LOAM		
		·							
		· -							
1Tunas C	Austina D Dest 11 -	NA-Dado	MC-Masked Cd C				Zi a anti Di B	na 14-14-t	
Type: C=Concent	tration, D=Depletion, F	M=Reduced Matrix,	MS=Masked Sand Grains.				² Location: PL=Pore Lini	ng, M=Matrix.	
Hydric Soil Ind	dicators:		·				Indicators for Prob	lematic Hydric So	ils ³ :
∐inkas-¹	J (A1)		Debaselis B	alow Surface Ico	\ (I pp p			, A10) (LRR K, L, MLR,	
Histosol				elow Surface (S8) (LKK K,			, , , ,	
	pipedon (A2) istic (A3)		MLRA 149	•	D MIDA 44	IOD)		Redox (A16) (LRR K	
				ırface (S9) (LRR i		+30)		Peat or Peat (S3) (LF	ΛΝ Ν, L, N)
	en Sulfide (A4)			ky Mineral (F1) (LKK K, L)			(S9) (LRR K, L, M)	ND 14 13
	ed Layers (A5)	(0.4.4)		ed Matrix (F2)				low Surface (S8) (LF	ik K, L)
	ed Below Dark Surfac	ce (A11)	X Depleted Ma					rface (S9) (LRR K, L)	55 K 1 5'
	ark Surface (A12)		Redox Dark					nese Masses (F12) (L	
	Mucky Mineral (S1)			rk Surface (F7)				oodplain Soils (F19)	•
	Gleyed Matrix (S4)		Redox Depre	essions (F8)				C (TA6) (MLRA 144A	, 145, 149B)
	Redox (S5)							Naterial (F21)	
Stripped	d Matrix (S6)		³ In	dicators of hydr	ophytic ve	getation and	Very Shallow	Dark Surface (TF12)
Dark Su	ırface (S7) (LRR R, M	LRA 149B)	wetl	land hydrology n	nust be pre	esent, unless	Other (Expla	in in Remarks)	
				dis	turbed or	problematic.			
Restrictive Lay	yer (if observed):		<u> </u>						<u> </u>
	Type: ROCK						Hydr	ic Soil Present?	YES
Depth (in	iches): 12							_	
Remarks:							•		

ø.				
ч	BT.	ı_	L.	
	v	п	п	

Vhb Sampling Point: 2023-3-1wet

		Absolute	Dom.	Indicator			
Tree	Stratum (Plot size: 30' RAD)	% Cover	Sp?	Status	Dominance Test Worksheet:		
1.	Fraxinus pennsylvanica	15	X	FACW	# Dominants OBL, FACW, FAC	10	(A)
2.	Ulmus americana	3		FACW			
3.	Populus deltoides	3		FAC	# Dominants across all strata:	11	(B)
4.							
5.					% Dominants OBL, FACW, FAC	: 91%	(A/B
6.							
7.					Prevalence Index Worksheet:		
C 11	Charles (Blat size AFI BAD	21	= Tota	Cover	Total % Cover of:	Multiply By	<u>y:</u>
	ng Stratum (Plot size: 15' RAD) Fraxinus pennsylvanica	15	х	FACW	OBL x 1 = FACW 87 x 2 =		
1. 2.	Ulmus americana			FACW	FACW 87 x 2 = FAC 84 x 3 =		_
3.	Ollius americana	<u> </u>		TACW	FACU 15 x 4 =		
4.					UPL x5=		
5.					Sum: 186 (A)	486	(B)
6.					(//)		(5)
7.					Prevalence Index = B/A	= 2.61	
,,					Trevalence mack		
		18	= Tota	Cover	Hydrophytic Vegetation Indica	ntors:	
Shru	o Stratum (Plot size: 15' RAD)				X Dominance Test is > 50		
1.	Alnus incana	15	х	FACW	X Prevalence Index is <=		
	Lonicera morrowii	15	X	FACU	Problematic Hydrophy	tic Vegetation ¹ (e	explain)
3.	Rhamnus cathartica	15	X	FAC	Rapid Test for Hydroph		
4.	Carpinus caroliniana	15	Х	FAC	Morphological Adaptat	tions	
5.	Acer negundo	15	Х	FAC	¹ Indicators of hydric soil and wetland	hydrology must be r	nresent
6.					unless disturbed or problematic.	myarology mast se p	pi eserre,
7.		<u></u>			Definitions of Vegetation Stra	ta:	
		75	= Tota	Cover			
Herb	Stratum (Plot size: 5' RAD)	<u> </u>	<u>-</u> '		Tree - Woody plants, excluding woo		
1.	Amphicarpaea bracteata	15	Х	FAC	(6m) or more in height and 3in (7.6cm	n) or larger in diamet	ter at
2.	Solidago gigantea	15	Х	FACW	breast height (DBH).		
3.	Phragmites australis	15	X	FACW			
4.	Equisetum arvense	15	X	FAC	Sapling - Woody plants, excluding v		
5.	Rubus pubescens	3		FACW	20ft (6m) or more in height and less t	han 3in (7.6cm) DBH	4.
6.	Lysimachia nummularia	3		FACW			
7.	Symphyotrichum lateriflorum	3		FAC			
8.	Eutrochium purpureum	3		FAC	Shrub - Woody plants, excluding wo	oody vines, approxim	nately 3 to
9.					20ft (1 to 6m) in height.		
10.							
11.					Herb - All herbaceous (non-woody) vines, regardless of size. Includes woo		
12.					less than approximately 3ft (1m) in he		oouy viries
14.	du Vice (District AFI DAD		= Tota	Cover			
	dy Vines (Plot size: 15' RAD)						
1.					Woody vine - Allaadia	ardless of balabt	
2.					Woody vine - All woody vines, reg	aruless of neight.	
3.					Hudrophytic		
4. 5.					Hydrophytic Vegetation		
J.			= Tota	Cover	=	VEC	
		-	- 1014	COVCI	i icaciit;		_
Remar	ks: (If observed, list morphological adaptations below). Ranunculus sp. was observed at 3%		= Tota	Cover	Present?	YES	



Vermont Potential Rare, Threatened, and Endangered Species and Natural Communities in the Project Region and Onsite Habitats Summary

Client: Vtrans Project: Ferrisburgh BF019-4(35)

Prepared by: VHB (C. Peterson, C. Fenner) October 28, 2023

	Field Habitat Assessment Date: October, 2023															
														Survey Recommended?		
	Species	Common Name	Туре	State Rank	Global Rank	VT Status	Federal Status	Last Observed Date	Habitat Description ¹	Occurrence Description ²	Optimal Survey	EO Mapped within Study Area (Yes/ No)	Potential for Habitat to Occur Onsite?	(yes/no)	Comments	
	Lasmigona compressa	Creek Heelsplitter	Animal	S2	G5	-	-	2003	Creeks, small rivers; prefers sand, fine gravel and mud substrates.	Lewis Creek, midway between Greenbush Road and Route 7	Summer - Fall	Yes	Yes	No	Although polygon mapped in Study Area, Project avoids aquatic habitats, so no survey recommended	
	Potamilus alatus	Pink Heelsplitter	Animal	S2	G5	E	-	1997	Creeks, small rivers; prefers sand, fine gravel and mud substrates.	Lewis Creek mouth, near F&W Department. Lewis Creek at Greenbush Road.	Summer - Fall	Yes	Yes	No	Although polygon mapped in Study Area and state-listed, Project avoids aquatic habitats, so no survey recommended	
	Bartramia longicauda	Upland Sandpiper	Animal	S2B	G5	E	-	1988	Prairies, open meadows and fields. Native grassland; mixed with tall grass and broad-leaved weeds.	Junction of Fuller Mountain Road and Four Winds Road, southeast 0.25 miles on Fuller Mountain, at Royer Farm.	Spring - Summer	No	Yes	No	No suitable habitat in Study Area	
	Sturnella magna	Eastern Meadowlark	Animal	S2B	G5	Т	-	2022	Wetter grasslands and prairies, pastures, hayfields, roughly 6 acres territory.	Quaker Street, between Jewell Lane and Greebush Road, fields on south side of Quaker Street just east of Harvest Lane.	Spring	No	Yes	No	No suitable habitat in Study Area	
	Myotis lucifugus	Little Brown Bat	Animal	S1	G3G4	E	UR	2006	Mixed woodlands with snags; caves, mines, anthropogenic structures	Ferrisburgh, north of Lewis Creek, south of Stage Road, west of Route 7, east of Greenbush Road. Mist-netting site "Pigeons Roost Pierce Woods" south end of Pidgeons Roost Road.	Summer	No	Yes	Yes*	Species is extremely rare in Vermont, listed state endangered, and site has potential suitable habitat. Survey recommended if Project requires tree cutting and cannot adhere to time-of-year restrictions	
	Myotis septentrionalis	Northern Long- eared Bat	Animal	S1	G2G3	E	E	2006	Mixed woodlands with snags; caves, mines, anthropogenic structures	Ferrisburgh, north of Lewis Creek, south of Stage Road, west of Route 7, east of Greenbush Road. Mist-netting site "Pigeons Roost Pierce Woods" south end of Pidgeons Roost Road.	Summer	No	Yes	Yes*	Species is extremely rare in Vermont, listed state endangered, and site has potential suitable habitat. Survey recommended if Project requires tree cutting and cannot adhere to time-of-year restrictions	
ea Centerpoint	Pyganodon grandis	Giant Floater	Animal	S2S3	G5	Т	-	1997	Shallow streams, lakes and pools with fine sediment such as sand or gravel substrates; preference to little to no flow.	Lewis Creek Delta, unspecified location; above and below Greenbush Road.	Summer	No	No	No	Although state-listed and potential habitat on site in Lewis Creek, Project avoids aquatic habitats, so no survey recommended	
tadius from Study Area	Lasmigona costata	Flutedshell	Animal	S 2	G5	E	-	2006	Small to medium rivers and lakes, often in gravel substrates with swift currents.	Lewis Creek, midway between Greenbush Road and Route 7	Late Summer - Fall	Yes	Yes	No	Although state-listed and potential habitat on site in Lewis Creek, Project avoids aquatic habitats, so no survey recommended	
1-Mile Element Occurrence F	Notropis heterolepis	Blacknose Shiner	Animal	S1	G5	-	-	2010	Creeks, small rivers, shallower areas of lakes with aquatic vegetation. Usually in cool, clear waters over sand.	Ferrisburgh, Lewis Creek, coordinates provided in DEC fish database, approx. 3 miles above mouth.	Late Summer - Fall	No	No	No	Although species is critically rare, it is not state/federally listed and the site does not provide potential habitat suitability.	
1-Mile	Ichthyomyzon unicuspis	Silver Lamprey	Animal	S2	G5	-	-	2016	Large streams and lakes, often those with gravel riffles, shallow streams with loose sediment for ammocoete spawning.	Lewis Creek, Ferrisburgh. Just below Greenbush Road crossing.	Spring - Summer	No	No	No	Species not listed and polygon not mapped in Study Area	
	Hetaerina americana	American Rubyspot	Animal	S2S3	G5	-	-	2006	Creeks to large rivers with moderate current and aquatic vegetation, frequent around riffles.	Lewis Creek, Charlotte, at Quinlan Bridge, about 200 meters above Route 7	Summer - Late Summer	Yes	Yes	No	Although polygon mapped in Study Area, Project avoids aquatic habitats, so no survey recommended	
	Potamogeton strictifolius	Straight-leaf Pondweed	Plant	S2S3	G5	-	-	1972	Shallow, still or slow-moving streams, lakes, ponds, rivers, tolerant to basic waters.	Lewis Creek elevation 96 feet	Spring	No	Yes	No	Species not listed and polygon not mapped in Study Area	
	Glyptemys insculpta	Wood Turtle	Animal	S3	G3	1	UR	2006	Forested streams, open grasslands, barrens, sandy shores (spring, nesting).	Ferrisburgh, Lewis Creek, southbound shoulder of Rte 7. 1/10 mile north of Lewis Creek.	Spring - Late Summer	Yes	No	No	Although polygon is mapped in Study Area, Lewis Creek bed and bank conditions not suitable habitat for this species	
	Leptodea fragilis	Fragile Papershell	Animal	S2	G5	E	-	1997	Freshwater, streams and rivers of all sizes and turbidity, preference for mud, gravel, and sand substrates.	Lewis Creek, unspecified location; above and below Greenbush Road.	Summer	Yes	Yes	No	Although state-listed and potential habitat on site in Lewis Creek, Project avoids aquatic habitats, so no survey recommended	
	Lampsilis ovata	Pocketbook	Animal	S2	G5	E	-	2022	Rivers of varying sizes, with moderate to slow flows. Substrate a mix of silt, mud and/or sand	Lewis Creek, at Greenbush Road, Greenbush Road to Route 7, downstream of Loven Road, Lewis Creek Delta.	Late Summer	Yes	Yes	No	Although state-listed and potential habitat on site in Lewis Creek, Project avoids aquatic habitats, so no survey recommended	
	Anguilla rostrata	American Eel	Animal	S2	G4	-	-	2021	Primarily riverine, but occasionaly in lakes and ponds. Variety of freshwater habitats, fond of dark corners of water bodies.	Ferrisburgh, captured.	Summer	Yes	Yes	No	Although lacking state/federal listing, species is rare, and recorded within the study area which provides potential suitable habitat	

¹Potential sources for habitat description listed below:

Brown, Paul Martin. 2007. Wild Orchids of the Northeast: New England, New York, Pennsylvania, and New Jersey. University Press of Florida.

Conant, Roger and Collins, Joseph T. 1998. Peterson Field Guides: Reptiles and Amphibians . Houghton Mifflin Company, Boston EFloras.org. http://www.efloras.org/index.aspx

Gilman, Arthur V. 2015. New Flora of Vermont. New York Botanical Garden.
Haines, Arthur. 2011. Flora Novae Angliae. New England Wildflower Society/Yale University Press, New Haven, CT. 973 Pp. $Illinois\ Natural\ History\ Survey.\ http://www.inhs.uiuc.edu/animals_plants/mollusk/musselmanual/TofC.html$

Langdon, Richard W., Ferguson, Mark T. and Cox, Kenneth M. 2006. Fishes of Vermont . Vermont Department of Fish and Wildlife.

Maine Department of Agriculture, Conservation and Forestry. Accessed: http://www.maine.gov/dacf/mnap/features/rare_plants/plantlist.htm Newcomb, Lawrence. 1977. Newcomb's Wildflower Guide. Little, Brown, and Company, Boston

Northern Prairie Wildlife Research Center. http://www.npwrc.usgs.gov/resource/distripets/tigb/usa/49.htm

Seymour, Frank Conkling. 1982. The Flora of New England. 2d ed. Phytologia Memoirs 5. Plainfield, NJ: Harold N. Moldenke and Alma L. Moldenke. 611 p. [7604]

Thompson, Elizabeth H. and Sorenson, Eric R. 2005. Wetland, Woodland, Wildland: A Guide to the Natural Communities of Vermont. Vermont Department of Fish and Wildlife and The Nature Conservancy. Vermont Natural Resources Atlas, Accessed September 19, 2023 and October 28, 2023. Element Occurrence Reports





Partial Floristic Inventory - Species Checklist

Project: Ferrisburgh BF 019-4(35)

Client: Vermont Agency of Transportation

Location: Ferrisburgh, Vermont **Prepared By:** VHB; October 23, 2023

Survey Date(s): VHB (M. Jackman) on October 9, 2023

Scientific Name ¹	Common Name	Family	VT Rarity Rank ^{2,3}	Non-Native Invasive
Acer negundo L.	boxelder	Aceraceae	_	Species
Acer rubrum L.	red maple	Aceraceae	_	
Acer saccharinum L.	silver maple	Aceraceae	_	_
Acer saccharum Marshall	<u>'</u>	Aceraceae	_	
	sugar maple			
Acception of tissions (L) R.M. King 8: U. Beh	bishop's goutweed	Apiaceae	-	-
Ageratina altissima (L.) R.M. King & H. Rob.	white snakeroot	Asteraceae	-	-
Alliaria petiolata (M. Bieb.) Cavara & Grande	garlic mustard	Brassicaceae	-	В
Amphicarpaea bracteata (L.) Fernald	American hogpeanut	Fabaceae	-	-
Artemisia vulgaris L.	common wormwood	Asteraceae	-	-
Asarum canadense L.	Canadian wildginger	Aristolochiaceae	-	-
Betula lenta L.	sweet birch	Betulaceae	-	-
Berberis vulgaris L.	common barberry	Berberidaceae	-	-
Bromus inermis Leyss.	smooth brome	Poaceae	-	-
Carpinus caroliniana Walter	American hornbeam	Betulaceae	-	-
Carya cordiformis (Wangenh.) K. Koch	bitternut hickory	Juglandaceae	-	-
Carex crinita Lam.	fringed sedge	Cyperaceae	-	-
Carya ovata (Mill.) K. Koch	shagbark hickory	Juglandaceae	-	-
Daucus carota L.	Queen Anne's lace	Apiaceae	-	-
Deparia acrostichoides (Sw.) M. Kato	silver false spleenwort	Dryopteridaceae	-	-
Doellingeria umbellata (Mill.) Nees	parasol whitetop	Asteraceae	-	-
Dryopteris marginalis (L.) A. Gray	marginal woodfern	Dryopteridaceae	-	-
Elaeagnus angustifolia L.	Russian olive	Elaeagnaceae	-	-
Eurybia divaricata (L.) G.L. Nesom	white wood aster	Asteraceae	-	-
Euthamia graminifolia (L.) Nutt.	flat-top goldentop	Asteraceae	_	_
Fagus grandifolia Ehrh.	American beech	Fagaceae	_	_
Frangula alnus Mill.	glossy buckthorn	Rhamnaceae	_	_
Fraxinus americana L.	white ash	Oleaceae	_	_
Fraxinus pennsylvanica Marshall	green ash	Oleaceae		_
Galium mollugo L.	false baby's breath	Rubiaceae	-	
•	•	Rubiaceae	-	_
Galium palustre L. Geum rivale L.	common marsh bedstraw		-	-
	purple avens	Rosaceae	-	
Hackelia virginiana (L.) I.M. Johnst.	beggarslice	Boraginaceae	-	-
Hamamelis virginiana L.	American witchhazel	Hamamelidaceae	-	-
Hesperis matronalis L.	dames rocket	Brassicaceae	-	WL
Impatiens capensis Meerb.	jewelweed	Balsaminaceae	-	-
Juniperus virginiana L.	eastern redcedar	Cupressaceae	-	-
Lonicera morrowii A. Gray	Morrow's honeysuckle	Caprifoliaceae	-	В
Lythrum salicaria L.	purple loosestrife	Lythraceae	-	В
Lysimachia nummularia L.	creeping jenny	Primulaceae	-	-
Maianthemum canadense Desf.	Canada mayflower	Liliaceae	-	-
Mitchella repens L.	partridgeberry	Rubiaceae	-	-
Onoclea sensibilis L.	sensitive fern	Dryopteridaceae	-	-
Osmorhiza berteroi DC.	sweetcicely	Apiaceae	-	-
Osmunda cinnamomea L.	cinnamon fern	Osmundaceae	-	-
Ostrya virginiana (Mill.) K. Koch	hophornbeam	Betulaceae	-	-
Parthenocissus quinquefolia (L.) Planch.	Virginia creeper	Vitaceae	-	-
Pastinaca sativa L.	wild parsnip	Apiaceae	-	WL
Phalaris arundinacea L.	reed canarygrass	Poaceae	-	WL
Phragmites australis (Cav.) Trin. ex Steud.	common reed	Poaceae	-	В
Phleum pratense L.	timothy	Poaceae	-	-
Pilea pumila (L.) A. Gray	Canadian clearweed	Urticaceae	-	_
Pinus strobus L.	eastern white pine	Pinaceae	-	-
I UIUS SUUDUS L.	eastern write pine	rinaceae	i -	_



Project: Ferrisburgh BF 019-4(35)

Client: Vermont Agency of Transportation

Location: Ferrisburgh, Vermont **Prepared By:** VHB; October 23, 2023

Survey Date(s): VHB (M. Jackman) on October 9, 2023

Scientific Name ¹	Common Name	Family	VT Rarity Rank ^{2,3}	Non-Native Invasive Species ⁴
Populus balsamifera L.	balsam poplar	Salicaceae	-	-
Populus deltoides W. Bartram ex Marshall	eastern cottonwood	Salicaceae	-	-
Populus tremuloides Michx.	quaking aspen	Salicaceae	-	-
Prunus serotina Ehrh.	black cherry	Rosaceae	-	-
Prunus virginiana L.	chokecherry	Rosaceae	-	-
Quercus bicolor Willd.	swamp white oak	Fagaceae	-	-
Quercus rubra L.	northern red oak	Fagaceae	-	-
Rhamnus cathartica L.	common buckthorn	Rhamnaceae	-	В
Rhus hirta	Staghor sumac	Anacardiacaea	-	-
Rubus idaeus L.	American red raspberry	Rosaceae	-	-
Rubus pubescens Raf.	dwarf red blackberry	Rosaceae	-	-
Salix nigra Marshall	black willow	Salicaceae	-	-
Solidago caesia L.	wreath goldenrod	Asteraceae	-	-
Solidago canadensis L.	Canada goldenrod	Asteraceae	-	-
Solanum dulcamara L.	climbing nightshade	Solanaceae	-	-
Solidago flexicaulis L.	zigzag goldenrod	Asteraceae	-	-
Solidago gigantea Aiton	giant goldenrod	Asteraceae	-	-
Solidago rugosa Mill.	wrinkleleaf goldenrod	Asteraceae	-	-
Cornus racemosa Lam.	gray dogwood	Cornaceae	=	-
Cornus sericea L.	redosier dogwood	Cornaceae	-	-
Symphyotrichum lateriflorum (L.) Á. Löve & D. Löve	calico aster	Asteraceae	-	-
Symphyotrichum novae-angliae (L.) G.L. Nesom	New England aster	Asteraceae	-	-
Taraxacum officinale F.H. Wigg.	common dandelion	Asteraceae	=	-
Thuja occidentalis L.	arborvitae	Cupressaceae	-	-
Tilia americana L.	American basswood	Tiliaceae	-	-
Toxicodendron radicans (L.) Kuntze	eastern poison ivy	Anacardiaceae	-	-
Trifolium pratense L.	red clover	Fabaceae	=	-
Trifolium repens L.	white clover	Fabaceae	-	-
Tsuga canadensis (L.) Carrière	eastern hemlock	Pinaceae	-	-
Tussilago farfara L.	coltsfoot	Asteraceae	-	-
Ulmus americana L.	American elm	Ulmaceae	-	-

¹ Nomenclature follows USDA-NRCS PLANTS database (plants.usda.gov/) (2023).

² The Vermont Rarity Rank from the "Rare and Uncommon Native Vascular Plants of Vermont - Vermont Natural Heritage Inventory - Vermont Fish & Wildlife Department", version dated May 4, 2022.

³ The Vermont Rarity Rank from the "Endangered and Threatened Plants of Vermont - Vermont Natural Heritage Inventory - Vermont Fish & Wildlife Department", version dated February 10, 2022.

⁴ Class B Noxious Weeds Species (B) from: Quarantine #3- Noxious Weeds (2012).
Watch List Species (WL) from: Vermont Invasive Exotic Plant Committee. 2017. Quarantine and Watch List Update.



United States Department of the Interior



FISH AND WILDLIFE SERVICE

New England Ecological Services Field Office 70 Commercial Street, Suite 300 Concord, NH 03301-5094 Phone: (603) 223-2541 Fax: (603) 223-0104

In Reply Refer To: November 07, 2023

Project Code: 2024-0013304

Project Name: Ferrisburgh BF 019-4(35)

Subject: List of threatened and endangered species that may occur in your proposed project

location or may be affected by your proposed project

To Whom It May Concern:

Updated 4/12/2023 - Please review this letter each time you request an Official Species List, we will continue to update it with additional information and links to websites may change.

About Official Species Lists

The purpose of the Act is to provide a means whereby threatened and endangered species and the ecosystems upon which they depend may be conserved. Federal and non-Federal project proponents have responsibilities under the Act to consider effects on listed species.

The enclosed species list identifies threatened, endangered, proposed, and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and/or may be affected by your proposed project. The species list fulfills the requirements of the U.S. Fish and Wildlife Service (Service) under section 7(c) of the Endangered Species Act (Act) of 1973, as amended (16 U.S.C. 1531 et seq.).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Please note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the Act, the accuracy of this species list should be verified after 90 days. The Service recommends that verification be completed by visiting the IPaC website at regular intervals during project planning and implementation for updates to species lists and information. An updated list may be requested by returning to an existing project's page in IPaC.

Endangered Species Act Project Review

Please visit the "New England Field Office Endangered Species Project Review and Consultation" website for step-by-step instructions on how to consider effects on listed

species and prepare and submit a project review package if necessary:

https://www.fws.gov/office/new-england-ecological-services/endangered-species-project-review

NOTE Please <u>do not</u> use the **Consultation Package Builder** tool in IPaC except in specific situations following coordination with our office. Please follow the project review guidance on our website instead and reference your **Project Code** in all correspondence.

Northern Long-eared Bat - (**Updated 4/12/2023**) The Service published a final rule to reclassify the northern long-eared bat (NLEB) as endangered on November 30, 2022. The final rule went into effect on March 31, 2023. You may utilize the **Northern Long-eared Bat Rangewide Determination Key** available in IPaC. More information about this Determination Key and the Interim Consultation Framework are available on the northern long-eared bat species page:

https://www.fws.gov/species/northern-long-eared-bat-myotis-septentrionalis

For projects that previously utilized the 4(d) Determination Key, the change in the species' status may trigger the need to re-initiate consultation for any actions that are not completed and for which the Federal action agency retains discretion once the new listing determination becomes effective. If your project was not completed by March 31, 2023, and may result in incidental take of NLEB, please reach out to our office at newengland@fws.gov to see if reinitiation is necessary.

Additional Info About Section 7 of the Act

Under section 7(a)(2) of the Act and its implementing regulations (50 CFR 402 et seq.), Federal agencies are required to determine whether projects may affect threatened and endangered species and/or designated critical habitat. If a Federal agency, or its non-Federal representative, determines that listed species and/or designated critical habitat may be affected by the proposed project, the agency is required to consult with the Service pursuant to 50 CFR 402. In addition, the Federal agency also may need to consider proposed species and proposed critical habitat in the consultation. 50 CFR 402.14(c)(1) specifies the information required for consultation under the Act regardless of the format of the evaluation. More information on the regulations and procedures for section 7 consultation, including the role of permit or license applicants, can be found in the "Endangered Species Consultation Handbook" at:

https://www.fws.gov/service/section-7-consultations

In addition to consultation requirements under Section 7(a)(2) of the ESA, please note that under sections 7(a)(1) of the Act and its implementing regulations (50 CFR 402 et seq.), Federal agencies are required to utilize their authorities to carry out programs for the conservation of threatened and endangered species. Please contact NEFO if you would like more information.

Candidate species that appear on the enclosed species list have no current protections under the ESA. The species' occurrence on an official species list does not convey a requirement to

consider impacts to this species as you would a proposed, threatened, or endangered species. The ESA does not provide for interagency consultations on candidate species under section 7, however, the Service recommends that all project proponents incorporate measures into projects to benefit candidate species and their habitats wherever possible.

Migratory Birds

In addition to responsibilities to protect threatened and endangered species under the Endangered Species Act (ESA), there are additional responsibilities under the Migratory Bird Treaty Act (MBTA) and the Bald and Golden Eagle Protection Act (BGEPA) to protect native birds from project-related impacts. Any activity, intentional or unintentional, resulting in take of migratory birds, including eagles, is prohibited unless otherwise permitted by the U.S. Fish and Wildlife Service (50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)). For more information regarding these Acts see:

https://www.fws.gov/program/migratory-bird-permit

https://www.fws.gov/library/collections/bald-and-golden-eagle-management

Please feel free to contact us at **newengland@fws.gov** with your **Project Code** in the subject line if you need more information or assistance regarding the potential impacts to federally proposed, listed, and candidate species and federally designated and proposed critical habitat.

Attachment(s): Official Species List

Attachment(s):

Official Species List

OFFICIAL SPECIES LIST

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

New England Ecological Services Field Office 70 Commercial Street, Suite 300 Concord, NH 03301-5094 (603) 223-2541

PROJECT SUMMARY

Project Code: 2024-0013304


Project Name: Ferrisburgh BF 019-4(35)

Project Type: Road/Hwy - Maintenance/Modification

Project Description: Transportation project in vicinity of US-7 bridge over Lewis Creek

Project Location:

The approximate location of the project can be viewed in Google Maps: https://www.google.com/maps/@44.24850765,-73.22904586803597,14z



Counties: Addison County, Vermont

ENDANGERED SPECIES ACT SPECIES

There is a total of 3 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries¹, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

1. <u>NOAA Fisheries</u>, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

MAMMALS

NAME STATUS

Indiana Bat Myotis sodalis

Endangered

There is **final** critical habitat for this species. Your location does not overlap the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/5949

Northern Long-eared Bat Myotis septentrionalis

Endangered

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9045

INSECTS

NAME STATUS

Monarch Butterfly *Danaus plexippus*

Candidate

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9743

CRITICAL HABITATS

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

YOU ARE STILL REQUIRED TO DETERMINE IF YOUR PROJECT(S) MAY HAVE EFFECTS ON ALL ABOVE LISTED SPECIES.

IPAC USER CONTACT INFORMATION

Agency: VHB

Name: carla fenner Address: 40 IDX Drive

Address Line 2: Building 100, Suite 200

City: South Burlington

State: VT Zip: 05403

Email cfenner@vhb.com Phone: 8027344355

Appendix G: Archeology Memo

Alexander Honsinger MA, RPA | Cultural Resources Specialist Vermont Agency of Transportation 219 North Main Street | Barre, VT 05641 802–793-7456 phone <u>| Al.Honsinger@vermont.gov</u> http://vtrans.vermont.gov



To: Julie Ann Held, Environmental Specialist

Subject: Ferrisburgh BF 019-4(35) – Archaeological Resource ID

This archaeological resource identification memo pertains to potential work at Bridge #139, constructed in 1957, which carries VT-7 over Lewis Creek in the town of Ferrisburgh.

Physical Environment

VTrans staff analyzed an approximately 2.6-ac area encompassing the bridge and four adjacent landform quadrants for this archaeological resource identification effort (Figures 1 and 2). The project area is situated along Lewis Creek in the Champlain Valley biophysical region (Vermont Geodata Portal 2022). Champlain Valley terrain adjoining the lake is characterized by level landforms containing diverse oak-hickory forests interspersed with agricultural land. Expansive swamps, marshes, and floodplains proximate to Lewis Creek provide waterfowl and marsh bird habitats that were significant resources to past peoples (Vermont Fish and Wildlife 2023). Bedrock within the preliminary project APE is mapped as the Upper Ordovician Iberville formation (Oib) and characterized by dark-gray shale with thin, discontinuous beds of siltstone (Ratcliffe et al. 2011). Shale and siltstone are most often too fissile and brittle to produce chipped stone tools; these materials may have been used in the past to manufacture expedient edge tools during instances when more suitable material was unavailable. According to the Natural Resource Conservation Service (NRCS) Websoil Survey, soils within the APE are classified as Hadley very fine sandy loam alluvium (34.9%), glaciolacustrine Vergennes Clay (16.5%), and Winooski very fine sandy loam alluvium (31.6%) (USDA 2023).

Pre-contact Archaeological Sensitivity

The source of Lewis Creek lies in the Southern Green Mountain physiographic province in the present-day town of Starksboro. The river's course subsequently meanders through Monkton, Hinesburg, Charlotte, and Ferrisburgh before emptying into Lake Champlain (Figure 3). Historic documentation suggests that Lewis Creek was an important node in traditional Abenaki territory. According to an 1896 letter written by naturalist Rowland E. Robinson to United States Bureau of Fisheries biologist William Converse Kendall, the outlet of Lewis Creek at Lake Champlain was a preferred fish netting location for migratory, lake-locked species and known to the Abenaki as "Sungahneetook," supposedly translating to "Fishing Weir River" (Kendall 1927:327) (Figure 4). During the nineteenth century, travels of citizens from Odanak to visit their ancestral homelands in the Champlain Valley and sell crafts were common (Smith 1886:664-678). Rowland also had a relationship with John Watso of Odanak, who acted as an informant regarding Abenaki lifeways and may have provided the author with the traditional placename for Lewis Creek (Leary 2021).



There are no previously recorded archaeological sites in the preliminary APE and no previous archaeological projects have been conducted within potential impact areas. While there are no previously recorded precontact archaeological sites within the preliminary APE, eight precontact sites lie within an 1 mile (1.6 km) radius of Bridge 139 (VDHP 2023). Previously recorded Pre-contact archaeological sites line the course of greater Lewis Creek and adjacent wetlands throughout the town of Ferrisburgh; site density along the watershed provides additional evidence for the significance of the river corridor within historic Abenaki and Precontact community settlement patterns.

Using the Vermont Division of Historic Preservation's (VDHP 2015) Environmental Predictive Model for Locating Pre-contact Archaeological Sites, undisturbed areas within vicinity of the preliminary APE score above the 32-point threshold to be considered archaeologically sensitive. Contributing factors to archaeological sensitivity include the proximity of Lewis Creek (0-90m), wetlands (0-90m), high recorded site density, and a natural travel corridor.

Historic Period Background and Archaeological Sensitivity

Records concerning European settlement in Ferrisburgh are limited until the close of the American Revolution. Following this, settlement again commenced, and families arrived to establish farms within the fertile Champlain Valley. Agriculture represented the predominate vocation of Ferrisburgh settlers following the town's founding and throughout the succeeding century (Smith 1886:439). Despite this, ancillary cottage industries of the period were developed in town including, but not limited to, the construction of sawmills, gristmills, and potasheries. Falls along Little Otter Creek, Cronkhite Brook, and Lewis Creek were among the watersheds selected for small-scale industry in Ferrisburgh, such as the sawmill formerly located downstream from the project area visible on historic maps (Walling 1857; Figure 4). Despite these efforts, the town's production sector was invariably overshadowed by the immense hydropower that could be drawn from the falls in Vergennes along the Otter Creek (Smith 1886:445-448).

Vermont residents began raising Merino sheep upon the introduction of Spanish flocks during the early nineteenth century. The breed figured prominently in the state's agricultural sector until regions possessing more amenable climate obtained flocks, such as the western United States and Australia. Following the reduction of the wool industry in the Champlain Valley, dairy production regained prominence and has remained significant in Ferrisburgh's agricultural economy (Robinson 1892:355-366; Town of Ferrisburgh 2011).

Historic maps demonstrate that the present route of VT-7 and Bridge #139 was not established until the mid-twentieth century and built to carry the roadway over Lewis Creek (Figures 5-8). This trapezoidal, artificial landform is clearly visible in LIDAR imagery (Figure 2; Vermont Geodata Portal 2017). Despite the presence of mapped domestic structures within available historic maps, the extensive construction impact of the bridge and roadway would have destroyed any remains within its footprint (Figures 5 and 6). In addition, analysis of LIDAR imagery did not reveal any anomalies or previously undiscovered foundations in the preliminary APE (Figure 2).



Summary

Following background research and desktop analysis, VTrans staff conducted a site visit on August 29, 2023, to assess the archaeological sensitivity of the project area (Figures 9-12). The areas denoted on the maps below (Figure 13 and 14) outside the VT-7 roadway prism and footprint of disturbance from the construction of Bridge 139 should be considered sensitive for precontact archaeological resources. Landforms proximate to the course of course of Lewis Creek depicted in the archaeological sensitivity maps below also have potential to contain deeply buried archaeological deposits. Unless these archaeologically sensitive areas can be avoided by project developments, further field investigations will be required. Once project plans and scope become available, a formal review will be issued.

Please let me know if you have any questions. Thank you, Alexander Honsinger VTrans Cultural Resources Specialist






Figure 1. Preliminary Project APE.






Figure 2. Preliminary APE on LIDAR imagery digital elevation model (Vermont Geodata Portal 2017).




Figure 3. Map depicting the Lewis Creek Watershed on USGS Topographic Maps.



Figure 4. A man fishes along the Lewis Creek ca. 1877 at the location of the former Stage Road Covered Bridge, now Bridge No. 139. Photograph from the personal collection of Rowland E. Robinson (La Narna 1887).






Figure 5. Approximate APE on Walling (1857) map.




Figure 6. Approximate APE on Beers (1871) map.




Figure 7. APE on USGS (1903) map.




Figure 8. APE on USGS (1963) map.



Figure 9. Northeastern bridge quadrant.



Figure 10. Northwestern bridge quadrant.



 ${\bf Figure~11.~Southwestern~bridge~quadrant.}$





 ${\bf Figure~12.~Southeastern~bridge~quadrant.}$






Figure 13. Archaeologically sensitive within the preliminary APE.






Figure 13. Archaeologically sensitive area within the preliminary APE and LIDAR imagery (Vermont Geodata Portal 2017).

VERMONT

References

Beers, F. W.

1871 County Atlas of Addison, Vermont. F. W. Beers and Co., New York.

Kendall, William Converse

1927 The Smelts. United States Bureau of Fisheries Bulletin No. 42: 217-375.

La Narna, Frank

Fishing in Lewis Creek. Electronic Resource, glcp.uvm.edu/landscape_new/search/details.php?ls=20354&sequence=000&set_seq=35 &imageSet=1702930738-6580a932a0fbe&AddRel=0, Accessed December 15, 2023.

Leary, Dean

2021 Reading Rowland Evans Robinson. Paper presented to the Rokeby Museum. Electronic Resource, https://rokeby.org/reading-rowland-evans-robinson-video/, Accessed December 15, 2023.

Ratcliffe, Nicholas M., Rolfe S. Stanley, Marjorie H. Gale, Peter J. Thompson, and Gregory J. Walsh

2011 Bedrock Geologic Map of Vermont. USGS Scientific Investigations Series Map 3184, 3 sheets, scale 1:100,000.

Robinson, Roland Evans

1886 Vermont A Study of Independence. Houghton, Mifflin and Company. Boston and New York.

Smith, Henry Perry

1886 History of Addison County, Vermont with Illustrations and Biographical Sketches of Some of its Prominent Men and Pioneers. D. Mason & Co. Syracuse, New York.

United States Department of Agriculture (USDA)

Web Soil Survey. Electronic Resource, https://websoilsurvey.nrcs.usda.gov/app/, accessed November 11, 2023.

Town of Ferrisburgh

2011 Welcome to Ferrisburgh, Vermont. Electronic Resource, https://www.ferrisburghvt.org/, accessed December 15, 2023.

Vermont Center For Geographic Information

2023 Parcel Viewer. Electronic Resource, https://maps.vcgi.vermont.gov/parcelviewer/, accessed November 11, 2023.

Vermont Division for Historic Preservation (VDHP)

2015 Environmental Predictive Model for Locating Pre-contact Archaeological Sites. Electronic Resource, https://accd.vermont.gov/historic-preservation/review-compliance/precontact-archaeological-sites, retrieved November 11, 2023.



2023 Online Resource Center. Electronic Resource, http://accdservices.vermont.gov/orc/, accessed November 11, 2023.

Vermont Fish and Wildlife

2023 Biophysical Regions and a Landscape Perspective for Conservation and Management. In, *Wildlife Habitat Management – A Landowner's Guide*, pp 8-11. Montpelier, Vermont.

Vermont Geodata Portal

- 2017 Lidar Hillshade. Electronic Resource, https://geodata.vermont.gov/pages/elevation, retrieved November 11, 2023.
- 2022 Vermont Biophysical Regions Map Electronic Resource, https://geodata.vermont.gov/datasets/VTANR::vermont-biophysical-regions/about, retrieved November 11, 2023.

Walling, Henry F.

1857 Map of Addison County, Vermont. Baker, Tilden & Co, Boston.



Appendix H: Historic Memo



Vermont Agency of Transportation Project Delivery Bureau - Environmental Section Barre City Place

Tel: 802.595-3744

To: JulieAnn Held

From: Judith Williams Ehrlich, VTrans Historic Preservation Officer

Date: March 27, 2024

Subject: Historic Resource Identification for Ferrisburgh BF 019-4(35)

I have completed a resource identification (ID) for Ferrisburgh BF 019-4(35). At this time, the project is anticipated to include repairs to or replacement of Bridge No. 139.

This Resource Identification effort is being undertaken to provide information to the VTrans designers working on a proposed improvement project. Toward that end, VTrans Cultural Resources staff have identified potential resources within a broad preliminary Area of Potential Effect to ensure the designers are aware of all cultural resources that could possibly be affected by a project. Once the project is defined at the Conceptual Design phase, Cultural Resources staff will be able to determine a formal Area of Potential Effect for purposes of Section 106 and 22 VSA § 14.

VTrans hired WSP USA, Inc. to survey and evaluate Bridge No. 139 on U.S. Route 7 in Ferrisburgh. In their report titled, "Historic Resources Identification Survey, Bridge No. 139 over Lewis Creek, U.S. Route 7, Ferrisburgh BF 019-4(35)" WSP recommended that Bridge No. 139 is not historic nor is it eligible for listing in the National Register of Historic Places. I concur with their recommendation.

There are no other buildings or structures in the project area.

There are no Section 4(f) property types in the project area.

Please do not hesitate to contact me should you require additional information.

Appendix I: Environmental Specialist Resource ID



State of Vermont Highways-PDB-Environmental 219 N. Main Street www.aot.state.vt.us Agency of Transportation

Date: March 27, 2024

Environmental Specialist: Julie Ann Held Project: Ferrisburgh BF 019-4(35)

6(f) Properties:

There aren't any 6(f) Properties within the project area.

Hazardous Waste:

There aren't any Hazardous Wastes Sites identified within the project area.

Contaminated Soils:

There aren't any Contaminated Soils within the project area.

Wild Scenic Rivers:

There aren't any designated Wild Scenic Rivers within the project area.

Act 250 Permits:

There aren't any Act 250 Permits within the project area.

FEMA Floodplains:

There are FEMA Floodplains mapped within the project area and a Flood Hazard Area/ River Corridor Permit may be required if there are impacts.

River Corridor:

There are River Corridors mapped within the project area and a Flood Hazard Area/ River Corridor Permit may be required if there are impacts.

Protected Lands:

There are Protected Lands mapped within the project area. These lands are listed as the Vermont River Conservancy Easement. The PM should design to avoid impacting these parcels due to requiring additional NEPA and permitting requirements.

US Coast Guard:

There aren't any US Coast Guard navigable waterways within the project area.

Lakes and Ponds:

There aren't any lakes or ponds within the project area.

Scenic Highway/ Byway:

There aren't any Scenic Highway/ Byways within the project area.

Environmental Justice:

There aren't any EJ populations present within the study area, therefore there isn't any potential to have a disproportionately high and adverse effect.

Other:

There aren't any other resources within the project area.

Appendix J: Hazardous Sites Map





Hazardous Waste Urban Soils Map

Vermont Agency of Natural Resources

vermont.gov



LEGEND


Landfills

OPERATING



Land Use Restrictions

- Class IV GW Reclass
- Class VI GW Reclass
- Deed Restriction
- Easement
- Land Record Notice
- Other
- Hazardous Site
- Hazardous Waste Generators
 - Brownfields
- Salvage Yard
- Aboveground Storage Tank
 - Underground Storage Tank (w
- Dry Cleaner
 - Architectural Waste Recycling
 - Urban Soil Background Areas
 - Parcels (standardized)
 - Town Boundary



495.0 0 248.00 495.0 Meters

WGS_1984_Web_Mercator_Auxiliary_Sphere 1" = 812 Ft. 1cm = 97 Meters

© Vermont Agency of Natural Resources THIS MAP IS NOT TO BE USED FOR NAVIGATION

DISCLAIMER: This map is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. ANR and the State of Vermont make no representations of any kind, including but not limited to, the warranties of merchantability, or fitness for a particular use, nor are any such warranties to be implied with respect to the data on this map.

NOTES

Map created using ANR's Natural Resources Atlas

Appendix K: Stormwater Resource ID



State of Vermont Environmental Section 219 North Main Street Barre, Vermont 05641

Vtrans.vermont.gov

Agency of Transportation

[phone] 802-498-5787

To: Project file

From: Heather Voisin, VTrans Green Infrastructure Engineer

Date: January 19, 2024

Subject: Ferrisburgh BF 019-4(35) - Stormwater Resource ID Review

Project Description: I have reviewed the project area for Ferrisburgh BF 019-4(35) for stormwater related regulatory and water quality concerns. At this time, the project scope has not yet been defined, so this review is based on the surrounding area and potential stormwater impacts. The project involves Bridge 139 on US Route7, which crosses the Lewis Creek. My evaluation has included the review of existing imagery and mapping (ANR Natural Resource Atlas, VTrans Operational Stormwater Permits) to capture existing stormwater features and existing drainage.

Regulatory Considerations

Once the scope of the project has been determined, an assessment of how much impervious area is involved will determine if an Operational Stormwater permit is required for the project. There do not appear to be any existing stormwater permits in the immediate vicinity of the site area.

Existing Drainage

Based on a review of available mapping and project photos, it appears that there are no drainage structures within the project area. Drainage from the roadway approaches mostly flow overland, while the bridge itself is curbed. The northbound lane of US Route7 north of the bridge appears to have timber curbing that extends a nominal amount, vertically at the shoulder and guardrail. This likely results in some concentration of stormwater flows along the side of the road, however larger storms would likely spill over the small lip of the curb. South of the bridge, there appears to be a recently (re)established drainage ditch leading to a culvert under Lewis Creek Drive.

Design Considerations

Depending on the extent of the project limits and roadway approach work, it may be worthwhile to consider improvements to the drainage from the roadway leading to either side of the bridge. And, to the extent that drainage work is conducted as part of this project, it is encouraged that it be aligned with the VTrans Phosphorus Control Highway Drainage Management Standards, as this may allow future credit toward achieving phosphorus reduction goals required by the Agency's TS4 permit.



Appendix L: Landscape Clearance Resource ID



State of Vermont | Agency of Transportation

Environmental Section 219 North Main Barre, VT 05641

Vtrans.vermont.gov

<u>To:</u> Project File

From: Bonnie Kirn Donahue, VTrans Landscape Architect

Date: January 31, 2024

<u>Project:</u> Ferrisburgh BF 019-4(35) 22B390

<u>Subject</u>: Landscape (LA) Clearance for Resource ID

I have reviewed the proposed area for Ferrisburgh BF 019-4(35) 22B390, and found the following:

SITE DESCRIPTION

The project area is located in a rural stretch of Route 7.

EXISTING CONDITIONS

The following items/conditions were found on site that could influence design decisions:

- 1. Context/setting:
 - a. This project is located in a rural area
- 2. Presence of utilities:
 - a. Desktop review. No utilities were identified.
- 3. Riparian buffer:
 - a. This project includes work within a riparian area and may benefit from a planting plan.
- 4. Trees to protect:
 - a. No trees to protect were identified in the project area.
- 5. Presence of hazard trees
 - a. Desktop review. No hazard trees were identified.
- 6. Special site features:
 - a. No special sites were identified in the project area.
- 7. <u>Plants observed</u>: (this is not a complete list of species on site)
 - a. Desktop review. No species were identified. See natural resources clearance.

- 8. <u>Invasive species observed</u>: (this is not a complete list of species on site)
 - a. Desktop review. No species were identified. See natural resources clearance.
- 9. Accessibility & Active Transportation:
 - a. This project includes bicycle facilities that should be protected.
 - i. Wide shoulders exist on both sides of the road.

RECOMMENDATIONS

- 1. Minimize tree clearing in this area.
- 2. Minimize disturbance in the riparian buffer.
- 3. Develop a riparian planting plan for any disturbed riparian areas on this project.
- 4. Protect, maintain, and improve the accessibility, function, and safety of active transportation infrastructure, such as:
 - a. This project is located in the High Use/Priority category in the VTrans Bicycle Corridor Priority map. Maintain wide shoulders and bicycle infrastructure.
- 5. Develop a plan for managing invasive species in the project area.

NOTES

1. I am available to assist with landscape architectural design, including planting plans, plant lists, hardscape/pedestrian access plans, etc. (bonnie.donahue@vermont.gov).

Appendix M: Utilities Resource ID

Ferrisburgh, BF 019-4(35) 22b390

Existing Utilities within Project Limits Report

US-7 Ferrisburgh BR#139 M.M. 6.200

AERIAL

Comcast
Consolidated Communications
Firstlight Fiber
Green Mountain Power
Waitsfield Champlain Valley Telecom

<u>UNDERGROUND</u>

Consolidated Communications

Ferrisburgh, BF 019-4(35) Pin: 22b390

The aerial utilities in the project area are 230' or more West of the bridge and will not be in conflict. Consolidated has buried Fiber in a 4" PVC conduit which hangs off the West side of the bridge. This will need to be relocated.

By: Jeff Brunet
Date: 9/21/2023

Appendix N: Local Input Questionnaire

Project Summary

This project, BF 019-4(35), focuses on bridge 139 on US Route 7 in Ferrisburgh, Vermont. The bridge is deteriorating and needs either a major maintenance action or replacement. Potential options being considered for this project include targeted repairs, deck replacement, and a new bridge. It is possible that VTrans will recommend a road closure and detour traffic away from the project site for the duration of the work. Efforts will be made to limit the detour to State roads.

Community Considerations

1. Are there regularly scheduled public events in the community that will generate increased traffic (e.g. vehicular, bicycles and/or pedestrians), or may be difficult to stage if the bridge is closed during construction? Examples include annual bike races, festivals, parades, cultural events, weekly farmers market, concerts, etc. that could be impacted? If yes, please provide approximate date, location and event organizers' contact info.

I am unaware of any regularly scheduled events that would impact this bridge beyond normal traffic.

- 2. Is there a "slow season" or period of time from May through October where traffic is less or no events are scheduled?
- U.S. 7 is the major north south route in the western part of the state. There is no slow season.
- 3. Please describe the location of the Town garage, emergency responders (fire, police, ambulance) and emergency response routes that might be affected by the closure of the bridge, one-way traffic, or lane closures and provide contact information (names, address, email addresses, and phone numbers.

Town garage - TH33 off of Little Chicago Rd. Ferrisburgh VFD - 3909 US-7, Ferrisburgh, VT 05456

Police - Ferrisburgh does not have a police department. They would be served by the VSP New Haven barracks or the Vergennes Police Dept. at 8 Main St. in Vergennes

None of these are in close proximity to the project area.

4. Are there businesses (including agricultural operations and industrial parks) or delivery services (fuel or goods) that would be adversely impacted either by a detour or due to work zone proximity?

North of the project there are a number of businesses along Rt. 7 including Vermont Cookie Love, The Village Cafe and Tavern, 9th State Cannabis, some used car dealerships, and some boat sales and service businesses

South of the project area is the Dakin Farms retail store.

5. Are there important public buildings (town hall, community center, senior center, library) or community facilities (recreational fields, town green, etc.) close to the project?

Public buildings are all well south of the project area.

6. What other municipal operations could be adversely affected by a road/bridge closure or detour?

Closure would have significant impacts on traffic flow in the region. Without knowing a proposed detour, it's difficult to consider potential impacts.

7. Are there any town highways that might be adversely impacted by traffic bypassing the construction on other local roads? Please indicate which roads may be affected and their condition (paved/unpaved, narrow, weight-limited bridges, etc), including those that may be or go into other towns.

Traffic would likely follow one of two local routes (both listed north to south starting at intersection w/U.S. 7):

- 1. Stage Rd. (paved), Greenbush Rd. (paved), to U.S. 7 at a dangerous intersection
- 2. Hollow Rd. (paved), Four Winds Rd. (paved), Dakin Rd. (paved), to U.S. 7 Travelers on the second local route might continue south on Shellhouse Mtn. Rd. (gravel south to Fuller Mtn. Rd., then paved) to Middlebrook Rd. (paved), though this would be less direct.
- 8. Is there a local business association, chamber of commerce, regional development corporation, or another downtown group that we should be working with? If known, please provide name, organization, email, and phone number.

none that I can think of

9. Are there any public transit services or stops that use the bridge or transit routes in the vicinity that may be affected if they become the detour route?

The TVT Burlington Link uses this road. Schedule available at the TVT website.

Schools

1. Where are the schools in your community and what are their yearly schedules (example: first week in September to third week in June)?

Ferrisburgh Elementary School - Little Chicago Rd.

Vergennes High School and Middle School - Monkton Rd., Vergennes

Both within Addison Northwest School District. The school year starts the week before Labor Day in August and runs through the second week of June

- 2. Is this project on specific routes that school buses or students use to walk to and from school? Students are not likely to be walking or biking to school along this route. Buses do use the route.
- 3. Are there recreational facilities associated with the schools nearby (other than at the school)? Not that I am aware of

Pedestrians and Bicyclists

1. What is the current level of bicycle and pedestrian use on the bridge?

I anticipate that bicycle and pedestrian use of the bridge is quite low. The routes listed above as local road by-passes offer much more attractive walking and biking opportunities.

2. Are the current lane and shoulder widths adequate for pedestrian and bicycle use?

Yes

3. Does the community feel there is a need for a sidewalk or bike lane on the bridge?

Not that I am aware of

4. Is pedestrian and bicycle traffic heavy enough that it should be accommodated during construction?

No

5. Does the Town have plans to construct either pedestrian or bicycle facilities leading up to the bridge? Please provide any planning documents demonstrating this (scoping study, master plan, corridor study, town or regional plan).

No

6. In the vicinity of the bridge, is there a land use pattern, existing generators of pedestrian and/or bicycle traffic, or zoning that will support development that is likely to lead to significant levels of walking and bicycling?

No

Design Considerations

1. Are there any concerns with the alignment of the existing bridge? For example, if the bridge is located on a curve, has this created any problems that we should be aware of?

No

2. Are there any concerns with the width of the existing bridge?

None

- 3. Are there any special aesthetic considerations we should be aware of?
- 4. Does the location have a history of flooding? If yes, please explain.

Not at the height of the existing bridge

5. Are there any known Hazardous Material Sites near the project site?

No

6. Are there any known historic, archeological and/or other environmental resource issues near the project site?

The bridge crosses Lewis Creek which is a popular fishing destination.

There are RTE element (2-3) occurrences downstream of the bridge and one additional occurrence upstream.

- 7. Are there any utilities (water, sewer, communications, power) attached to the existing bridge? Please provide any available documentation.

 I do not know.
- 8. Are there any existing, pending, or planned municipal utility projects (communications, lighting, drainage, water, wastewater, etc.) near the project that should be considered?

 Not that I am aware of

9. Are there any other issues that are important for us to understand and consider? U.S. 7 is the major north south route in the western part of the state.

Land Use & Zoning

- Please provide a copy of your existing and future land use map or zoning map, if applicable.
 The town plan is available on line.
 Zoning by-laws, including a zoning map, are also available online.
- 2. Are there any existing, pending or planned development proposal that would impact future transportation patterns near the bridge? If so, please explain.

 Not that I am aware of.
- 3. Is there any planned expansion of public transit or intercity transit service in the project area? Please provide the name and contact information for the relevant public transit provider. Not that I am aware of. TVT did recently expand their Link service to add a mid-day run. No further expansion is planned at this time.

Communications

1. Please identify any local communication outlets that are available for us to use in communicating with the local population. Include weekly or daily newspapers, blogs, radio, public access TV, Facebook, Front Page Forum, etc. Also include any unconventional means such as local low-power FM.

The Addison Independent is the local newspaper.

2. Other than people/organizations already referenced in this questionnaire, are there any others who should be kept in the loop as the project moves forward?

Not that I am aware of

Appendix O: Operations Input Questionnaire (blank)

Pending Response from District.

Bridge Scoping Project BF 019-4(35) Operations Input Questionnaire

The Structures Section has begun the scoping process for BF 019-4(35), Ferrisburgh, US Route 7, Bridge 139, over Lewis Creek. This is a rolled beam / concrete deck bridge constructed in 19. The Structure Inspection, Inventory, and Appraisal Sheet (attached) rates the deck as 5 (fair), the superstructure as 6 (satisfactory), and the substructures as 7 (good). We are interested in hearing your thoughts regarding the items listed below. Leave it blank if you don't wish to comment on a particular item.

ite	ms listed below. Leave it blank if you don't wish to comment on a particular item.
1.	What are your thoughts on the general condition of this bridge and the general maintenance effort required to keep it in service?
2.	What are your comments on the current geometry and alignment of the bridge (curve, sag, banking, sight distance)?
3.	Do you feel that the posted speed limit is appropriate?
4.	Is the current bridge and approach roadway width adequate for winter maintenance including snow plowing?
5.	Are the joints salvageable or would you recommend replacement?
6.	Are the railings constantly in need of repair or replacement? What type of railing works best for your district?
7.	Are you aware of any unpermitted driveways within close proximity to the bridge? We frequently encounter driveways that prevent us from meeting railing and safety standards.
8.	Are you aware of abutting property owners that are likely to need special attention during the planning and construction phases? These could be people with disabilities, elderly, or simply

folks who feel they have been unfairly treated in the past.

Bridge Scoping Project BF 019-4(35) Operations Input Questionnaire

9.	Do you find that extra effort is required to keep the slopes and riverbanks around the bridge in a stable condition? Is there frequent flood damage that requires repair?
10.	Does this bridge seem to catch an unusual amount of debris from the waterway?
11.	Are you familiar with traffic volumes in the area of this project?
12.	Do you think a closure with off-site detour and accelerated construction would be appropriate? Do you have any opinion about a possible detour route, assuming that we use State route for State projects and any route for Town projects? Are there locations on a potential detour that are already congested that we should consider avoiding?
13.	Please describe any larger projects that you have completed that may not be reflected on the attached Appraisal sheet, such as deck patches, paving patches, railing replacement with new type, steel coating, etc.
14.	If there is a sidewalk on this bridge, how effective are the Town's efforts to keep it free of snow and ice?
15.	Are there any drainage issues that we should address on this project?
16.	Are you aware of any complaints that the public has about issues that we can address on this project?
17.	Is there anything else we should be aware of?

Appendix P: Crash Data

Ferrisburgh US Route 7 Bridge 139 is located at MM 6.20

Ferrisburgh	US Route 7 Bridge 139 is located a	it MM 6.20											
	Crash Date	City/Town AOT Route	Crash Type Collision Dire	ection	Weather	Report Number Milepoint	Animal	Time of Day	Impairment II	nvolving	Road Characteristics	Road Condition	Surface Condition
4836391	December 19, 2019 at 4:21 PM	Ferrisburgh US-7	Property Damage Only Left Turn and	d Thru, Angle Broadside>v	Clear	19B503588 0.24	None/Othe	r Day	None N	lone	T - Intersection	None	Dry
	October 17, 2019 at 9:06 AM	Ferrisburgh US-7	.,	,		19B502946 0.3°		Day					,
	May 10, 2018 at 2:57 PM	Ferrisburgh US-7	Injury No Turns, The	nru moves only, Broadside ^<	Clear	18B501427 0.63	None/Othe		None F	leavy Truck	Four-way Intersection	None	Dry
												None	Dry
	May 5, 2019 at 2:57 PM	Ferrisburgh US-7	Injury No Turns, The	nru moves only, Broadside ^<	Cloudy		None/Othe		None i	ione	Four-way Intersection	Notic	ыу
	February 5, 2019 at 5:48 PM	Ferrisburgh US-7						Night					
	June 17, 2019 at 4:04 PM	Ferrisburgh US-7		nru moves only, Broadside ^<	Clear		None/Othe				Four-way Intersection	None	Dry
	June 9, 2021 at 10:37 AM	Ferrisburgh US-7	Injury Rear End				None/Othe		None N	lone	Four-way Intersection	None	Other - Explain in Narrative
5923781	June 9, 2021 at 11:19 AM	Ferrisburgh US-7				21B501222 0.64		Day					
5925160	March 15, 2021 at 11:30 AM	Ferrisburgh US-7				21B500477 0.64	1	Day					
5931592	September 24, 2021 at 9:18 PM	Ferrisburgh US-7				21VG01446 0.64	1	Night					
	January 18, 2018 at 4:49 PM	Ferrisburgh US-7	Injury Rear End		Clear	18B500221 0.65	None/Othe		None N	lone	Four-way Intersection	None	Dry
	January 9, 2020 at 6:50 AM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe		None N	lone	Railway grade crossing	None	Dry
	February 10, 2017 at 4:25 PM	Ferrisburgh US-7	Injury Rear End		Clear		None/Othe				T - Intersection		Dry
	May 30, 2018 at 2:15 PM	Ferrisburgh US-7		d Thru. Head On ^v	Clear		L None/Othe			lone	· mersection	None	5.7
			Property Damage Only Left Turn and	u IIIIu, Head OII ··v	Clear				None i	ione		Notic	
	June 28, 2019 at 12:22 AM	Ferrisburgh US-7				19B501646 1.53		Night					
	June 3, 2019 at 7:32 PM	Ferrisburgh US-7				19B501409 1.53		Night					
		Ferrisburgh US-7	Property Damage Only Single Vehicle				None/Othe				T - Intersection	None	Dry
	March 11, 2022 at 3:13 PM	Ferrisburgh US-7	Injury Left Turn and	d Thru, Head On ^v	Clear		None/Othe	r Day	None N	lone	T - Intersection	None	Dry
5929558	November 29, 2021 at 6:30 AM	Ferrisburgh US-7				21B502928 1.53	L	Day					
4099450	June 14, 2019 at 3:17 PM	Ferrisburgh US-7	Injury Rear End		Cloudy	19B501521 1.56	None/Othe	r Day	None N	lone	Four-way Intersection	None	Dry
5925517	May 24, 2021 at 7:50 AM	Ferrisburgh US-7	Property Damage Only			21VG00768 1.6	None/Othe	r Day	None N	lone			
	November 23, 2020 at 3:05 PM	Ferrisburgh US-7	Injury Single Vehicle	le Crash	Cloudy		None/Othe			lone	Not at a Junction	None	Dry
	September 22, 2022 at 9:22 AM	Ferrisburgh US-7	Property Damage Only		- · · · ·		7 None/Othe				Not at a Junction		-
	June 22, 2019 at 9:36 AM	Ferrisburgh US-7	Injury Rear End		Clear		None/Othe				T - Intersection	None	Dry
					Clear						Not at a Junction		
3846015	July 25, 2018 at 6:29 PM	Ferrisburgh US-7	Property Damage Only Rear End				None/Othe						Dry
	November 7, 2019 at 8:40 AM	Ferrisburgh US-7	Property Damage Only Rear End		Cloudy		None/Othe				Not at a Junction		Dry
	April 11, 2018 at 12:50 PM	Ferrisburgh US-7		on Sideswipe	Cloudy		None/Othe				Not at a Junction		Dry
	January 21, 2021 at 12:00 PM	Ferrisburgh US-7	Property Damage Only Rear End		Freezing Precipitation		None/Othe				Driveway	None	Wet
	February 10, 2019 at 1:00 AM	Ferrisburgh US-7	Property Damage Only Head On		Clear	19VG00152 2.48	None/Othe	r Night	Alcohol N	lone	Not at a Junction	None	Dry
	September 3, 2019 at 5:44 PM	Ferrisburgh US-7	Property Damage Only Left Turn and	d Thru, Angle Broadside>v	Clear	19B502462 2.3	7 None/Othe	r Day	Alcohol N		Driveway	None	Dry
	April 22, 2019 at 5:34 PM	Ferrisburgh US-7		-		19B500970 2.82		Day					
	July 2, 2021 at 4:55 PM	Ferrisburgh US-7				21B501491 2.82	,	Day					
	March 7, 2018 at 6:54 PM	Ferrisburgh US-7	Property Damage Only Other - Expla	ain in Narrative	Freezing Precipitation		None/Othe		None N	lone	Not at a Junction	Road Surface Condition(wet, icy, snow, slush, etc)	Snow
			Property Dainage Only Other - Expla	alli ili Nallative	rreezing rrecipitation	208500549 2.84			None i	ione	NOT at a Junction	Road Surface Condition(wet, icy, snow, sidsh, etc)	SHOW
	February 29, 2020 at 2:21 PM	Ferrisburgh US-7						Day					
	February 18, 2017 at 3:10 PM	Ferrisburgh US-7				17B500513 2.87		Day					
	November 11, 2019 at 1:35 AM	Ferrisburgh US-7	Property Damage Only Single Vehicle	le Crash	Freezing Precipitation		None/Othe				Not at a Junction	None	Wet
	September 7, 2018 at 4:38 PM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe	r Day	None N	lone	Four-way Intersection	None	Dry
810881	October 26, 2017 at 6:40 AM	Ferrisburgh US-7	Property Damage Only Rear End		Rain	17B503623 3.09	None/Othe	r Night	None N	lone	Not at a Junction	Road Surface Condition(wet, icy, snow, slush, etc)	Wet
5525891	May 25, 2020 at 6:15 PM	Ferrisburgh US-7				20B501274 3.13	L	Day					
5926286	February 2, 2021 at 4:40 AM	Ferrisburgh US-7				21B500195 3.11	ı	Night					
	January 11, 2022 at 11:29 AM	Ferrisburgh US-7	Injury No Turns, The	nru moves only, Broadside ^<	Clear		None/Othe		None N	lone	Four-way Intersection	None	Dry
	March 10, 2020 at 5:11 PM	Ferrisburgh US-7	injury incrums, in	na mores omy, produside	Cicui	20B500643 3.17		Day	Hone .	ione	roar way intersection	Tronc	5.17
						20B500642 3.17		,					
	March 10, 2020 at 5:01 PM	Ferrisburgh US-7	Property Damage Only Rear End		ci. I			Day	<u>.</u>	lone	Not at a Junction	None	Dry
	June 7, 2018 at 7:40 AM	Ferrisburgh US-7	.,,		Cloudy		None/Othe						
	May 24, 2019 at 3:49 PM	Ferrisburgh US-7	Injury Rear End		Clear		None/Othe				Not at a Junction		Dry
	March 18, 2021 at 2:47 PM	Ferrisburgh US-7	Injury Rear End		Clear		None/Othe				Four-way Intersection		Dry
3840193	March 5, 2019 at 6:28 AM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe		None N	lone	Four-way Intersection	None	Dry
5945690	August 3, 2022 at 5:03 PM	Ferrisburgh US-7	Injury Rear End		Clear	22B5002412 3.272	None/Othe	r Day	None N	lone	Not at a Junction	None	Dry
	August 4, 2018 at 1:50 PM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe		None N	lone	T - Intersection	None	Dry
	May 27, 2022 at 3:26 AM	Ferrisburgh US-7		ion Sideswipe	Clear		None/Othe		None N	lone	Driveway	None	Dry
	September 13, 2022 at 7:49 AM	Ferrisburgh US-7		d Thru, Same Direction Sideswipe/Angle Crash vv	Rain		None/Othe				Not at a Junction	Road Surface Condition(wet, icy, snow, slush, etc)	Wet
	February 24, 2017 at 4:22 PM	Ferrisburgh US-7	rroperty barrage only lest run and	a ma, same birection sideswipe, raigie crasii vi	TAGILI .	17B500582 3.95		Day	Tronc 1	ione	Not at a surretion	noda Sarrace condition(wee, rey, snow, slash, etc)	
	November 23, 2021 at 4:22 PM		Droporty Damago Only Roa- 5-4		Clear		None/Othe		None N	lone	T - Intersection	None	Dry
		Ferrisburgh US-7	Property Damage Only Rear End	Cidentin									,
	June 26, 2020 at 9:44 PM	Ferrisburgh US-7	Injury Opp Direction		Clear		None/Othe			,	Not at a Junction		Dry
	May 25, 2017 at 3:15 AM	Ferrisburgh US-7	Property Damage Only Single Vehicle	le Crash	Clear	17B502122 4.19	None/Othe	r Night			Not at a Junction		Dry
	September 29, 2017 at 3:10 PM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe				Not at a Junction	None	Dry
	March 6, 2019 at 5:28 PM	Ferrisburgh US-7	Property Damage Only Rear End				None/Othe			lone	Not at a Junction	None	Dry
	December 20, 2018 at 6:11 AM	Ferrisburgh US-7	Property Damage Only Rear End		Cloudy		None/Othe		Alcohol N	lone	Not at a Junction	None	Dry
	December 8, 2017 at 4:19 PM	Ferrisburgh US-7		nru moves only, Broadside ^<	Clear		None/Othe				T - Intersection	Unknown	Dry
	January 5, 2018 at 8:04 PM	Ferrisburgh US-7	Property Damage Only Single Vehicle		Clear		None/Othe				Not at a Junction	Road Surface Condition(wet, icv. snow, slush, etc)	Snow
	January 2, 2018 at 1:35 PM	Ferrisburgh US-7	Property Damage Only Single Vehicle		Clear		None/Othe		Alcohol and Drugs N		Not at a Junction	None	Dry
				ic cross	Clear					lone		None	Dry
	July 16, 2022 at 10:30 AM	Ferrisburgh US-7	Property Damage Only Rear End		Cieai		None/Othe		None N	ione	T - Intersection	None	ыу
	December 23, 2020 at 5:51 AM	Ferrisburgh US-7				20B503259 4.54		Night	1				
	May 4, 2021 at 1:10 PM	Ferrisburgh US-7				21B500893 4.55		Day					
	January 2, 2017 at 7:45 PM	Ferrisburgh US-7	Property Damage Only Single Vehicle		Clear		1 Deer	Night			Not at a Junction		Dry
	September 10, 2018 at 6:51 PM	Ferrisburgh US-7	Injury Single Vehicle	le Crash	Rain		7 None/Othe	r Day	None N	lone	Not at a Junction	Road Surface Condition(wet, icy, snow, slush, etc)	Wet
	July 2, 2020 at 2:47 PM	Ferrisburgh US-7				20B501612 5.36		Day					
	August 11, 2021 at 5:50 AM	Ferrisburgh US-7				21B501922 5.38	3	Night					
	February 14, 2017 at 3:39 PM	Ferrisburgh US-7	Injury Rear End		Clear		None/Othe		None N	lone	Other - Explain in Narrative	Unknown	Dry
	December 6, 2017 at 4:25 PM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe				Not at a Junction	None	Dry
	September 27, 2019 at 3:46 PM			d Thru, Angle Broadside>v	Clear		None/Othe				T - Intersection		Dry
		Ferrisburgh US-7	Property Damage Only Left Turn and	u IIIIu, Aligie bioausiue>V	cical			,	ivone P	iorie	i - intersection		Diy
	December 8, 2020 at 7:50 AM	Ferrisburgh US-7				20B503147 5.8		Day	1.				
	January 24, 2022 at 8:55 AM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe				Not at a Junction	Road Surface Condition(wet, icy, snow, slush, etc)	
	May 12, 2017 at 5:27 PM	Ferrisburgh US-7	Property Damage Only Rear End		Clear		None/Othe				Not at a Junction	None	Dry
3857705	March 1, 2019 at 1:48 AM	Ferrisburgh US-7	Property Damage Only Single Vehicle	le Crash	Clear		None/Othe		Alcohol F	leavy Truck	Not at a Junction	None	Dry
3851210	September 14, 2018 at 3:39 PM	Ferrisburgh US-7	Property Damage Only Rear End		Clear	18B502927 5.87	None/Othe	r Day	None N	lone	Not at a Junction	Work zone (construction / maintenance / utility)	Dry
	May 1, 2017 at 5:19 PM	Ferrisburgh US-7		ain in Narrative	Clear		None/Othe			Notorcycle	Not at a Junction	None	Dry
	February 8, 2022 at 4:50 PM	Ferrisburgh US-7	Injury Rear End		Cloudy		None/Othe			lone	Not at a Junction	None	Dry
5924123	October 28, 2021 at 7:00 PM	Ferrisburgh US-7	Property Damage Only Single Vehicle	le Crash	Clear		None/Othe	/		lone	Not at a Junction	None	Dry
	June 28, 2018 at 5:28 PM	Ferrisburgh US-7	Injury Rear End	ic crusii	Rain		None/Othe			lone	T - Intersection	None	Wet
3043389	September 16, 2022 at 10:44 AM	Family Life 7			Naill		None/Othe None/Othe					Hone	**CC
	September 16, 2022 at 10:44 AM	remsburgh US-/	Property Damage Only			22B5002895 6.14	+ None/Othe	Day	None N	lone	Not at a Junction		
5945652													


4347657 September 8, 2019 at 12:45 PM	Ferrisburgh US-7				19B502507	6.19	Day				
5930045 January 16, 2022 at 3:03 AM	Ferrisburgh US-7	Property Damage Only	Single Vehicle Crash	Clear	22B5000112	6.2 None/Other	Night	None Heavy	ruck Not at a Junction	None	Dry
4099489 June 9, 2019 at 8:48 PM	Ferrisburgh US-7	Property Damage Only	Single Vehicle Crash	Clear	19B501470	6.28 None/Other	Night	None None	Not at a Junction	None	Dry
3848852 December 17, 2018 at 6:10 PM	Ferrisburgh US-7	Property Damage Only	Single Vehicle Crash	Clear	18B503886	6.39 None/Other	Night	None None	Not at a Junction	None	Dry
5931923 August 7, 2021 at 2:47 AM	Ferrisburgh US-7				21B501858	6.53	Night				
5927358 February 4, 2021 at 1:22 PM	Ferrisburgh US-7	Injury	Rear End	Clear	21B500219	6.74 None/Other	Day	None None	Not at a Junction	None	Dry
809264 August 19, 2017 at 2:18 PM	Ferrisburgh US-7	Property Damage Only	Other - Explain in Narrative	Cloudy	17B502851	6.76 None/Other	Day	None None	Not at a Junction	None	Dry
803907 April 18, 2017 at 4:32 PM	Ferrisburgh US-7	Property Damage Only	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^	Clear	17B501221	6.81 None/Other	Day	None Heavy	ruck T - Intersection	None	Dry
5922176 January 12, 2021 at 9:31 AM	Ferrisburgh US-7	Injury	Right Turn and Thru, Broadside ^<	Cloudy	21B500072	6.82 None/Other	Day	None Heavy	ruck Not at a Junction	None	Dry
3852442 August 24, 2018 at 4:13 PM	Ferrisburgh US-7	Property Damage Only	Right Turn and Thru, Same Direction Sideswipe/Angle Crash ^^	Clear	18B502684	6.91 None/Other	Day	None None	Not at a Junction	None	Dry
4254391 August 24, 2019 at 4:52 PM	Ferrisburgh US-7				19B502343	6.93	Day				
734452 January 7, 2017 at 2:49 PM	Ferrisburgh US-7	Property Damage Only	No Turns, Thru moves only, Broadside ^<	Cloudy	17B500059	6.94 None/Other	Day	None None	Four-way Intersection	None	Dry
809312 August 5, 2017 at 8:16 PM	Ferrisburgh US-7	Property Damage Only	No Turns, Thru moves only, Broadside ^<	Clear	17B502666	6.94 None/Other	Night	None None	Other - Explain in Nari	ative None	Dry
3844687 August 14, 2018 at 5:40 PM	Ferrisburgh US-7	Property Damage Only			18B502573	6.94 None/Other	Day	None None			
5007572 January 29, 2020 at 2:20 PM	Ferrisburgh US-7	Property Damage Only	No Turns, Thru moves only, Broadside ^<	Clear	20B500286	6.94 None/Other	Day	None None	Four-way Intersection	None	Dry
5919209 November 21, 2020 at 1:55 PM	Ferrisburgh US-7	Injury			20B503013	6.94 None/Other	Day	None None		None	
920690 October 9, 2021 at 3:54 AM	Ferrisburgh US-7	Injury	Single Vehicle Crash	Clear	21B502493	6.94 None/Other	Night	None None	Four-way Intersection	None	Dry
927830 April 15, 2021 at 6:34 PM	Ferrisburgh US-7				21B500730	6.94	Day				
849808 October 26, 2018 at 6:05 PM	Ferrisburgh US-7	Injury	No Turns, Thru moves only, Broadside ^<	Clear	18B503356	6.95 None/Other	Night	None None	Four-way Intersection	None	Dry
8842114 March 16, 2018 at 9:01 AM	Ferrisburgh US-7	Property Damage Only	Left Turn and Thru, Angle Broadside>v	Clear	18B500817	6.98 None/Other	Day	None None	Not at a Junction	None	Dry
422387 September 27, 2019 at 7:44 AM	Ferrisburgh US-7	Property Damage Only	Left Turn and Thru, Angle Broadside>v	Clear	19B502711	6.98 None/Other	Day	None None	T - Intersection	None	Dry
921584 January 17, 2022 at 5:48 AM	Ferrisburgh US-7	Property Damage Only	Head On	Freezing Precipitation	22B5000118	6.98 None/Other	Night	None None	Not at a Junction	Road Surface Condition(wet, icy, snow, slush, etc)	Snow
930604 March 6, 2022 at 3:10 PM	Ferrisburgh US-7	Injury	Rear End	Clear	22B5000610	6.98 None/Other	Day	None None	Not at a Junction	None	Dry
3847035 June 25, 2018 at 11:07 AM	Ferrisburgh US-7	Injury	No Turns, Thru moves only, Broadside ^<	Clear	18B501938	6.99 None/Other	Day	None None	Four-way Intersection	None	Dry
3843736 June 29, 2018 at 4:12 PM	Ferrisburgh US-7	Property Damage Only	Rear End	Clear	18B501992	7.13 None/Other	Day	None None	Not at a Junction	None	Dry
5927795 December 9, 2020 at 4:16 PM	Ferrisburgh US-7				20B503165	7.27	Day				
5928046 October 12, 2020 at 9:56 AM	Ferrisburgh US-7	1			20B502659	7.28	Day				
4254398 August 19, 2019 at 3:56 PM	Ferrisburgh US-7	1			19B502270	999.99	Day				
4386239 September 18, 2019 at 4:11 PM	Ferrisburgh US ROUTE 7	/ Injury	No Turns, Thru moves only, Broadside ^<	Clear	19B502622	None/Other	Day	None None	T - Intersection	None	Dry
934567 February 4, 2022 at 1:39 AM	Ferrisburgh US ROUTE 7	,			22B5000309		Night		*	•	

Appendix Q: Detour Maps



Ferrisburgh BF 019-4(35) Regional Detour Distance

Detour Distance = 35.6 miles, Travel Time = 49 min



Map data ©2024 Google 2 mi **L**


Main St New Haven, VT 05472

↑	1.	Head east on VT-17 E	
↑	2.	Continue onto Rte 116 N	8.7 mi
\rightarrow	3.	Turn right onto VT-2A N	16.6 mi
*	4.	Turn left to merge onto I-89 N toward Burling	5.0 mi ston
r	5.	Take exit 13 for I-189 toward US-7/Shelburne/Burlington	- 3.5 mi
↑	6.	Continue onto I-189 W/Interstate 189 W	0.2 mi
\leftarrow	7.	Use any lane to turn left onto Shelburne St	- 1.4 mi
			- 0.1 mi

South End Burlington, VT

Google Maps Ferrisburgh BF 019-4(35) Regional Detour Through Distance

Through Distance = 24.6 miles, Travel Time = 35 min



Map data ©2023 Google 2 mi **L**

Main St New Haven, VT 05472

1. Head northwest on US-7 N


1 Pass by Buffalo Wild Wings (on the left in 24.6 mi)

24.6 mi

South End Burlington, VT 05401

Google Maps Ferrisburgh BF 019-4(35) Western Local Bypass Detour Distance = 2.7 miles, Travel Time = 6 min

Travel Time = 6 min




Map data ©2023 1000 ft **∟**

8 Dakin Rd Ferrisburgh, VT 05456

↑	1.	Head north on US-7 N toward Dakin Rd	
←	2.	Turn left onto Quaker St	423 ft
\rightarrow	3.	Turn right onto Greenbush Rd	1.0 mi
\rightarrow	4.	Turn right onto Stage Rd	0.5 mi
←		Turn left onto US-7 N Destination will be on the left	—— 1.0 mi
			20 ft

6973 US-7 North Ferrisburgh, VT 05473

Google Maps Ferrisburgh BF 019-4(35) Eastern Local Bypass Detour Distance = 2.9 miles, Travel Time = 5 min



Map data ©2023 1000 ft **∟**

8 Dakin Rd Ferrisburgh, VT 05456


↑	1.	Head east on Dakin Rd	
\leftarrow	2.	Turn left onto Four Winds Rd	0.8 mi
\leftarrow	3.	Turn left onto Old Hollow Rd	1.2 mi
ightharpoonup		Turn right onto US-7 N Destination will be on the left	- 0.8 mi
			20 ft

6973 US-7 North Ferrisburgh, VT 05473



Ferrisburgh BF 019-4(35) Local Bypass Through Distance

Through Distance = 1.3 miles, Travel Time = 2 min



Map data ©2023 1000 ft _____

8 Dakin Rd Ferrisburgh, VT 05456

1


1. Head north on US-7 N toward Dakin Rd


1 Destination will be on the left

1.3 mi


6973 US-7 North Ferrisburgh, VT 05473

Appendix R: Plans





EXISTING US ROUTE 7 TYPICAL SECTION SCALE % " = 1'-0"



EXISTING BRIDGE TYPICAL SECTION SCALE 3/8" = 1'-0"

MATERIAL TOLERANG	CES
(IF USED ON PROJECT)	
SURFACE	
- PAVEMENT (TOTAL THICKNESS)	+/- 1/4"
- AGGREGATE SURFACE COURSE	+/- 1/2"
SUBBASE	+/- "
SAND BORROW	+/- "


PROJECT NAME:	FERRISBURGH		
PROJECT NUMBER:	BF 019-4(35)		
FILE NAME: 22j390\ PROJECT LEADER: L	s22j390typical.dgn .J.STONE	PLOT DATE: DRAWN BY:	

CHECKED BY: -----

SHEET 2 OF 14

DESIGNED BY: -----

EXISTING TYPICAL SECTIONS



PROJECT LEADER: L.J.STONE

US ROUTE 7 PROFILE SHEET

DESIGNED BY: -----


GRADES SHOWN TO THE NEAREST

HUNDREDTH ARE FINISH GRADE ALONG &

DRAWN BY: D.D.BEARD

SHEET 3 OF 14

CHECKED BY: -----



CHANNEL PROFILE

SCALE: HORIZONTAL I"=20'-0"


VERTICAL I"=10'-0"

NOTE:
GRADES SHOWN TO THE NEAREST
TENTH ARE EXISTING GROUND ALONG &
GRADES SHOWN TO THE NEAREST
HUNDREDTH ARE FINISH GRADE ALONG &


PROJECT NAME: FERRISBURGH PROJECT NUMBER: BF 019-4(35)

FILE NAME: s22b390profile.dgn
PROJECT LEADER: L.J.STONE
DESIGNED BY: ----CHANNEL PROFILE SHEET

PLOT DATE: II-APR-2024
DRAWN BY: D.D.BEARD
CHECKED BY: ----SHEET 4 OF 14



EXISTING US ROUTE 7 TYPICAL SECTION SCALE % " = 1'-0"




REHABILITATION BRIDGE TYPICAL SECTION SCALE 3/8" = 1'-0"


MATERIAL TOLERANG	CES
(IF USED ON PROJECT)	_
SURFACE	
- PAVEMENT (TOTAL THICKNESS)	+/- 1/4"
- AGGREGATE SURFACE COURSE	+/- 1/2"
SUBBASE	+/- "
SAND BORROW	+/- "

PROJECT NAME:	FERRISBURGH
PROJECT NUMBER:	BF 019-4(35)

FILE NAME: 22j390\s22j390typical.dgn				
PROJECT LEADER: L.J.STONE				
DESIGNED BY:				
REHABILITATION TYPICAL SECTIONS				


PLOT DATE: II-APR-2024
DRAWN BY: D.D.BEARD
CHECKED BY: ----SHEET 5 OF I4





EXISTING US ROUTE 7 TYPICAL SECTION SCALE $\frac{3}{8}$ " = 1'-0"

SCALE 3/8" = 1'-0"



PROJECT NUMBER: BF 019-4(35)

FILE NAME: 22j390\s22j390typical.dgn

DECK REPLACEMENT TYPICAL SECTIONS


PROJECT LEADER: L.J.STONE


DESIGNED BY: -----

PLOT DATE: II-APR-2024


DRAWN BY: D.D.BEARD

CHECKED BY: -----SHEET 7 OF 14





EXISTING US ROUTE 7 TYPICAL SECTION SCALE % " = 1'-0"



SUPERSTRUCTURE REPLACEMENT TYPICAL SECTION SCALE 3/8" = 1'-0"

SURFACE	
- PAVEMENT (TOTAL THICKNESS)	+/- 1/
- AGGREGATE SURFACE COURSE	+/- 1/2
SUBBASE	+/- "
SAND BORROW	+/- "

PROJECT NAME: FERRISBURGH	
PROJECT NUMBER: BF 019-4(35)	
FILE NAME: 22j390\s22j390typical.dgn PROJECT LEADER: L.J.STONE	PLOT DATE: II-APR-2024 DRAWN BY: D.D.BEARD
DESIGNED BY:	CHECKED BY:
SUPER REPLACEMENT TYPICAL SECTIONS	SHEET 9 OF 14

MATERIAL TOLERANCES

