



**2022 School Facilities Inventory Report** 


ADDISON CENTRAL SD | MIDDLEBURY UNION HIGH SCHOOL | 73 CHARLES Facility Name:

AVENUE, MIDDLEBURY 5753 - High (9 thru 12) - Main Building

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$11,988,339






Value of Assets/GSF \$79.92



Site Plan - Google Earth





Location Plan - Google Maps

### FCI = 72.6%100.0% 90.0% 80.0% 70.0% 60.0% 50.0% 40.0% 30.0% 20.0% 10.0% 0.0% FCI Distribution

Facility Condition Index (FCI) Compared to Portfolio

(See Last Page for Explanation of Terms)

Page 1 of 5 v2022-03-29



## AGENCY OF EDUCATION



### **2022 School Facilities Inventory Report**

Facility Name: ADDISON CENTRAL SD | MIDDLEBURY UNION HIGH SCHOOL | 73 CHARLES

AVENUE, MIDDLEBURY 5753 - High (9 thru 12) - Main Building

**Respondent Information** 

Date/Time Completed 2021-12-16 - 2:11 PM

Respondent Name Bruce MacIntire

Respondent Title Director of Facilities

Respondent Email bmacintire@acsdvt.org

Respondent Phone Number (802) 382-1198

**Facility Information** 

School Type High (9 thru 12)

**Building Identification Main Building** 

Stories

Building Area 150000 (Gross Square Footage - GSF)

Year Constructed 1956 Year of Last Major Renovation 1997

FCI (Depleted Value) 72.2%

**Environmental & Safety Issues** 

Hazardous Materials Yes

Hazardous (HZD) Materials include Asbestos containing materials (ACM)

HZD Issues are Major

HZD Issues include ACM tile and mastic exist in 40% of the building

Indoor Air Quality (IAQ) Issues Yes

IAQ Issues include Insufficient Air Change Ratio

IAQ Issues are Major

IAQ Issues include Old air handling equipment does not provide adequate air exchange for 50% of the building

Fire or Life/Safety (FL/S) Issues No

FL/S Issues are

Other Risk Factors Yes

Other Risk Factors include Dangerous Traffic Patterns, Ice and payment

Other Risk Factors are Falling Ice from roofs, poor condition of paved surfaces are hazardous.

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

**Utilities - Adequacy** 

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Adequate

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

**Electrical Capacity Adequate** 

v2022-03-29 Page 2 of 5



# AGENCY OF EDUCATION



# **2022 School Facilities Inventory Report**

Installed in -

Facility Name:	ADDISON CENTRA	AL SD	MIDD	LEBURY UN	ION H	IIGH	SCHOOL	.   73 C	HA	RLES	
	AVENUE, MIDDLE		•					•			
Building Envelope - Roof	,			<u> </u>	<u>,                                    </u>			<u> </u>			
Roof 1 is	Metal										
Covers	90%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	1987	40	5	\$13.00 /	SF	for	33,750	SF	=	\$438,750	
Roof 2 is	Single-Ply EPDM/TPO/PV	/C Memb	orane			•	•				
Covers	9%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	2007	20	5	\$11.00 /	SF	for	3,375	SF	=	\$37,125	
Roof 3 is	Skylight										
Covers	1%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	1985	30	-7	\$50.00 /	SF	for	375	SF	=	\$18,750	Ŵ
Roof 4 is	-										
Covers	0%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Building Envelope - Windows						·					
Primary Window System											
% of Windows That are this Type		EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in		30	17	\$60.00 /	SF	for	18,000	SF	=	\$1,080,000	
Secondary Window System											
% of Windows That are this Type		EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	1994	30	2	\$70.00 /	SF	for	18,000	SF	=	\$1,260,000	
Services - Elevators											
Primary Conveyance/Elevators								1			
Quantity of Stops		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	15	\$25,000.00 /	STOP	for	4	STOP	=	\$100,000	
Secondary Conveyance/Elevators		5111	CPIII	Cook	/ 11-26		0	11-26-		Takal Malasa	
Quantity of Stops		EUL	C-RUL	Cost ,	/ Unit		Quantity	Units		Total Value	
Installed in	-		N/A	- /		for		) -	=	\$0	
Services - Plumbing	Cumply & Conitony Modi	um Done	itu (Inglud	oc Fixturos)							
Primary Plumbing System Area of building served			C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in		EUL 40	-26	\$15.00 /		for	150,000		=	\$2,250,000	۸
Secondary Plumbing System		40	-20	\$15.00 /	GSF	101	150,000	GSF	<u> -  </u>	\$2,250,000	<u> </u>
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		LOL	N/A	- /		for	Quantity	Offics	=	\$0	
Services - Cooling - Central System	-	_	IV/ A	- /		101	_		-	<del>3</del> 0	
Primary Central Cooling System	None										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A	- /	_	for	_	-	=	\$0	
Secondary Plumbing System		1	1.471			1.0.				Ÿ	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A	- /		for	-	-	=	\$0	
Services - Heating - Central System			14/14			1.0.				<del>, , , , , , , , , , , , , , , , , , , </del>	
Primary Heating System	Boiler(s)/System - Gas										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	5	\$62.00 /		for	4,286		=	\$265,714	
Secondary Heating System				, = == /			,			/	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in			NI/A	,		for				ĊO	

v2022-03-29 Page 3 of 5



# AGENCY OF EDUCATION



**2022 School Facilities Inventory Report** ADDISON CENTRAL SD | MIDDLEBURY UNION HIGH SCHOOL | 73 CHARLES Facility Name: AVENUE, MIDDLEBURY 5753 - High (9 thru 12) - Main Building **Services - HVAC Distribution** Primary HVAC Distribution System HVAC System, Hydronic Piping, 2-Pipe Area of building served 100% C-RUL Quantity Units Installed in 1997 \$5.00 / SF for 150,000 SF \$750,000 Secondary HVAC Distribution System Area of building served 0% C-RUL Cost / Unit Quantity Units Total Value Installed in for Services - Package Systems Primary HVAC Package Unit & Splits Split System, Ductless, Multi Zone Area of building served 15% Installed in 1997 15 -10 \$6,000.00 / TON for TON \$540,000 Secondary HVAC Package Unit & Splits Split System, Ductless, Multi Zone Area of building served 5% C-RUL Total Value Cost / Quantity Installed in 2020 \$6,000.00 / TON for 30 TON \$180,000 **Services - Fire Suppression** Primary Fire Suppression System Sprinkler System, Medium Density/Complexity Area of building served 100% C-RUL Cost / Unit Quantity Units **Total Value** Installed in 1997 \$5.00 / GSF 150,000 GSF \$750,000 for Secondary Fire Suppression System Kitchen Hood or Computer Center Suppression System Area of building served 1 EA C-RUL Cost / Unit Quantity Units Total Value Installed in 1997 \$10,000.00 / EA \$10,000 **Services - Fire Alarm System** Primary Fire Suppression System Modern Addressable Fire Alarm System Area of building served 100% C-RUL Cost / Unit Quantity Units Total Value Installed in 2016 \$3.00 / SF 150.000 SF \$450.000 for Secondary Fire Suppression System Area of building served 0% C-RUL Cost / Unit Quantity Units Total Value Installed in -**Services - Security Systems** Primary Security & Low Volt System Security & Low Voltage Systems - Average Area of building served 5% Cost / Unit Quantity Units Installed in 1997 \$4.00 / GSF 7,500 GSF \$30,000 Secondary Security & Low Volt System C-RUL Area of building served 0% Installed in Services - Electrical Distribution/Infrastructure Electrical Distribution/Infrastructure Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density Area of building served 100% Installed in 1997 \$22.00 / GSF 150,000 GSF \$3,300,000 Services - Solar Power (PV) Solar (Electric Generation) Provided None Owned/Maintained by School -Value of Solar PV Panels: C-RUL Quantity Units Quantity of Panels 0 Cost / Unit Installed in -**Ancillary Structures** Ancillary Structures Relocatable Building - Classroom/Office - Basic/Portable Total SF of Ancillary Structures 4800 C-RUL Cost / Unit Quantity Units 4,800 SF Installed in 2013 \$110.00 / SF Secondary Ancillary Structures C-RUL Total SF of Secondary Ancillary Structures 0 Cost / Unit Quantity Units

**Additional Comments** 

Installed in

v2022-03-29 Page 4 of 5

for





### **2022 School Facilities Inventory Report**

Facility Name: ADDISON CENTRAL SD | MIDDLEBURY UNION HIGH SCHOOL | 73 CHARLES

AVENUE, MIDDLEBURY 5753 - High (9 thru 12) - Main Building

# **Explanation of Terms**

Explanation of Terms								
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.							
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.							
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.							
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.							
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.							
Calculated Remaining Useful Life( C-RUL)	The current number of remaining years a system may be expected to perform in designed service.							
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.							
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.							
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in th total system cost.							
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.							
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).							
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.							

v2022-03-29 Page 5 of 5