

### 2022 School Facilities Inventory Report

Facility Name: **BENNINGTON RUTLAND SU | SUNDERLAND ELEM SCHOOL | 98 BEAR RIDGE RD, SUNDERLAND 5250 - Combination - Main Building**


March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) **\$605,514**



GPS: 43.08473429755146, -73.12775298864437

#### Relative Asset Values




Value of Assets/GSF **\$75.69**





Site Plan - Google Earth

#### Projected Capital Planning Cash Flow



#### Facility Condition Index (FCI) Compared to Portfolio



Location Plan - Google Maps

(See Last Page for Explanation of Terms)

### 2022 School Facilities Inventory Report

Facility Name: **BENNINGTON RUTLAND SU | SUNDERLAND ELEM SCHOOL | 98 BEAR RIDGE RD, SUNDERLAND 5250 - Combination - Main Building**

#### Respondent Information

Date/Time Completed **2022-01-04 - 12:29 PM**  
 Respondent Name **Greg Harrington**  
 Respondent Title **Director of Operations**  
 Respondent Email **gharrington@brsu.org**  
 Respondent Phone Number **(802) 362-2452**

#### Facility Information

School Type **Combination**  
 Building Identification **Main Building**  
 Stories **1**  
 Building Area **8000 (Gross Square Footage - GSF)**  
 Year Constructed **1969**  
 Year of Last Major Renovation **N/A**  
 FCI (Depleted Value) **74.9%**

#### Environmental & Safety Issues

Hazardous Materials **Yes** ⚠  
 Hazardous (HZD) Materials include **Asbestos containing materials (ACM)**  
 HZD Issues are **Minor**  
 HZD Issues include **Asbestos tiles in custodial office and storage room.**

Indoor Air Quality (IAQ) Issues **No**  
 IAQ Issues include -  
 IAQ Issues are -  
 IAQ Issues include -

Fire or Life/Safety (FL/S) Issues **No**  
 FL/S Issues are -

Other Risk Factors **No**  
 Other Risk Factors include -  
 Other Risk Factors are -

#### Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues **No**  
 ADA Issues are **N/A**  
 ADA Issues include **N/A**

#### Utilities - Adequacy

IT / Internet Service **Adequate**  
 Building Wi-Fi Coverage **Adequate**  
 Cellular Reception **Adequate**  
 Water Service Pressure **Adequate**  
 Natural Gas/Propane Pressure **N/A**  
 Electrical Capacity **Adequate**

### 2022 School Facilities Inventory Report

Facility Name: **BENNINGTON RUTLAND SU | SUNDERLAND ELEM SCHOOL | 98 BEAR RIDGE RD, SUNDERLAND 5250 - Combination - Main Building**

#### Building Envelope - Roof

Roof 1 is <b>Single-Ply EPDM/TPO/PVC Membrane</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>100%</b>	20	5	\$11.00 / SF	8,000	SF	\$88,000
Installed in <b>2007</b>						
Roof 2 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						
Roof 3 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						
Roof 4 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Building Envelope - Windows

Primary Window System <b>Window, Wood-Frame</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type <b>80%</b>	30	16	\$70.00 / SF	1,536	SF	\$107,520
Installed in <b>2008</b>						
Secondary Window System <b>Window, Wood-Frame</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type <b>20%</b>	30	-23	\$70.00 / SF	384	SF	\$26,880
Installed in <b>1969</b>						

#### Services - Elevators

Primary Conveyance/Elevators <b>None</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops <b>0</b>	-	N/A	- / -	0	-	\$0
Installed in -						
Secondary Conveyance/Elevators -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops <b>0</b>	-	N/A	- / -	0	-	\$0
Installed in -						

#### Services - Plumbing

Primary Plumbing System <b>Supply &amp; Sanitary, Low Density (Includes Fixtures)</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>100%</b>	40	-13	\$7.00 / GSF	8,000	GSF	\$56,000
Installed in <b>1969</b>						
Secondary Plumbing System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Cooling - Central System

Primary Central Cooling System <b>None</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						
Secondary Plumbing System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Heating - Central System

Primary Heating System <b>Boiler(s)/System - Fuel Oil</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>100%</b>	30	15	\$60.00 / MBH	229	MBH	\$13,714
Installed in <b>2007</b>						
Secondary Heating System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

### 2022 School Facilities Inventory Report

Facility Name: **BENNINGTON RUTLAND SU | SUNDERLAND ELEM SCHOOL | 98 BEAR RIDGE RD, SUNDERLAND 5250 - Combination - Main Building**

#### Services - HVAC Distribution

Primary HVAC Distribution System **Piped System to Unit Ventilators/Fan Coils, 2-Pipe System**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
80%	30	15	\$10.00 / GSF	6,400	GSF	\$64,000

Installed in 2007

Secondary HVAC Distribution System **HVAC System, Hydronic Piping, 2-Pipe**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
20%	40	-13	\$5.00 / SF	1,600	SF	\$8,000

Installed in 1969

#### Services - Package Systems

Primary HVAC Package Unit & Splits **None**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0

Installed in -

Secondary HVAC Package Unit & Splits -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0

Installed in -

#### Services - Fire Suppression

Primary Fire Suppression System **Sprinkler System, Medium Density/Complexity**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
5%	40	-13	\$5.00 / GSF	400	GSF	\$2,000

Installed in 1969

Secondary Fire Suppression System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0

Installed in -

#### Services - Fire Alarm System

Primary Fire Suppression System **Modern Addressable Fire Alarm System**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
100%	20	7	\$3.00 / SF	8,000	SF	\$24,000

Installed in 2009

Secondary Fire Suppression System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0

Installed in -

#### Services - Security Systems

Primary Security & Low Volt System **Security & Low Voltage Systems - Average**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
20%	15	8	\$4.00 / GSF	1,600	GSF	\$6,400

Installed in 2015

Secondary Security & Low Volt System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0

Installed in -

#### Services - Electrical Distribution/Infrastructure

Electrical Distribution/Infrastructure **Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
100%	40	-13	\$22.00 / GSF	8,000	GSF	\$176,000

Installed in 1969

#### Services - Solar Power (PV)

Solar (Electric Generation) Provided **None**

Owned/Maintained by School -

Quantity of Panels 0

Installed in -

Value of Solar PV Panels: -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

#### Ancillary Structures

Ancillary Structures **Relocatable Building - Classroom/Office - Basic/Portable**

Total SF of Ancillary Structures	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
300	15	10	\$110.00 / SF	300	SF	\$33,000

Installed in 2017

Secondary Ancillary Structures -

Total SF of Secondary Ancillary Structures	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0	-	N/A	- / -	-	-	\$0

Installed in -

#### Additional Comments

**2022 School Facilities Inventory Report**

Facility Name: **BENNINGTON RUTLAND SU | SUNDERLAND ELEM SCHOOL | 98 BEAR RIDGE RD, SUNDERLAND 5250 - Combination - Main Building**

## Explanation of Terms

<b>Projected Capital Planning Cash Flow</b>	The estimated replacement costs of systems as they expire annually.
<b>Facility Condition Index (FCI)</b>	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
<b>Total Value of Assets</b>	The total estimated replacement cost of all the assets listed in the form.
<b>Value of Assets per GSF</b>	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
<b>Facility Condition Index (FCI) Compared to Portfolio</b>	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
<b>Calculated Remaining Useful Life( C-RUL)</b>	The current number of remaining years a system may be expected to perform in designed service.
<b>Expected Useful Life (EUL)</b>	The total number of years a system can be expected to perform in designed service when new.
<b>Gross Square Footage (GSF)</b>	The total square footage contained within the building for all floors/levels.
<b>Cost per Unit</b>	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
<b>Quantity</b>	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
<b>Units</b>	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
<b>Ancillary Structures</b>	Buildings on site that are typically known as portables, relocatables or temporary buildings.