

### AGENCY OF EDUCATION

#### **2022 School Facilities Inventory Report**



Facility Name: ESSEX NORTH SU | CANAAN SCHOOLS | 99 SCHOOL STREET, CANAAN 5903 -

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$1,792,194



GPS: 44.99553669894481, -71.53751401463879




Site Plan - Google Earth




Location Plan - Google Maps

Relative Asset Values



Value of Assets/GSF \$68.51

#### Projected Capital Planning Cash Flow



#### Facility Condition Index (FCI) Compared to Portfolio FCI = 86.5%100.0% 90.0% 80.0% **Depleted Value** 70.0% 60.0% 50.0% 40.0% 30.0% Ū 20.0% 10.0% 0.0% FCI Distribution

(See Last Page for Explanation of Terms)

Combination - Secondary Building







#### 2022 School Facilities Inventory Report

Facility Name:	ESSEX NORTH SU   CANAAN SCHOOLS   99 SCHOOL STREET, CANAAN 5903 -			
	Combination - Secondary Building			
Respondent Information				
Date/Time Completed	2021-12-08 - 9:51 AM			
Respondent Name	Scott Conroy			
Respondent Title	Director of Facilities and Maintenance			
Respondent Email	sconroy@canaanschools.org			
Respondent Phone Number	(802) 266-8910 x2006			
acility Information				
School Type	Combination			
Building Identification	Secondary Building			
Stories	1			
Building Area	26158 (Gross Square Footage - GSF)			
Year Constructed	1946			
Year of Last Major Renovation	1977			
FCI (Depleted Value)	86.5%			
nvironmental & Safety Issues				
Hazardous Materials	Yes	<u>/</u>		
Hazardous (HZD) Materials include	Asbestos containing materials (ACM)			
HZD Issues are	Major			
HZD Issues include	One small piece of asbestos in gym side room, asbestos in boiler room crawl space and are all labeled and warnings about asbestos			
Indoor Air Quality (IAQ) Issues	Yes	<u>/</u>		
IAQ Issues include	Have installed new air system in 2021			
IAQ Issues are	Minor			
IAQ Issues include	new air system			
Fire or Life/Safety (FL/S) Issues	Yes	<u>/</u> !		
FL/S Issues are	Dated fire alarm system (non addressable), no sprinkler system			
Other Risk Factors	Yes			
Other Risk Factors include	Snow and drainage of roofs where entering buildings			
	Area between the high school and elementary has steps outside and snow and ice become issues while going from			
Other Risk Factors are	building to building. Blocked off for car traffic but students and teachers need to go outside to enter either			
landicap Accessibility (ADA) Issues	building.	_		
Handicap Accessibility (ADA) Issues	Vec	^		
ADA Issues are		<u>Z:</u>		
	e Major Area between two buildings High school and Elementary school has steps, no ramps for access. Also Gym entrance			
ADA Issues include	is not wheelchair accessible.			
Itilities - Adequacy				
IT / Internet Service				
Building Wi-Fi Coverage	Marginal	Z		
Cellular Reception	Marginal	Z		
Water Service Pressure	Adequate			
Natural Gas/Propane Pressure	Adequate			
Electrical Capacity	Marginal	1		





# AGENCY OF EDUCATION

#### 2022 School Facilities Inventory Report

Facility Name: ESSEX NORTH SU | CANAAN SCHOOLS | 99 SCHOOL STREET, CANAAN 5903 -Combination - Secondary Building

	Combination - Sec	Lonua	ry build	ling							
Building Envelope - Roof											
Roof 1 is	Built-Up Roof or Modified	d Bitume	en								
Covers 2	25%	EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in 1	1946	25	-51	\$14.00 /	SF	for	6,540	SF	=	\$91,553	$\wedge$
Roof 2 is	Metal								1		
Covers	25%	EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in	1999	40	17	\$13.00 /	SF	for	6,540	SF	=	\$85,014	
Roof 3 is	Metal										
Covers 2	25%	EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in a	1999	40	17	\$13.00 /	SF	for	6,540	SF	=	\$85,014	
Roof 4 is	Metal								1 1		
Covers		EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in	1999	40	17	\$13.00 /	SF	for	6,540	SF	=	\$85,014	
Building Envelope - Windows			ļ		-	+		-		1 7 -	
Primary Window System	Window, Metal-Frame										
% of Windows That are this Type		EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in	1946	30	-46	\$60.00 /	SF	for	3,767	SF	=	\$226,005	$\wedge$
Secondary Window System	Window, Metal-Frame								1 1		
% of Windows That are this Type 4		EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in 1	1977	30	-15	\$60.00 /	SF	for	2,511	SF	=	\$150,670	$\wedge$
Services - Elevators				,,		1	-/			+,	<u> </u>
Primary Conveyance/Elevators	None										
Quantity of Stops		EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in	1946	-	N/A	- /	-	for	0	-	=	\$0	
Secondary Conveyance/Elevators	Wheelchair Lift								1 1		
Quantity of Stops		EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in 2	2014	25	17	\$17,000.00 /	EA	for	1	EA	=	\$17,000	
Services - Plumbing									<u> </u>		
Primary Plumbing System	Supply & Sanitary, Low D	ensity (I	ncludes Fi	xtures)							
Area of building served	100%	EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in a	1946	40	-36	\$7.00 /	GSF	for	26,158	GSF	=	\$183,106	$\wedge$
Secondary Plumbing System -	-					-					
Area of building served	0%	EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Services - Cooling - Central System			,			1.				1.1	
Primary Central Cooling System	None										
Area of building served (		EUL	C-RUL	Cost /	′Unit		Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Secondary Plumbing System	-								1 1		
Area of building served (		EUL	C-RUL	Cost /	′Unit		Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Services - Heating - Central System				/		1 **				ŢŬ	
Primary Heating System	Boiler(s)/System - Fuel Oi	1									
Area of building served		EUL	C-RUL	Cost /	′Unit		Quantity	Units		Total Value	
Installed in 2		30	20	\$60.00 /		for		MBH	=	\$22,421	
Secondary Heating System				ç00.00 j			574			<i>Y22,121</i>	
Area of building served		EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in 2		30	20	\$60.00 /		for		MBH	=	\$22,421	
	2012	50	20	Ş00.00 /	IVIDII	101	574		1-	γ <i>∠</i> ∠,4∠1	





## AGENCY OF EDUCATION

#### 2022 School Facilities Inventory Report

		•								
Facility Name:	<b>ESSEX NORTH SU</b>		IAAN S	CHOOLS   99 S	CHOOL	STREET,	, CANA	AN	5903 -	
	<b>Combination - Se</b>	conda	rv Buil	ding						
ervices - HVAC Distribution			,	8						
Primary HVAC Distribution System	Piped System to Unit Ve	ntilators,	Fan Coils	, 2-Pipe System						
Area of building served		EUL	C-RUL		nit	Quantity	Units		Total Value	
Installed in	1977	30	-15	\$10.00 / G	SF for	5,232	GSF	=	\$52,316	Â
Secondary HVAC Distribution System	Piped System to Unit Ve	ntilators,	Fan Coils	, 2-Pipe System						
Area of building served		EUL	C-RUL		nit	Quantity	Units		Total Value	
Installed in	1977	30	-15	\$10.00 / G	SF for	5,232	GSF	=	\$52,316	$\wedge$
ervices - Package Systems										
Primary HVAC Package Unit & Splits	None									
Area of building served	0%	EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	
Secondary HVAC Package Unit & Splits	-									-4
Area of building served	0%	EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	1946	-	N/A	- / -	for	-	-	=	\$0	
ervices - Fire Suppression										
Primary Fire Suppression System	None									
Area of building served	0%	EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	
Secondary Fire Suppression System	-									_
Area of building served	0%	EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	1
Installed in		-	N/A	- / -	for	-	-	=	\$0	
ervices - Fire Alarm System		1		· · · ·						1
Primary Fire Suppression System	Older type Zoned Systen	n								
Area of building served		EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	2019	20	17	\$1.50 / G	SF for	26,158	GSF	=	\$39,237	
Secondary Fire Suppression System	-	.1		<u> </u>						1
Area of building served		EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	
ervices - Security Systems										1
Primary Security & Low Volt System	Security & Low Voltage S	Systems -	Average							
Area of building served	50%	EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	2012	15	5	\$4.00 / G	SF for	13,079	GSF	=	\$52,316	
Secondary Security & Low Volt System	Security & Low Voltage S	Systems -	Average	•						-
Area of building served	50%	EUL	C-RUL	Cost / U	nit	Quantity	Units		Total Value	
Installed in	2019	15	12	\$4.00 / G	SF for	13,079	GSF	=	\$52,316	
ervices - Electrical Distribution/Infrastructure										
Electrical Distribution/Infrastructure		w/Sub Pa	anels and	Generator/UPS - Me	dium Dens					-
Area of building served		EUL	C-RUL	Cost / U		Quantity			Total Value	
Installed in	1977	40	-5	\$22.00 / G	SF for	26,158	GSF	=	\$575,476	<u>\</u>
ervices - Solar Power (PV)										
Solar (Electric Generation) Provided										
Owned/Maintained by School				Value of Solar PV Pa						
Quantity of Panels		EUL	C-RUL	Cost / U		Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	
ncillary Structures										
Ancillary Structures								1		
Total SF of Ancillary Structures		EUL	C-RUL	Cost / U		Quantity			Total Value	
Installed in		-	N/A	- / -	for		-	=	\$0	<u> </u>
Secondary Ancillary Structures				1			_			
Total SF of Secondary Ancillary Structures		EUL	C-RUL	Cost / U		Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	1





### 2022 School Facilities Inventory Report

#### Facility Name: ESSEX NORTH SU | CANAAN SCHOOLS | 99 SCHOOL STREET, CANAAN 5903 -Combination - Secondary Building

### **Explanation of Terms**

Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life( C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.