

2022 School Facilities Inventory Report



Facility Name: FRANKLIN NORTHEAST SU | BERKSHIRE ELEMENTARY SCHOOL | 4850 WATER TOWER ROAD, RICHFORD 5476 - Combination - Main Building

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$3,193,629



GPS: 44.972512559276886, -72.76615625862007




Site Plan - Google Earth




Location Plan - Google Maps


Relative Asset Values



Value of Assets/GSF \$106.45







(See Last Page for Explanation of Terms)





2022 School Facilities Inventory Report

Facility Name:	FRANKLIN NORTHEAST SU BERKSHIRE ELEMENTARY SCHOOL 4850 WATER				
	TOWER ROAD, RICHFORD 5476 - Combination - Main Building				
Respondent Information					
-	2021-12-12 - 11:55 AM				
Respondent Name	Leonard Badeau				
Respondent Title	Principal				
Respondent Email	leonard.badeau@fnesu.org				
Respondent Phone Number	(802) 933-2290				
Facility Information					
School Type	Combination				
Building Identification	Main Building				
Stories	2				
Building Area	30000 (Gross Square Footage - GSF)				
Year Constructed	1960				
Year of Last Major Renovation	2017				
FCI (Depleted Value)	80.2%				
Environmental & Safety Issues					
Hazardous Materials	Yes	/			
Hazardous (HZD) Materials include	Asbestos containing materials (ACM)				
HZD Issues are	Major				
HZD Issues include	We have asbestos insulation (wrapping) of a few pipes in our boiler room. This is the only area of the school that has the asbestos, and the wrapping is in good condition. Per our Absestos abatement / management plan there is no needed action on this unless the wrapping begins to deteriorate or a project is needed to be completed in that area that would damage or require removal of the wrapping.				
Indoor Air Quality (IAQ) Issues	No				
IAQ Issues include					
IAQ Issues are					
IAQ Issues include	-				
Fire or Life/Safety (FL/S) Issues	No				
FL/S Issues are					
Other Risk Factors					
Other Risk Factors include					
Other Risk Factors are					
Handicap Accessibility (ADA) Issues					
Handicap Accessibility (ADA) Issues	Maybe	\wedge			
ADA Issues are	Minor	_			
	I am unsure if this is an accessibility issue, as we have ramps or leveled entryways in the north, west, and east entrances to the building, but the south entrance (our main recess door), does not have a ramp exit. There for in the event of an incident that blocked exits out the north, east, or west, an individual would not have ramp access to exit. However, all classrooms on the first floor have ground level access so they can leave via those classrooms, but if they needed to use the recess door (south exit), they would not have a ramp to use.				
Utilities - Adequacy					
IT / Internet Service	Adequate				
Building Wi-Fi Coverage	Adequate				
Cellular Reception	Inadequate	/			
Water Service Pressure	Adequate	_			
Natural Gas/Propane Pressure					
• •					





2022 School Facilities Inventory Report

Facility Name: FRANKLIN NORTHEAST SU | BERKSHIRE ELEMENTARY SCHOOL | 4850 WATER TOWER ROAD, RICHFORD 5476 - Combination - Main Building

TOWER ROA		10 54/0	5 - Complination	i - iviai	n bullaing			
Building Envelope - Roof								
Roof 1 is Single-Ply EPDM/	TPO/PVC Memb	rane						
Covers 50%	EUL	C-RUL	Cost / Uni	t	Quantity Unit	5	Total Value	
Installed in 2003	20	1	\$11.00 / SF	for	7,500 SF	=	\$82,500	1
Roof 2 is Single-Ply EPDM/	TPO/PVC Memb	rane						1
Covers 50%	EUL	C-RUL	Cost / Uni	t	Quantity Units	5	Total Value	
Installed in 2003	20	1	\$11.00 / SF	for	7,500 SF	=	\$82,500	1
Roof 3 is -	20	_	çılıco (c.		.,		<i>\\</i>	1
Covers 0%	EUL	C-RUL	Cost / Uni	t	Quantity Unit	5	Total Value	1
Installed in -	-	N/A	- / -	for		=	\$0	1
Roof 4 is -			1				ΨŬ	1
Covers 0%	EUL	C-RUL	Cost / Uni	t	Quantity Units		Total Value	1
Installed in -	-	N/A	- / -	for		=	\$0	1
Building Envelope - Windows			1	101			ψŪ	1
Primary Window System Window, Wood-F	rame							
% of Windows That are this Type 100%	EUL	C-RUL	Cost / Uni	t	Quantity Units	5	Total Value	1
Installed in 1965	30	-27	\$70.00 / SF	for	7,200 SF	=	\$504,000	1
Secondary Window System -	50	27	970.00 7 31	101	7,200 51		<i>\$</i> 30 4 ,000	
% of Windows That are this Type 0%	EUL	C-RUL	Cost / Uni	t	Quantity Units	:	Total Value	1
Installed in -	LOL	N/A	- / -	for	Quantity Onit.	, =	\$0	
ervices - Elevators			- / -	101			ŲÇ	1
Primary Conveyance/Elevators Elevator, Hydraul	lic Machine/Cor	troller/Ca	h					
Quantity of Stops 2	EUL	C-RUL	Cost / Uni	t	Quantity Units	:	Total Value	1
Installed in 1985	30	-7	\$25,000.00 / STC		2 STOP	, 	\$50,000	1
Secondary Conveyance/Elevators -		-7	323,000.00 / 310		2 310F		Ş30,000	
Quantity of Stops 0	EUL	C-RUL	Cost / Uni	+	Quantity Units	-	Total Value	1
Installed in -	LOL	N/A	Cost / Oni	for	0 -	, =		1
Services - Plumbing	-	N/A	- / -	101	0 -		ŞU	1
Primary Plumbing System Supply & Sanitary	/ Low Donsity (I	ncludos Eix	(turos)					
Area of building served 100%	EUL	C-RUL	Cost / Uni	+	Quantity Units		Total Value	1
Installed in 1965	40	-17	\$7.00 / GSF		30,000 GSF	, =	\$210,000	1
	40	-17	\$7.00 / GSF	101	50,000 G3F		\$210,000	
Secondary Plumbing System - Area of building served 0%	EUL	C-RUL	Cost / Uni	+	Quantity Units		Total Value	1
	LOL	N/A		for	Quantity Offic) =		1
	-	N/A	- / -	TOP		=	\$0	L
Services - Cooling - Central System Primary Central Cooling System Central Cooling Sv	vetom Chillor(e) Air Cool	od					
Area of building served 30%	EUL	C-RUL	Cost / Uni	+	Quantity Units	-	Total Value	1
Installed in 2017	25	20	\$1,200.00 / TOI	-	36 TON	, =	\$43,200	1
	25	20	\$1,200.00 / 101		50 TUN		\$45,200	
Secondary Plumbing System - Area of building served 0%	EUL	C-RUL	Cost / Uni	+	Quantity Units		Total Value	1
C C	EUL	N/A		for	Quantity Units			1
Installed in -	-	N/A	- / -	101		=	\$0	1
ervices - Heating - Central System	Fuel Oil							
Primary Heating System Boiler(s)/System Area of building served 100%	EUL	C-RUL	Cost / Uni	+	Quantity Unit		Total Value	1
6					<i>.</i>			,
Installed in 1985	30	-7	\$60.00 / MB	H for	857 MBH	=	\$51,429	
Secondary Heating System -					0		Tatal)(a)	
Area of building served 0%	EUL	C-RUL	Cost / Uni		Quantity Units		Total Value	4
Installed in -	-	N/A	- / -	for		=	\$0	





2022 School Facilities Inventory Report

Facility Name: FRANKLIN NORTHEAST SU | BERKSHIRE ELEMENTARY SCHOOL | 4850 WATER TOWER ROAD, RICHFORD 5476 - Combination - Main Building

	TOWER ROAD, R	ICHFO	RD 547(6 - Combina	tion -	Mair	n Buildin	g			
ervices - HVAC Distribution											
Primary HVAC Distribution System	Piped System to Unit Ve	entilators	/Fan Coils,	2-Pipe System							
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	-7	\$10.00 /	GSF	for	30,000		=	\$300,000	
Secondary HVAC Distribution System				+			,			+	4
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	1
Installed in		-	N/A	Cost _		for	Quantity	Onits	=	\$0	
ervices - Package Systems	-	-	N/A	- /	-	101	-	-	1- 1	ŲÇ	
Primary HVAC Package Unit & Splits	Package Linits (RTLIs)										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	1
Installed in		20	-17	\$7,000.00 /		for		TON	=	\$840.000	
Secondary HVAC Package Unit & Splits		20	-17	Ş7,000.00 J	TON	101	120	TON	-		4
, , , , , , , , , , , , , , , , , , , ,		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	ı I
Area of building served		EUL		Cost		6	Quantity	Units			
Installed in	-		N/A	- /	' -	for		-	=	\$0	
rvices - Fire Suppression	Control I and Control Mardia	D									
Primary Fire Suppression System					/ 11.0.14		0	L lusito		Tetel	1
Area of building served		EUL	C-RUL	Cost	/ Unit	6	Quantity	Units		Total Value	
Installed in	1985	40	3	\$5.00 /	GSF	for	30,000	GSF	=	\$150,000	
Secondary Fire Suppression System	Kitchen Hood or Compu	iter Cente	er Suppres	sion System							
Area of building served	1 EA	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	1
Installed in	1985	20	-17	\$10,000.00	É EA	for	1	EA	=	\$10,000	
rvices - Fire Alarm System		-		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						1	
Primary Fire Suppression System	Modern Addressable Fir	re Alarm S	Svstem								
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	L
Installed in		20	-17	\$3.00 /		for	30,000		=	\$90,000	
Secondary Fire Suppression System		20	17	Ş3.00 J	51	101	50,000	51		<i>\$50,000</i>	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	1
Installed in		-	N/A	- /		for	Quantity	onits	=	\$0	
rvices - Security Systems				/		101			1-1	ŲŲ	
Primary Security & Low Volt System	Security & Low Voltage	Systems -	- Average								
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	1
Installed in		15	-22	\$4.00 /		for	30,000		=	\$120,000	
		15	-22	Ş4.00 J	031	101	30,000	031		\$120,000	
Secondary Security & Low Volt System Area of building served		EUL	C-RUL	Cost	/ Unit		Quantitu	Units		Total Value	1
C C				Cost		6	Quantity	Units			
Installed in		-	N/A	- /	-	for		-	=	\$0	
rvices - Electrical Distribution/Infrastructure		(6 6									
Electrical Distribution/Infrastructure						1 Densi		11-26-6		T-+-1)/-1	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	2017	40	35	\$22.00 /	GSF	for	30,000	GSF	=	\$660,000	
rvices - Solar Power (PV)											
Solar (Electric Generation) Provided											
Owned/Maintained by School				Value of Solar P		: -					
Quantity of Panels		EUL	C-RUL	Cost			Quantity	Units		Total Value	
		-	N/A	- /	-	for	-	-	=	\$0	
Installed in	-										
ncillary Structures											
ncillary Structures Ancillary Structures	None					_					
ncillary Structures	None	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
ncillary Structures Ancillary Structures	None -	EUL -	C-RUL		/ Unit	for	Quantity	Units -	=	Total Value <mark>\$0</mark>	
ncillary Structures Ancillary Structures Total SF of Ancillary Structures	None - -	EUL -				for	Quantity -	Units -			
ncillary Structures Ancillary Structures Total SF of Ancillary Structures Installed in	None - - -	EUL - EUL			_	for	Quantity - Quantity	Units - Units	=		
ncillary Structures Ancillary Structures Total SF of Ancillary Structures Installed in Secondary Ancillary Structures	None - - - 0	-	N/A	- / Cost	_	for for	-	-	=	\$0	

-





2022 School Facilities Inventory Report

Facility Name: FRANKLIN NORTHEAST SU | BERKSHIRE ELEMENTARY SCHOOL | 4850 WATER TOWER ROAD, RICHFORD 5476 - Combination - Main Building

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.