

2022 School Facilities Inventory Report



Facility Name: FRANKLIN NORTHEAST SU | RICHFORD ELEMENTARY SCHOOL | 1 ELEMENTARY SCHOOL ROAD, RICHFORD 5476 - Combination - Main Building

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$1,589,817



GPS: 44.98390021677246, -72.67850567135693




Site Plan - Google Earth




Location Plan - Google Maps

Relative Asset Values




Value of Assets/GSF \$88.42

Projected Capital Planning Cash Flow



Facility Condition Index (FCI) Compared to Portfolio



(See Last Page for Explanation of Terms)







2022 School Facilities Inventory Report

Facility Name:	FRANKLIN NORTHEAST SU RICHFORD ELEMENTARY SCHOOL 1 ELEMENTARY	
	SCHOOL ROAD, RICHFORD 5476 - Combination - Main Building	
espondent Information		
Date/Time Completed	2021-12-15 - 9:16 AM	
Respondent Name	Gerard Capone	
Respondent Title	Director of Facilities	
Respondent Email	jerry.capone@fnesu.org	
Respondent Phone Number	(802) 848-7416 x130	
acility Information		
School Type	Combination	
Building Identification	Main Building	
Stories	1	
Building Area	17980 (Gross Square Footage - GSF)	
Year Constructed	1968	
Year of Last Major Renovation	N/A	
FCI (Depleted Value)	95.6%	
nvironmental & Safety Issues		
Hazardous Materials		
Hazardous (HZD) Materials include	Asbestos containing materials (ACM)	
HZD Issues are	Major	
HZD Issues include	Gym (2542 sf) and gym office (252 sf) has Asbestos mastic under floor tiles	
Indoor Air Quality (IAQ) Issues	Yes	
IAQ Issues include	Insufficient Air Change Ratio, Heating And ventilation is inefficient installed in 1968, Exhaust is not energy efficient	
	Major	
IAQ Issues are		
IAQ Issues include	Aging heating and ventilation not energy efficient.	
IAQ Issues include Fire or Life/Safety (FL/S) Issues	Aging heating and ventilation not energy efficient. Maybe	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are	Aging heating and ventilation not energy efficient. Maybe -	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors	Aging heating and ventilation not energy efficient. Maybe - Yes	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are	Aging heating and ventilation not energy efficient. Maybe - Yes	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement.	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are andicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are andicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are ADA Issues include	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are ADA Issues include	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A N/A	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are ADA Issues include Itilities - Adequacy IT / Internet Service	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A N/A N/A Marginal	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are ADA Issues include Itilities - Adequacy IT / Internet Service Building Wi-Fi Coverage	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A N/A N/A Marginal Adequate	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are ADA Issues include Itilities - Adequacy IT / Internet Service Building Wi-Fi Coverage Cellular Reception	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A N/A N/A Marginal Adequate Inadequate	
IAQ Issues include Fire or Life/Safety (FL/S) Issues FL/S Issues are Other Risk Factors Other Risk Factors include Other Risk Factors are Iandicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues ADA Issues are ADA Issues include Itilities - Adequacy IT / Internet Service Building Wi-Fi Coverage	Aging heating and ventilation not energy efficient. Maybe - Yes Flooding During heavy rains and snow melt flooding in basement. No N/A N/A N/A Marginal Adequate Inadequate Adequate	





2022 School Facilities Inventory Report

Facility Name: FRANKLIN NORTHEAST SU | RICHFORD ELEMENTARY SCHOOL | 1 ELEMENTARY SCHOOL ROAD, RICHFORD 5476 - Combination - Main Building

	SCHOOL ROAD, N			- combinatio		in Dunung			
Building Envelope - Roof									
Roof 1 is	Built-Up Roof or Modifie	e <mark>d Bitum</mark> e							
Covers	50%	EUL	C-RUL	Cost / Un	it	Quantity Unit	s	Total Value	
Installed in	1968	25	-29	\$14.00 / SF	for	8,990 SF	=	\$125,860	<u>/</u>
Roof 2 is	Built-Up or Modified Bit	umen							
Covers	25%	EUL	C-RUL	Cost / Un	it	Quantity Unit	s	Total Value	
Installed in		25	3	\$14.00 / SF	for	4,495 SF	=	\$62,930	
Roof 3 is	Single-Ply EPDM/TPO/P	VC Memb	rane						
Covers	25%	EUL	C-RUL	Cost / Un	it	Quantity Unit	S	Total Value	
Installed in	2020	20	18	\$11.00 / SF	for	4,495 SF	=	\$49,445	
Roof 4 is	-								
Covers	0%	EUL	C-RUL	Cost / Un	it	Quantity Unit	s	Total Value	
Installed in	-	-	N/A	- / -	for		=	\$0	
Building Envelope - Windows			• • •						
Primary Window System									
% of Windows That are this Type	100%	EUL	C-RUL	Cost / Un	it	Quantity Unit	s	Total Value	
Installed in	1968	30	-24	\$60.00 / SF	for	4,315 SF	=	\$258,912	<u> </u>
Secondary Window System									
% of Windows That are this Type	0%	EUL	C-RUL	Cost / Un	it	Quantity Unit	s	Total Value	
Installed in	-	-	N/A	- / -	for		=	\$0	
Services - Elevators									
Primary Conveyance/Elevators	None								
Quantity of Stops	0	EUL	C-RUL	Cost / Un	it	Quantity Unit	s	Total Value	
Installed in		-	N/A	- / -	for	0 -	=	\$0	
Secondary Conveyance/Elevators									
Quantity of Stops	0	EUL	C-RUL	Cost / Un	it	Quantity Unit	S	Total Value	
Installed in	-	-	N/A	- / -	for	0 -	=	\$0	
Services - Plumbing									
Primary Plumbing System									
Area of building served		EUL	C-RUL	Cost / Un		Quantity Unit	-	Total Value	
Installed in		40	-14	\$7.00 / GS	F for	17,980 GSF	=	\$125,860	<u>!</u>
Secondary Plumbing System									
Area of building served		EUL	C-RUL	Cost / Un		Quantity Unit		Total Value	
Installed in	-	-	N/A	- / -	for		=	\$0	
Services - Cooling - Central System									
Primary Central Cooling System									
Area of building served		EUL	C-RUL	Cost / Un		Quantity Unit		Total Value	
Installed in		-	N/A	- / -	for		=	\$0	
Secondary Plumbing System									
Area of building served		EUL	C-RUL	Cost / Un		Quantity Unit		Total Value	
Installed in	-	-	N/A	- / -	for		=	\$0	
Services - Heating - Central System									
Primary Heating System		5 11						Tatal)/ab	
Area of building served		EUL	C-RUL	Cost / Un		Quantity Unit		Total Value	
Installed in		30	17	\$62.00 / ME	BH for	514 MBH	=	\$31,850	
Secondary Heating System									
Area of building served		EUL	C-RUL	Cost / Un	-	Quantity Unit		Total Value	
Installed in	-	-	N/A	- / -	for		=	\$0	





2022 School Facilities Inventory Report

Facility Name: FRANKLIN NORTHEAST SU | RICHFORD ELEMENTARY SCHOOL | 1 ELEMENTARY SCHOOL ROAD, RICHFORD 5476 - Combination - Main Building

9	SCHOOL ROAD, R	ICHFO	RD 5476	- Combina	ition - I	Mai	n Buildiı	ng			
Services - HVAC Distribution											
Primary HVAC Distribution System	IVAC System, Hydronic P	Piping, 2-	Pipe			_					
Area of building served 1	.00%	EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in 1	.968	40	-14	\$5.00 /	SF	for	17,980	SF	=	\$89,900	
Secondary HVAC Distribution System	orced Air System (AHUs)	, Ductwo	rk, VAVs), 2	-Pipe System	ļ						
Area of building served 1		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in 1		30	-24	\$18.00 /		for	17,980		=	\$323,640	
ervices - Package Systems				,						+===;==	
Primary HVAC Package Unit & Splits	lone										
Area of building served (EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Secondary HVAC Package Unit & Splits -				,		-			1 1		1
Area of building served (EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	1
Installed in -		-	N/A	- /		for	-	-	=	\$0	
Services - Fire Suppression			, / .	7					1 1	÷*	_
Primary Fire Suppression System	lone										
Area of building served (EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in -		-	N/A	- /		for	-	-	=	\$0	
Secondary Fire Suppression System -				,						7.	1
	201	E 111		Cash /	11		0	11		T -+-)/-	
Area of building served C	J%	EUL	C-RUL	Cost /	Unit	c	Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Services - Fire Alarm System	Anderes Addressedule Eire	Aller of C									
Primary Fire Suppression System					11		0	11		T -+-)/-	1
Area of building served 1		EUL	C-RUL	Cost /	Unit	c	Quantity	Units		Total Value	
Installed in 2	2000	20	-2	\$3.00 /	SF	for	17,980	SF	=	\$53,940	Ζ
Secondary Fire Suppression System -	201	E 111			11		0	11		T -+-)/-	1
Area of building served C	J%	EUL	C-RUL	Cost /	Unit	c	Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Services - Security Systems	in the Outer of Velterer C										
Primary Security & Low Volt System S				Cast /	ا ا م ا م		0	Linite		Tatal \/alua	1
Area of building served 1		EUL	C-RUL	Cost /	Unit	ć	Quantity	Units		Total Value	
Installed in 2	2000	15	-7	\$4.00 /	GSF	for	17,980	GSF	=	\$71,920	
Secondary Security & Low Volt System -				a /			a				
Area of building served C)%	EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Services - Electrical Distribution/Infrastructure		(0.1.5									
Electrical Distribution/Infrastructure						Densi					
Area of building served 1		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in 1	.968	40	-14	\$22.00 /	GSF	for	17,980	GSF	=	\$395,560	Z
Services - Solar Power (PV)											
Solar (Electric Generation) Provided											
Owned/Maintained by School -		-		alue of Solar P			A 111			-	
Quantity of Panels)	EUL	C-RUL	Cost /		c	Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Ancillary Structures											
Ancillary Structures	lone	-		_ _ (o		1	-	
Total SF of Ancillary Structures		EUL	C-RUL	Cost /			Quantity	Units		Total Value	
Installed in -		-	N/A	- /	-	for	-	-	=	\$0	
Secondary Ancillary Structures -											
• •										T 1 1 1 1	
Total SF of Secondary Ancillary Structures		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	

Date of installs unknown have 0000 in the date field





2022 School Facilities Inventory Report

Facility Name: FRANKLIN NORTHEAST SU | RICHFORD ELEMENTARY SCHOOL | 1 ELEMENTARY SCHOOL ROAD, RICHFORD 5476 - Combination - Main Building

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.