

2022 School Facilities Inventory Report


Facility Name: **FRANKLIN NORTHEAST SU | RICHFORD JR/SR HIGH SCHOOL | 1 CORLISS HEIGHTS, RICHFORD 5476 - Combination - Main Building**

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) **\$3,757,690**





GPS: 44.99521086253848, -72.67025756343389




Value of Assets/GSF **\$99.41**



Site Plan - Google Earth



Location Plan - Google Maps



(See Last Page for Explanation of Terms)

2022 School Facilities Inventory Report

Facility Name: **FRANKLIN NORTHEAST SU | RICHFORD JR/SR HIGH SCHOOL | 1 CORLISS HEIGHTS, RICHFORD 5476 - Combination - Main Building**

Respondent Information

Date/Time Completed **2021-12-21 - 10:58 AM**
 Respondent Name **Gerard Capone**
 Respondent Title **Director of Facilities**
 Respondent Email **jerry.capone@fnesu.org**
 Respondent Phone Number **(802) 848-7416 x130**

Facility Information

School Type **Combination**
 Building Identification **Main Building**
 Stories **4**
 Building Area **37800 (Gross Square Footage - GSF)**
 Year Constructed **1917**
 Year of Last Major Renovation **1997**
 FCI (Depleted Value) **63.2%**

Environmental & Safety Issues

Hazardous Materials **Yes** ⚠
 Hazardous (HZD) Materials include **Asbestos containing materials (ACM)**
 HZD Issues are **Minor**
 HZD Issues include **Asbestos pipe wrap inside a brick wall**

Indoor Air Quality (IAQ) Issues **No**
 IAQ Issues include **-**
 IAQ Issues are **-**
 IAQ Issues include **-**

Fire or Life/Safety (FL/S) Issues **Yes** ⚠
 FL/S Issues are **Ice build up resulting in closing some sidewalks**

Other Risk Factors **Yes** ⚠
 Other Risk Factors include **Ice and snow shedding**
Ice and snow fall from roof, resulting in closing some sidewalks.
 Other Risk Factors are **Poor drainage around perimeter of building causing Moisture issue in walls below grade**
Poor parking lot and driveway drainage, causing ice buildup and slip and fall risks

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues **No**
 ADA Issues are **N/A**
 ADA Issues include **N/A**

Utilities - Adequacy

IT / Internet Service **Adequate**
 Building Wi-Fi Coverage **Adequate**
 Cellular Reception **Marginal** ⚠
 Water Service Pressure **Adequate**
 Natural Gas/Propane Pressure **Adequate**
 Electrical Capacity **Adequate**

2022 School Facilities Inventory Report

Facility Name: **FRANKLIN NORTHEAST SU | RICHFORD JR/SR HIGH SCHOOL | 1 CORLISS HEIGHTS, RICHFORD 5476 - Combination - Main Building**

Building Envelope - Roof

Roof 1 is Metal	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers 100%	40	15	\$13.00 / SF	9,450	SF	\$122,850
Installed in 1997						
Roof 2 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers 0%	-	N/A	- / -	-	-	\$0
Installed in -						
Roof 3 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers 0%	-	N/A	- / -	-	-	\$0
Installed in -						
Roof 4 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers 0%	-	N/A	- / -	-	-	\$0
Installed in -						

Building Envelope - Windows

Primary Window System Window, Wood-Frame	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type 70%	30	27	\$70.00 / SF	6,350	SF	\$444,528
Installed in 2019						
Secondary Window System Window, Wood-Frame	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type 30%	30	5	\$70.00 / SF	2,722	SF	\$190,512
Installed in 1997						

Services - Elevators

Primary Conveyance/Elevators Elevator, Hydraulic, Machine/Controller/Cab	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops 4	30	-19	\$25,000.00 / STOP	4	STOP	\$100,000
Installed in 1973						
Secondary Conveyance/Elevators -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops 0	-	N/A	- / -	0	-	\$0
Installed in -						

Services - Plumbing

Primary Plumbing System Supply & Sanitary, Low Density (Includes Fixtures)	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served 100%	40	15	\$7.00 / GSF	37,800	GSF	\$264,600
Installed in 1997						
Secondary Plumbing System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served 0%	-	N/A	- / -	-	-	\$0
Installed in -						

Services - Cooling - Central System

Primary Central Cooling System None	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served 0%	-	N/A	- / -	-	-	\$0
Installed in -						
Secondary Plumbing System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served 0%	-	N/A	- / -	-	-	\$0
Installed in -						

Services - Heating - Central System

Primary Heating System Boiler(s)/System - Solid Fuel (Wood/Pellet)	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served 100%	25	12	\$250.00 / MBH	1,080	MBH	\$270,000
Installed in 2009						
Secondary Heating System Boiler(s)/System - Gas	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served 100%	30	5	\$62.00 / MBH	1,080	MBH	\$66,960
Installed in 1997						

2022 School Facilities Inventory Report

Facility Name: **FRANKLIN NORTHEAST SU | RICHFORD JR/SR HIGH SCHOOL | 1 CORLISS HEIGHTS, RICHFORD 5476 - Combination - Main Building**

Services - HVAC Distribution

Primary HVAC Distribution System **Forced Air System (AHUs, Ductwork, VAVs), 2-Pipe System**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1997	30	5	\$18.00 / GSF	37,800	GSF	\$680,400

Secondary HVAC Distribution System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

Services - Package Systems

Primary HVAC Package Unit & Splits **Split System, Ductless, Multi Zone**

Area of building served	40%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2014	15	7	\$6,000.00 / TON	60	TON	\$362,880

Secondary HVAC Package Unit & Splits -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

Services - Fire Suppression

Primary Fire Suppression System **Sprinkler System, Medium Density/Complexity**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1997	40	15	\$5.00 / GSF	37,800	GSF	\$189,000

Secondary Fire Suppression System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

Services - Fire Alarm System

Primary Fire Suppression System **Modern Addressable Fire Alarm System**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1997	20	-5	\$3.00 / SF	37,800	SF	\$113,400

Secondary Fire Suppression System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

Services - Security Systems

Primary Security & Low Volt System **Security & Low Voltage Systems - Average**

Area of building served	80%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2004	15	-3	\$4.00 / GSF	30,240	GSF	\$120,960

Secondary Security & Low Volt System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

Services - Electrical Distribution/Infrastructure

Electrical Distribution/Infrastructure **Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1997	40	15	\$22.00 / GSF	37,800	GSF	\$831,600

Services - Solar Power (PV)

Solar (Electric Generation) Provided **None**

Owned/Maintained by School -

Quantity of Panels 0

Installed in -

Value of Solar PV Panels: -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

Ancillary Structures

Ancillary Structures **None**

Total SF of Ancillary Structures -

Installed in -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

Secondary Ancillary Structures -

Total SF of Secondary Ancillary Structures 0

Installed in -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

Additional Comments

Ice and snow fall from roof, resulting in closing some sidewalks.

2022 School Facilities Inventory Report

Facility Name: **FRANKLIN NORTHEAST SU | RICHFORD JR/SR HIGH SCHOOL | 1 CORLISS HEIGHTS, RICHFORD 5476 - Combination - Main Building**

Explanation of Terms

Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.