

2022 School Facilities Inventory Report



Facility Name: HARWOOD UNIFIED UNION SUPERVISORY DISTRICT | THATCHER BROOK

PRIMARY US | 47 STOWE STREET, WATERBURY 5676 - Elementary (PreK thru 4) -

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$6,827,241



GPS: 44.339172101318226, -72.75312290876704




Site Plan - Google Earth




Location Plan - Google Maps

Relative Asset Values



Value of Assets/GSF \$97.53



Facility Condition Index (FCI) Compared to Portfolio FCI = 66.4%100.0% 90.0% 80.0% **Depleted Value** 70.0% 60.0% 50.0% 40.0% 30.0% \overline{O} 20.0% 10.0% 0.0% FCI Distribution

(See Last Page for Explanation of Terms)





2022 School Facilities Inventory Report

Facility Name:	HARWOOD UNIFIED UNION SUPERVISORY DISTRICT THATCHER BROOK
	PRIMARY US 47 STOWE STREET, WATERBURY 5676 - Elementary (PreK thru 4) -
Respondent Information	
Date/Time Completed	2022-01-13 - 9:34 AM
Respondent Name	Brad Gresham
Respondent Title	Director of Maintenance
Respondent Email	bgresham@huusd.org
Respondent Phone Number	(802) 583-8020
acility Information	
School Type	Elementary (PreK thru 4)
Building Identification	Main Building
Stories	3
Building Area	70000 (Gross Square Footage - GSF)
Year Constructed	1900
Year of Last Major Renovation	2006
FCI (Depleted Value)	66.4%
Environmental & Safety Issues	
Hazardous Materials	
Hazardous (HZD) Materials include	
HZD Issues are	-
HZD Issues include	-
Indoor Air Quality (IAQ) Issues	No
IAQ Issues include	• · · · · · · · · · · · · · · · · · · ·
IAQ Issues are	·
IAQ Issues include	-
Fire or Life/Safety (FL/S) Issues	No
FL/S Issues are	-
Other Risk Factors	No
Other Risk Factors include	-
Other Risk Factors are	-
Handicap Accessibility (ADA) Issues	
Handicap Accessibility (ADA) Issues	No
ADA Issues are	N/A
ADA Issues include	N/A
Jtilities - Adequacy	
IT / Internet Service	
Building Wi-Fi Coverage	
Cellular Reception	
Water Service Pressure	
Natural Gas/Propane Pressure	N/A
Electrical Capacity	Adequate





2022 School Facilities Inventory Report

Facility Name: HARWOOD UNIFIED UNION SUPERVISORY DISTRICT | THATCHER BROOK PRIMARY US | 47 STOWE STREET, WATERBURY 5676 - Elementary (PreK thru 4) -

	•			•						
Building Envelope - Roof										
	Asphalt Shingle					A				I
Covers		EUL	C-RUL	Cost / Unit		Quantity	Units		Total Value	
Installed in		30	10	\$5.50 / SF	for	18,667	SF	=	\$102,667	
	Single-Ply EPDM/TPO/P					.			T	I
Covers		EUL	C-RUL	Cost / Unit	6	Quantity	Units		Total Value	
Installed in		20	-22	\$11.00 / SF	for	4,667	SF	=	\$51,333	Z
Roof 3 is			0.000			.			T	I
Covers		EUL	C-RUL	Cost / Unit		Quantity	Units		Total Value	
Installed in		-	N/A	- / -	for	-	-	=	\$0	
Roof 4 is										1
Covers		EUL	C-RUL	Cost / Unit	6	Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	
Building Envelope - Windows										
Primary Window System						0	11		Tabalata	I
% of Windows That are this Type		EUL	C-RUL	Cost / Unit		Quantity	Units		Total Value	,
Installed in		30	-92	\$70.00 / SF	for	15,960	SF	=	\$1,117,200	
Secondary Window System			0.000			.			T	1
% of Windows That are this Type		EUL	C-RUL	Cost / Unit	6	Quantity	Units		Total Value	
Installed in	2006	30	14	\$60.00 / SF	for	840	SF	=	\$50,400	
Services - Elevators	Eleveter Undreulie Me	eh in e /C ex	etweller /Ce							
Primary Conveyance/Elevators						Our at it.	Linita		Total Value	
Quantity of Stops		EUL	C-RUL	1111	6	Quantity				
Installed in		30	14	\$25,000.00 / STOP	for	5	STOP	=	\$125,000	
Secondary Conveyance/Elevators		EUL	C-RUL	Cost / Unit		Our at it.	Units		Total Value	
Quantity of Stops		EUL		Cost / Unit	6	Quantity				
Installed in	-	-	N/A	- / -	for) -	=	\$0	
Services - Plumbing	Supply & Capitony Low	Donaity (I	naludas Fi	uturoc)						
Primary Plumbing System		EUL				Quantity	Unite		Total Value	
Area of building served		-	C-RUL	1111	6	Quantity	Units		Total Value	
Installed in		40	24	\$7.00 / GSF	for	70,000	GSF	=	\$490,000	
Secondary Plumbing System		ET 11		Cast / Linit		Our at it.	Linita	1	Tatal	
Area of building served		EUL	C-RUL	Cost / Unit	6	Quantity	Units		Total Value	
Installed in	•	-	N/A	- / -	for	-	-	=	\$0	
Services - Cooling - Central System	Nene									
Primary Central Cooling System Area of building served		EUL	C-RUL	Cost / Unit		Quantity	Units		Total Value	
Installed in		EUL	N/A		for	Quantity	Units			
		-	N/A	- / -	TOP	-	-	=	\$0	
Secondary Plumbing System		ELU.		Cont / Linit		Our antitu	Linite		Tatal Malua	1
Area of building served		EUL	C-RUL	Cost / Unit	6	Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	
Services - Heating - Central System	Doilor(c)/Custom Early	2:1								
, , ,	Boiler(s)/System - Fuel (C-RUL	Cost / Unit		Quantity	Luite		Total Value	1
Area of building served		EUL	C-RUL		6	Quantity	Units			
Installed in		30	14	\$60.00 / MBH	for	2,000	MBH	=	\$120,000	
Secondary Heating System								1	T	I
Area of building served		EUL	C-RUL	Cost / Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	





2022 School Facilities Inventory Report

Facility Name: HARWOOD UNIFIED UNION SUPERVISORY DISTRICT | THATCHER BROOK PRIMARY US | 47 STOWE STREET. WATERBURY 5676 - Elementary (PreK thru 4) -

	PRIMARY US	47 STOW	/E STRE	E T, WATER E	BURY 56	76 - Elen	nentary	/ (Pr	eK thru 4) -	
rvices - HVAC Distribution										
Primary HVAC Distribution System	Piped System to Unit	Ventilators/	Fan Coils,	2-Pipe System						
Area of building served	95%	EUL	C-RUL	Cost /	Unit	Quanti	ty Units	S	Total Value	
Installed in	2006	30	14	\$10.00 /	GSF fo	or 66,50	00 GSF	=	\$665,000	
Secondary HVAC Distribution System	Piped System to Unit	Ventilators/	Fan Coils, I	2-Pipe System	•	•				-
Area of building served	5%	EUL	C-RUL	Cost /	Unit	Quanti	ty Units		Total Value	
Installed in	1996	30	4	\$10.00 /	GSF fo	or 3,50	00 GSF	=	\$35,000	
vices - Package Systems										
Primary HVAC Package Unit & Splits										-
Area of building served	95%	EUL	C-RUL	Cost /	Unit	Quanti	ty Units		Total Value	
Installed in		20	4	\$7,000.00 /	TON fo	or 2	56 TON	=	\$1,862,000	
Secondary HVAC Package Unit & Splits								_		-
Area of building served		EUL	C-RUL	Cost /	Unit	Quanti	· ·		Total Value	4
Installed in	1996	20	-6	\$7,000.00 /	TON fo	or	14 TON	=	\$98,000	
vices - Fire Suppression										
Primary Fire Suppression System									T	
Area of building served		EUL	C-RUL	Cost /	Unit	Quanti	1		Total Value	4
Installed in	2006	40	24	\$5.00 /	GSF fo	or 70,0	00 GSF	=	\$350,000]
Secondary Fire Suppression System	-									
Area of building served	0%	EUL	C-RUL	Cost /	Unit	Quanti	ty Units	5	Total Value	
Installed in	-	-	N/A	- /	- fo	or -	-	=	\$0	1
vices - Fire Alarm System										
Primary Fire Suppression System	Modern Addressable	Fire Alarm S	ystem							
Area of building served	100%	EUL	C-RUL	Cost /	Unit	Quanti	ty Units	5	Total Value	
Installed in	1996	20	-6	\$3.00 /	SF fo	or 70,00	00 SF	=	\$210,000	
Secondary Fire Suppression System	-									-
Area of building served	0%	EUL	C-RUL	Cost /	Unit	Quanti	ty Units		Total Value	
Installed in	-	-	N/A	- /	- fo	or -	-	=	\$0	
vices - Security Systems										
Primary Security & Low Volt System										-
Area of building served		EUL	C-RUL	Cost /	Unit	Quanti	ty Units	5	Total Value	4
Installed in		-	N/A	- /	- fe	or -	-	=	\$0	
Secondary Security & Low Volt System										-
Area of building served		EUL	C-RUL	Cost /	Unit	Quanti	ty Units	5	Total Value	4
Installed in		-	N/A	- /	- fe	or -	-	=	\$0	
vices - Electrical Distribution/Infrastructure										
Electrical Distribution/Infrastructure									T	
Area of building served		EUL	C-RUL	Cost /	Unit	Quanti			Total Value	4
Installed in	2006	40	24	\$22.00 /	GSF fo	or 70,0	00 GSF	=	\$1,540,000]
rvices - Solar Power (PV)	Calas Davis Di t	hala (5) () 5								
Solar (Electric Generation) Provided		ortaic (PV) Pa		(aluce of Colors D)	(Densley de	0.041				
Owned/Maintained by School Quantity of Panels		ELU		/alue of Solar PV / Cost		Quanti	h lloit		Total Value	
		EUL	C-RUL			-				4
Installed in	2010	20	8	\$85.00 /	5F 10	or 1	25 SF	=	\$10,641	1
cillary Structures	Nono									
Ancillary Structures Total SF of Ancillary Structures		EUL	C-RUL	Cost /	Unit	Quanti	ty Units		Total Value	1
Installed in		EOE	N/A				cy onits	> =		1
installed in		-	N/A	- /	- T(or		=	ŞU	l
Cocondom Anaillan Church	-									1
Secondary Ancillary Structures		ELU		-Cost-/	Linit	Quanti	ty Linite		Total Value	
Secondary Ancillary Structures Total SF of Secondary Ancillary Structures Installed in	0	EUL	C-RUL	/ Cost - /	-	Quanti or -	ty Units	5 =	Total Value \$0	1





2022 School Facilities Inventory Report

Facility Name: HARWOOD UNIFIED UNION SUPERVISORY DISTRICT | THATCHER BROOK PRIMARY US | 47 STOWE STREET, WATERBURY 5676 - Elementary (PreK thru 4) -

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.