

### 2022 School Facilities Inventory Report

Facility Name: **KINGDOM EAST SD | BURKE TOWN SCHOOL | 3293 BURKE HOLLOW ROAD, WEST BURKE 5871 - Middle (5 thru 8) - Secondary Building**


March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) **\$133,863**



GPS: 44.625290148359795, -71.96023281631018

#### Relative Asset Values





Value of Assets/GSF **\$78.74**




Site Plan - Google Earth

#### Projected Capital Planning Cash Flow



Location Plan - Google Maps

#### Facility Condition Index (FCI) Compared to Portfolio



(See Last Page for Explanation of Terms)

### 2022 School Facilities Inventory Report

Facility Name: **KINGDOM EAST SD | BURKE TOWN SCHOOL | 3293 BURKE HOLLOW ROAD, WEST BURKE 5871 - Middle (5 thru 8) - Secondary Building**

#### Respondent Information

Date/Time Completed **2022-02-15 - 1:46 PM**  
 Respondent Name **Danny Pickering**  
 Respondent Title **Facilities Manager**  
 Respondent Email **dpickering@kingdomeast.org**  
 Respondent Phone Number **(802) 626-6100 x1400**

#### Facility Information


School Type **Middle (5 thru 8)**  
 Building Identification **Secondary Building**  
 Stories **1**  
 Building Area **1700 (Gross Square Footage - GSF)**  
 Year Constructed **1974**  
 Year of Last Major Renovation **N/A**  
 FCI (Depleted Value) **97.7%**

#### Environmental & Safety Issues

Hazardous Materials **No**  
 Hazardous (HZD) Materials include -  
 HZD Issues are -  
 HZD Issues include -

Indoor Air Quality (IAQ) Issues **No**  
 IAQ Issues include -  
 IAQ Issues are -  
 IAQ Issues include -

Fire or Life/Safety (FL/S) Issues **No**  
 FL/S Issues are -

Other Risk Factors **Yes**   
 Other Risk Factors include **Outdated PTAC units & water heater**  
 Other Risk Factors are **There are PTAC Units within the structure and a water heater that are very outdated and will need to be replaced.**

#### Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues **No**  
 ADA Issues are **N/A**  
 ADA Issues include **N/A**

#### Utilities - Adequacy

IT / Internet Service **Marginal**   
 Building Wi-Fi Coverage **Adequate**  
 Cellular Reception **Marginal**   
 Water Service Pressure **Adequate**  
 Natural Gas/Propane Pressure **N/A**  
 Electrical Capacity **Marginal** 

### 2022 School Facilities Inventory Report

Facility Name: **KINGDOM EAST SD | BURKE TOWN SCHOOL | 3293 BURKE HOLLOW ROAD, WEST BURKE 5871 - Middle (5 thru 8) - Secondary Building**

#### Building Envelope - Roof

Roof 1 is <b>Metal</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>100%</b>	40	-8	\$13.00 / SF	1,700	SF	\$22,100
Installed in <b>1974</b>						
Roof 2 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						
Roof 3 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						
Roof 4 is -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Building Envelope - Windows

Primary Window System <b>Window, Wood-Frame</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type <b>100%</b>	30	-18	\$70.00 / SF	408	SF	\$28,560
Installed in <b>1974</b>						
Secondary Window System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Elevators

Primary Conveyance/Elevators <b>None</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops <b>0</b>	-	N/A	- / -	0	-	\$0
Installed in -						
Secondary Conveyance/Elevators -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops <b>0</b>	-	N/A	- / -	0	-	\$0
Installed in -						

#### Services - Plumbing

Primary Plumbing System <b>Supply &amp; Sanitary, Low Density (Includes Fixtures)</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>100%</b>	40	-8	\$7.00 / GSF	1,700	GSF	\$11,900
Installed in <b>1974</b>						
Secondary Plumbing System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Cooling - Central System

Primary Central Cooling System <b>Central Cooling System - Chiller(s) - Air Cooled</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>100%</b>	25	-23	\$1,200.00 / TON	7	TON	\$8,160
Installed in <b>1974</b>						
Secondary Plumbing System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Heating - Central System

Primary Heating System <b>Boiler(s)/System - Solid Fuel (Wood/Pellet)</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>100%</b>	25	-23	\$250.00 / MBH	49	MBH	\$12,143
Installed in <b>1974</b>						
Secondary Heating System -	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in -						

### 2022 School Facilities Inventory Report

Facility Name: **KINGDOM EAST SD | BURKE TOWN SCHOOL | 3293 BURKE HOLLOW ROAD, WEST BURKE 5871 - Middle (5 thru 8) - Secondary Building**

#### Services - HVAC Distribution

Primary HVAC Distribution System **HVAC System, Hydronic Piping, 2-Pipe**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1974	40	-8	\$5.00 / SF	for 1,700	SF	= \$8,500



Secondary HVAC Distribution System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

#### Services - Package Systems

Primary HVAC Package Unit & Splits **None**

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

Secondary HVAC Package Unit & Splits -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

#### Services - Fire Suppression

Primary Fire Suppression System **None**

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

Secondary Fire Suppression System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

#### Services - Fire Alarm System

Primary Fire Suppression System **Modern Addressable Fire Alarm System**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2014	20	12	\$3.00 / SF	for 1,700	SF	= \$5,100

Secondary Fire Suppression System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

#### Services - Security Systems

Primary Security & Low Volt System **None**

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

Secondary Security & Low Volt System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	for -	-	= \$0

#### Services - Electrical Distribution/Infrastructure

Electrical Distribution/Infrastructure **Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1974	40	-8	\$22.00 / GSF	for 1,700	GSF	= \$37,400



#### Services - Solar Power (PV)

Solar (Electric Generation) Provided **None**

Owned/Maintained by School -

Quantity of Panels 0

Installed in	-	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
		-	N/A	- / -	for -	-	= \$0

Value of Solar PV Panels: -

#### Ancillary Structures

Ancillary Structures **None**

Total SF of Ancillary Structures -

Installed in	-	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
		-	N/A	- / -	for -	-	= \$0

Secondary Ancillary Structures -

Total SF of Secondary Ancillary Structures 0

Installed in	-	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
		-	N/A	- / -	for -	-	= \$0

#### Additional Comments

This is a modular structure with no foundation to it and it houses class rooms.

**2022 School Facilities Inventory Report**

Facility Name: **KINGDOM EAST SD | BURKE TOWN SCHOOL | 3293 BURKE HOLLOW ROAD, WEST BURKE 5871 - Middle (5 thru 8) - Secondary Building**

## Explanation of Terms

<b>Projected Capital Planning Cash Flow</b>	The estimated replacement costs of systems as they expire annually.
<b>Facility Condition Index (FCI)</b>	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
<b>Total Value of Assets</b>	The total estimated replacement cost of all the assets listed in the form.
<b>Value of Assets per GSF</b>	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
<b>Facility Condition Index (FCI) Compared to Portfolio</b>	The Facility Condition Index (FCI) of the building overlaid on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
<b>Calculated Remaining Useful Life( C-RUL)</b>	The current number of remaining years a system may be expected to perform in designed service.
<b>Expected Useful Life (EUL)</b>	The total number of years a system can be expected to perform in designed service when new.
<b>Gross Square Footage (GSF)</b>	The total square footage contained within the building for all floors/levels.
<b>Cost per Unit</b>	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
<b>Quantity</b>	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
<b>Units</b>	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
<b>Ancillary Structures</b>	Buildings on site that are typically known as portables, relocatables or temporary buildings.