



2022 School Facilities Inventory Report


KINGDOM EAST SD | CONCORD GRADED/MIDDLE SCHOOL | 173 SCHOOL Facility Name:

STREET, CONCORD 5824 - Combination - Secondary Building

March 29, 2022







Value of Assets/GSF \$77.84




Site Plan - Google Earth





Location Plan - Google Maps



(See Last Page for Explanation of Terms)

Page 1 of 5 v2022-03-29



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

KINGDOM EAST SD | CONCORD GRADED/MIDDLE SCHOOL | 173 SCHOOL Facility Name:

STREET, CONCORD 5824 - Combination - Secondary Building

Respondent Information

Date/Time Completed 2022-02-15 - 11:44 AM

Respondent Name Daniel Pickering Respondent Title Facilities Manager

Respondent Email dpickering@kingdomeast.org

Respondent Phone Number (802) 626-6100 x1400

Facility Information

School Type Combination

Building Identification Secondary Building

Stories

Building Area 31683 (Gross Square Footage - GSF)

Year Constructed 1968 Year of Last Major Renovation N/A 92.8%

FCI (Depleted Value)

Environmental & Safety Issues

Hazardous Materials No

Hazardous (HZD) Materials include

HZD Issues are -

HZD Issues include

Indoor Air Quality (IAQ) Issues No

IAQ Issues include -

IAO Issues are -

IAQ Issues include

Fire or Life/Safety (FL/S) Issues Yes

Currently during the construction nobody took into account the snow load that can amount on a room in the NEK,

FL/S Issues are we have markers on the roof and whenever snow rises about the measured set points, the roof is no longer considered safe and the building has to be evacuated or we cancel all events.

Other Risk Factors Yes

Other Risk Factors include

No insulation in the gymnasium building / roof has a snow load limit / aged electrical infrastructure, HVAC aged infrastructure

There is no insulation in the gym so the heat is poured into the massive area and just disperses, the roof has a limit Other Risk Factors are of snow it can have on it and when it has met the threshold it stands the chance of collapsing. Both electrical and HVAC infrastructures are old, and outdated.

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Adequate

Water Service Pressure Adequate

Natural Gas/Propane Pressure N/A

Electrical Capacity Marginal

v2022-03-29 Page 2 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

| Facility Name: | KINGDOM EAST S | SD CO | ONCOR | D GRADED/I | MIDDI | E SC | CHOOL | 173 S | CHC | OOL | |
|---|----------------------------|-----------|----------------|---------------|----------|-------|-------------|----------|-----|--------------------|------------|
| | STREET, CONCOR | D 582 | 4 - Com | bination - So | econda | arv l | Building | | | | |
| Building Envelope - Roof | | | | | | , | 8 | | | | |
| | Single-Ply EPDM/TPO/P\ | /C Memb | rane | | | | | | | | |
| Covers | 100% | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | 2008 | 20 | 6 | \$11.00 / | SF | for | 31,683 | SF | = | \$348,513 | |
| Roof 2 is | - | 1 | | | | | | | 1 1 | | |
| Covers | 0% | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / | - | for | - | - | = | \$0 | |
| Roof 3 is | - | | | | | | | | | | |
| Covers | 0% | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / | - | for | - | - | = | \$0 | |
| Roof 4 is | - | | | | | | | | | | |
| Covers | 0% | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / | - | for | - | - | = | \$0 | |
| Building Envelope - Windows | | | | | | | | | | | |
| Primary Window System | | | | | | | | | | | |
| % of Windows That are this Type | 100% | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | | 30 | -24 | \$70.00 / | SF | for | 7,604 | SF | = | \$532,274 | ⚠ |
| Secondary Window System | | | | | | | | | | | |
| % of Windows That are this Type | | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / | - | for | - | - | = | \$0 | |
| Services - Elevators | | | | | | | | | | | |
| Primary Conveyance/Elevators | | | | | | | | | _ | | |
| Quantity of Stops | | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | | - | N/A | - / | - | for | C |) - | = | \$0 | |
| Secondary Conveyance/Elevators | | | 0.5111 | | | | | | | | |
| Quantity of Stops | | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / | - | for | C |) - | = | \$0 | |
| Services - Plumbing | Const. O. Const. and Louis | N = 11 (1 | a alicela a Et | | | | | | | | |
| Primary Plumbing System | | | | | I I mile | | Our matitus | Haita | | Tatal Malus | |
| Area of building served | | EUL | C-RUL | Cost / | Unit | r | Quantity | Units | | Total Value | ٨ |
| Installed in | | 40 | -14 | \$7.00 / | GSF | for | 31,683 | GSF | = | \$221,781 | <u> </u> |
| Secondary Plumbing System | | 5111 | C DIII | Cook 1 | 11 | | 0 | 1 be the | | Tatal Malas | |
| Area of building served | | EUL | C-RUL | Cost / | | r | Quantity | Units | - | Total Value | |
| Installed in | - | - | N/A | - / | _ | for | - | | = | \$0 | |
| Services - Cooling - Central System | News | | | | | | | | | | |
| Primary Central Cooling System Area of building served | | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | | - EOL | N/A | | - | for | Qualitity | UTITES | = | †Otal value \$0 | |
| Secondary Plumbing System | | _ | IN/A | - / | | 101 | _ | | | 3 0 | |
| Area of building served | | EUL | C-RUL | Cost / | Unit | | Quantity | Unite | | Total Value | |
| Installed in | | LOL | N/A | - / | | for | Quaritity | Offics | = | \$0 | |
| Services - Heating - Central System | | <u> </u> | 14/74 | | | 101 | | | 1-1 | \$0 | |
| Primary Heating System | Boiler(s)/System - Fuel C |)il | | | | | | | | | |
| Area of building served | | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | | 30 | -24 | \$60.00 / | | for | | MBH | = | \$48,882 | Λ |
| Secondary Heating System | | 30 | | Ç00.00 / | 741011 | 1.01 | 013 | 11.511 | | ŸŦ0,002 | <u>ن</u> ے |
| Area of building served | | EUL | C-RUL | Cost / | Unit | | Quantity | Units | | Total Value | |
| Installed in | | | N/A | - / | | for | - carrierey | | = | \$0 | |
| Ilistalieu III | | _ | TV/ A | - / | | 101 | _ | | | ŞU | |

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

| Facility Name: | VINCEONA FACT | CD I C | ONCOR | D CDADED /MID | DIEC | CLICOL | 172.00 | CLIC | 201 | |
|---|---|------------|-----------|------------------------|---------|-----------|--------|--|-------------|-------------|
| racinty Name. | KINGDOM EAST SD CONCORD GRADED/MIDDLE SCHOOL 173 SCHOOL STREET, CONCORD 5824 - Combination - Secondary Building | | | | | | | | | |
| | STREET, CONCO | KD 582 | 4 - Com | bination - Secoi | ndary | Building | | | | |
| Services - HVAC Distribution | | | . | | | | | | | |
| Primary HVAC Distribution System | | | | | | | | | | |
| Area of building served | | EUL | C-RUL | Cost / Unit | | Quantity | • | | Total Value | |
| Installed in | 1999 | 30 | 7 | \$10.00 / GSF | for | 31,683 | GSF | = | \$316,830 | |
| Secondary HVAC Distribution System | - | | | | | | | | | |
| Area of building served | 0% | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | -/- | for | - | - | = | \$0 | |
| Services - Package Systems | | | | | | | | | | |
| Primary HVAC Package Unit & Splits | Split Systems | | | | | | | | | |
| Area of building served | 100% | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | 1999 | 15 | -8 | \$2,000.00 / TON | for | 127 | TON | = | \$253,464 | \triangle |
| Secondary HVAC Package Unit & Splits | - | | | | | | | | | |
| Area of building served | 0% | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | _ | N/A | -/- | for | _ | - | = | \$0 | |
| Services - Fire Suppression | | | | | | | | | | |
| Primary Fire Suppression System | None | | | | | | | | | |
| Area of building served | | EUL | C-RUL | Cost / Unit | i i | Quantity | Units | | Total Value | |
| Installed in | _ | _ | N/A | -/- | for | _ | _ | = | \$0 | |
| Secondary Fire Suppression System | _ | Į. | , | | | l | | | · | |
| | | 5111 | 6.5111 | 0 . / | | | | | T . IV. I | |
| Area of building served | 0% | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / - | for | - | - | = | \$0 | |
| Services - Fire Alarm System | | | | | | | | | | |
| Primary Fire Suppression System | | | | | _ | | | | | |
| Area of building served | | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | | 20 | -34 | \$1.50 / GSF | for | 31,683 | GSF | = | \$47,525 | Ţ |
| Secondary Fire Suppression System | | | | | | | | | | |
| Area of building served | 0% | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | -/- | for | - | - | = | \$0 | |
| Services - Security Systems | | | | | | | | | | |
| Primary Security & Low Volt System | None | | | | | | | | | |
| Area of building served | 0% | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | -/- | for | - | - | = | \$0 | |
| Secondary Security & Low Volt System | - | • | • | | | | | | | |
| Area of building served | 0% | EUL | C-RUL | Cost / Unit | : | Quantity | Units | | Total Value | |
| Installed in | - | _ | N/A | -/- | for | _ | - | = | \$0 | |
| Services - Electrical Distribution/Infrastructure | ! | | | | • | ļ. | | | | |
| Electrical Distribution/Infrastructure | | el w/Sub P | anels and | Generator/UPS - Medi | um Dens | ity | | | | |
| Area of building served | | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | | 40 | -14 | \$22.00 / GSF | | 31,683 | | = | \$697,026 | \triangle |
| Services - Solar Power (PV) | | | | ,, | | , | | <u>l </u> | , , , , , , | <u> </u> |
| Solar (Electric Generation) Provided | None | | | | | | | | | |
| Owned/Maintained by School | | | | Value of Solar PV Pane | els: - | | | | | |
| Quantity of Panels | | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | | _ | N/A | -/- | for | _ | _ | = | \$0 | |
| Ancillary Structures | | | , | | 1.0. | | | <u> </u> | Y · | |
| Ancillary Structures | None | | | | | | | | | |
| Total SF of Ancillary Structures | | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | | - | N/A | - / - | for | | - | = | \$0 | |
| | | | IV/A | - / - | 101 | | | - | ŞÜ | |
| Secondary Ancillary Structures | | EL II | C BLU | C / 1 | | النام الم | Harte | | Tatal Malus | |
| Total SF of Secondary Ancillary Structures | | EUL | C-RUL | Cost / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | - / - | for | - | - | = | \$0 | |

Additional Comments

The gym is in serious need of redesign and infrastructure support. It is an extreme hazard depending on the season.

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: KINGDOM EAST SD | CONCORD GRADED/MIDDLE SCHOOL | 173 SCHOOL

STREET, CONCORD 5824 - Combination - Secondary Building

Explanation of Terms

| Projected Capital Planning Cash Flow | The estimated replacement costs of systems as they expire annually. |
|--|---|
| Facility Condition Index (FCI) | The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service. |
| Total Value of Assets | The total estimated replacement cost of all the assets listed in the form. |
| Value of Assets per GSF | The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building. |
| Facility Condition Index (FCI) Compared to Portfolio | The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart. |
| Calculated Remaining Useful Life(C-RUL) | The current number of remaining years a system may be expected to perform in designed service. |
| Expected Useful Life (EUL) | The total number of years a system can be expected to perform in designed service when new. |
| Gross Square Footage (GSF) | The total square footage contained within the building for all floors/levels. |
| Cost per Unit | The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost. |
| Quantity | The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost. |
| Units | The expressed unit of measure for a given system (GSF, EACH, TON, etc). |
| Ancillary Structures | Buildings on site that are typically known as portables, relocatables or temporary buildings. |
| | |

v2022-03-29 Page 5 of 5