

### 2022 School Facilities Inventory Report

Facility Name: **MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Addition 1**


March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) **\$324,156**



GPS: 44.809287665525744, -73.08252178933525

#### Relative Asset Values





Value of Assets/GSF **\$79.45**




Site Plan - Google Earth

#### Projected Capital Planning Cash Flow



Location Plan - Google Maps

#### Facility Condition Index (FCI) Compared to Portfolio



(See Last Page for Explanation of Terms)

### 2022 School Facilities Inventory Report

Facility Name: **MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Addition 1**

#### Respondent Information

Date/Time Completed **2021-12-21 - 11:28 AM**  
 Respondent Name **Len Smith**  
 Respondent Title **Facilities Manager**  
 Respondent Email **lesmith@maplerun.org**  
 Respondent Phone Number **(802) 324-7052**

#### Facility Information

School Type **High (9 thru 12)**  
 Building Identification **Addition 1**  
 Stories **1**  
 Building Area **4080 (Gross Square Footage - GSF)**  
 Year Constructed **2020**  
 Year of Last Major Renovation **N/A**  
 FCI (Depleted Value) **6.4%**

#### Environmental & Safety Issues

Hazardous Materials **No**  
 Hazardous (HZD) Materials include -  
 HZD Issues are -  
 HZD Issues include -

Indoor Air Quality (IAQ) Issues **No**  
 IAQ Issues include -  
 IAQ Issues are -  
 IAQ Issues include -

Fire or Life/Safety (FL/S) Issues **No**  
 FL/S Issues are -

Other Risk Factors **No**  
 Other Risk Factors include -  
 Other Risk Factors are -

#### Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues **No**  
 ADA Issues are **N/A**  
 ADA Issues include **N/A**

#### Utilities - Adequacy

IT / Internet Service **Adequate**  
 Building Wi-Fi Coverage **Adequate**  
 Cellular Reception **Marginal**  
 Water Service Pressure **Adequate**  
 Natural Gas/Propane Pressure **Adequate**  
 Electrical Capacity **Adequate**



### 2022 School Facilities Inventory Report

Facility Name: **MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Addition 1**

#### Building Envelope - Roof

Roof 1 is <b>Metal</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>75%</b>	40	38	\$13.00 / SF	3,060	SF	\$39,780
Installed in <b>2020</b>						
Roof 2 is <b>Single-Ply EPDM/TPO/PVC Membrane</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>25%</b>	20	18	\$11.00 / SF	1,020	SF	\$11,220
Installed in <b>2020</b>						
Roof 3 is <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						
Roof 4 is <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Covers <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						

#### Building Envelope - Windows

Primary Window System <b>Window, Wood-Frame</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type <b>100%</b>	30	28	\$70.00 / SF	979	SF	\$68,544
Installed in <b>2020</b>						
Secondary Window System <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
% of Windows That are this Type <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						

#### Services - Elevators

Primary Conveyance/Elevators <b>None</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops <b>0</b>	-	N/A	- / -	0	-	\$0
Installed in <b>-</b>						
Secondary Conveyance/Elevators <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Quantity of Stops <b>0</b>	-	N/A	- / -	0	-	\$0
Installed in <b>-</b>						

#### Services - Plumbing

Primary Plumbing System <b>Supply &amp; Sanitary, Low Density (Includes Fixtures)</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>5%</b>	40	38	\$7.00 / GSF	204	GSF	\$1,428
Installed in <b>2020</b>						
Secondary Plumbing System <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						

#### Services - Cooling - Central System

Primary Central Cooling System <b>None</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						
Secondary Plumbing System <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						

#### Services - Heating - Central System

Primary Heating System <b>None</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						
Secondary Heating System <b>-</b>	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Area of building served <b>0%</b>	-	N/A	- / -	-	-	\$0
Installed in <b>-</b>						

### 2022 School Facilities Inventory Report

Facility Name: **MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Addition 1**

#### Services - HVAC Distribution

Primary HVAC Distribution System **Forced Air System (AHUs, Ductwork, VAVs), 2-Pipe System**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
90%	30	28	\$18.00 / GSF	3,672	GSF	\$66,096
Installed in 2020						

Secondary HVAC Distribution System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Package Systems

Primary HVAC Package Unit & Splits **Split System, Ductless, Multi Zone**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
10%	15	13	\$6,000.00 / TON	2	TON	\$9,792
Installed in 2020						

Secondary HVAC Package Unit & Splits -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Fire Suppression

Primary Fire Suppression System **Sprinkler System, Medium Density/Complexity**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
100%	40	38	\$5.00 / GSF	4,080	GSF	\$20,400
Installed in 2020						

Secondary Fire Suppression System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Fire Alarm System

Primary Fire Suppression System **Modern Addressable Fire Alarm System**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
100%	20	18	\$3.00 / SF	4,080	SF	\$12,240
Installed in 2020						

Secondary Fire Suppression System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Security Systems

Primary Security & Low Volt System **Security & Low Voltage Systems - Average**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
30%	15	13	\$4.00 / GSF	1,224	GSF	\$4,896
Installed in 2020						

Secondary Security & Low Volt System -

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
0%	-	N/A	- / -	-	-	\$0
Installed in -						

#### Services - Electrical Distribution/Infrastructure

Electrical Distribution/Infrastructure **Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density**

Area of building served	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
100%	40	38	\$22.00 / GSF	4,080	GSF	\$89,760
Installed in 2020						

#### Services - Solar Power (PV)

Solar (Electric Generation) Provided **None**

Owned/Maintained by School -

Quantity of Panels 0

Installed in -

Value of Solar PV Panels: -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

#### Ancillary Structures

Ancillary Structures **None**

Total SF of Ancillary Structures -

Installed in -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

Secondary Ancillary Structures -

Total SF of Secondary Ancillary Structures 0

Installed in -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

#### Additional Comments

The Connector building has 2 primary gas fired AHU's without cooling there is a multi zone mini ductless that services 3 areas The Fire alarm system resides in

### 2022 School Facilities Inventory Report

Facility Name: **MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Addition 1**

## Explanation of Terms

<b>Projected Capital Planning Cash Flow</b>	The estimated replacement costs of systems as they expire annually.
<b>Facility Condition Index (FCI)</b>	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
<b>Total Value of Assets</b>	The total estimated replacement cost of all the assets listed in the form.
<b>Value of Assets per GSF</b>	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
<b>Facility Condition Index (FCI) Compared to Portfolio</b>	The Facility Condition Index (FCI) of the building overlaid on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
<b>Calculated Remaining Useful Life( C-RUL)</b>	The current number of remaining years a system may be expected to perform in designed service.
<b>Expected Useful Life (EUL)</b>	The total number of years a system can be expected to perform in designed service when new.
<b>Gross Square Footage (GSF)</b>	The total square footage contained within the building for all floors/levels.
<b>Cost per Unit</b>	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
<b>Quantity</b>	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
<b>Units</b>	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
<b>Ancillary Structures</b>	Buildings on site that are typically known as portables, relocatables or temporary buildings.