

2022 School Facilities Inventory Report


MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH Facility Name: MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Secondary Building 1

March 29, 2022





44.809287665525744



Value of Assets/GSF \$91.33








Location Plan - Google Maps

Projected Capital Planning Cash Flow \$1,400,000 \$1,200,000 \$1,000,000 \$800,000 \$600,000 \$400,000 \$200,000 \$0 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 ■ Hard Cost ■ 3% Annual Escalations





(See Last Page for Explanation of Terms)

Page 1 of 5 v2022-03-29



AGENCY OF EDUCATION **2022 School Facilities Inventory Report**

MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH Facility Name:

MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Secondary Building 1

Respondent Information

Date/Time Completed 2021-12-21 - 2:20 PM

Respondent Name Len Smith

Respondent Title Facilities Manager Respondent Email letriclen@maplerun.org

Respondent Phone Number (802) 324-7052

Facility Information

School Type High (9 thru 12)

Building Identification Secondary Building 1

Stories

Building Area

39545 (Gross Square Footage - GSF)

Year Constructed 1860 1997 Year of Last Major Renovation

FCI (Depleted Value) 64.8%

Environmental & Safety Issues

Hazardous Materials Yes

Hazardous (HZD) Materials include Asbestos containing materials (ACM), Science chemicals, custodial floor care supplies

HZD Issues are Major

HZD Issues include Floor tiles and pipe insulation stored science chemicals and sand filter on science drains

Indoor Air Quality (IAQ) Issues Maybe



IAQ Issues include visable signs of mold Mold was found in ajoining wall of E204and 203 it was remediated in 2019 There is sign of water infiltration but no

IAQ Issues are Major

IAQ Issues include Signs of water infiltration no visable signs of mold

Fire or Life/Safety (FL/S) Issues No

FL/S Issues are

Other Risk Factors No

Other Risk Factors include -

Other Risk Factors are -

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Marginal

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

Electrical Capacity Adequate

v2022-03-29 Page 2 of 5







2022 School Facilities Inventory Report

Facility Name:	MAPLE RUN UNII	FIED SE) BEL	LOWS FREE	ACAD	EMY	(ST ALB	ANS)	71	SOUTH	
	MAIN STREET, ST	ALBAI	NS 547	8 - High (9 th	hru 12	2) - Se	condar	y Build	ding	1	
Building Envelope - Roof	,			<u> </u>				,			
	Single-Ply EPDM/TPO/P\	/C Memb	rane								
Covers		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in		20	12	\$11.00 /	SF	for	2,472	SF	=	\$27,187	
	Single-Ply EPDM/TPO/P\										1
Covers		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in		20	18	\$11.00 /	SF	for	2,966	SF	=	\$32,625	
	Asphalt Shingle	EUL	C-RUL	Cost /	[/] Unit		Quantity	Unite		Total Value	1
Covers		30	C-RUL	\$5.50 /		for		Units	_		
Installed in		30	5	\$5.50 /	SF	tor	4,449	SF	=	\$24,468	
Roof 4 is Covers		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	İ
Installed in		-	N/A	- /	-	for	Quantity	Ullits	=	\$0	
Building Envelope - Windows	-	_	IN/A	- /		101	_	_	┸	Ş U	
Primary Window System	Window Wood-Frame										
% of Windows That are this Type		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in		30	21	\$70.00 /		for	6.644		=	\$465,049	
Secondary Window System				, , , , , , , , , , , , , , , , , , ,						Ţ 100/0 10	
% of Windows That are this Type		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in		30	28	\$70.00 /	SF	for	2,847	SF	=	\$199,307	
Services - Elevators		<u>l</u>					·			, ,	
Primary Conveyance/Elevators	Elevator, Hydraulic, Mac	chine/Cor	troller/Ca	ab							
Quantity of Stops	4	EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in	1965	30	-27	\$25,000.00 /	STOP	for	4	STOP	=	\$100,000	\triangle
Secondary Conveyance/Elevators											•
Quantity of Stops	0	EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	C) -	=	\$0	
Services - Plumbing											
Primary Plumbing System							i.	1			l
Area of building served		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		40	15	\$15.00 /	GSF	for	39,545	GSF	=	\$593,175	
Secondary Plumbing System		51.11	C DIII	Cont	/ 11:-		0	11-26-		T-t-ly/-ly-	Ì
Area of building served		EUL	C-RUL	Cost /	[/] Unit	£	Quantity	Units	_	Total Value	
Installed in	-	-	N/A	- /	_	for		_	=	\$0	
Services - Cooling - Central System Primary Central Cooling System	Central Cooling System -	. Chillarls	\ - Air Coo	led							
Area of building served		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in		25	0	\$1,200.00 /		for	· · ·	TON	=	\$18,982	\wedge
Secondary Plumbing System										\$20,502	<u> </u>
Area of building served		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in		25	114	\$1,200.00 /		for	•	TON	=	\$9,491	
Services - Heating - Central System				, , , , , ,						127	
Primary Heating System	Boiler(s)/System - Gas										
Area of building served		EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in	1973	30	-19	\$62.00 /	MBH	for	1,017	MBH	=	\$63,046	\triangle
Secondary Heating System											· - -
Area of building served	0%	EUL	C-RUL	Cost /	[/] Unit		Quantity	Units		Total Value	
Installed in	_	-	N/A	- /	-	for	-	-	=	\$0	
IIIStalieu III											

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

2022 School i demaes	<u> </u>										
Facility Name:	MAPLE RUN UNIF	IED SI	D BEL	LOWS FREE	ACAD	EMY	(ST ALB	ANS)	71	SOUTH	
	MAIN STREET, ST	ALBA	NS 547	8 - High (9 t	hru 12	2) - S	econdar	y Build	ding	1	
Services - HVAC Distribution	<u> </u>					_		,			
Primary HVAC Distribution System	Forced Air System (AHUs	. Ductwo	ork. VAVs)	. 2-Pipe System							
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	-19	\$18.00 /		for	39,545		=	\$711,810	\triangle
Secondary HVAC Distribution System				, 2-Pipe System	031	101	33,313	031		Ψ/11,010	<u> </u>
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	C ROL	\$18.00 /		for	3,955		=	\$71,181	
ervices - Package Systems	1337	30	3	\$18.00 /	USI	101	3,333	USI		\$71,181	
Primary HVAC Package Unit & Splits	Package Units (RTUs)										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		20	-5	\$7,000.00 /		for		TON	=	\$110,726	٨
		20	-5	\$7,000.00 7	TON	101	10	TON		\$110,720	<u> </u>
Secondary HVAC Package Unit & Splits		FIII	C DIII	Cook	/ 11:5:4		O	Lleite		Tatal Malus	
Area of building served		EUL	C-RUL	Cost	/ Unit	C	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
ervices - Fire Suppression	Control of Control of Manie	na Damaii	h/Cananla								
Primary Fire Suppression System					/ 11-15		0	Line Share		Tatal Malas	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	٨
Installed in		40	-9	\$5.00 /	GSF	for	27,682	GSF	=	\$138,408	<u></u>
Secondary Fire Suppression System	Kitchen Hood or Comput	er Cente	er Suppres	sion System							
Area of building served	1 EA	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	2002	20	0	\$10,000.00 /	EA	for	1	EA	=	\$10,000	\wedge
ervices - Fire Alarm System						<u> </u>					
Primary Fire Suppression System	Modern Addressable Fire	e Alarm S	System								
Area of building served	100%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	2020	20	18	\$3.00 /	SF	for	39,545	SF	=	\$118,635	
Secondary Fire Suppression System	-			,		-	, , , , , , , , , , , , , , , , , , ,		-	. ,	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A		_	for	-	-	=	\$0	
ervices - Security Systems				,		1				7.5	
Primary Security & Low Volt System	Security & Low Voltage S	vstems -	- Average								
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		15	-10	\$4.00 /		for	11,864		=	\$47,454	\wedge
Secondary Security & Low Volt System				ψσσ γ		1.0.	11)00.		-	Ψ /	<u> </u>
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A	C03t /	-	for	Qualitity	Offics	=	\$0	
Services - Electrical Distribution/Infrastructure			IN/ A	- /		101				ŞU	
Electrical Distribution/Infrastructure		w/Sub D	anals and	Generator/LIPS -	Mediun	n Dans	itv				
Area of building served		EUL	C-RUL	Cost	/ Unit	Della	Quantity	Units		Total Value	
Installed in			15	4		for	,		-	4	
	1997	40	15	\$22.00 /	ОЗГ	tor	39,545	ОЗГ		\$869,990	
Services - Solar Power (PV) Solar (Electric Generation) Provided	None										
Owned/Maintained by School				Value of Solar P	V Danala						
Quantity of Panels		EUL	C-RUL	Cost			Quantity	Units		Total Value	
Installed in						for	Quantity	Units	=		
	-	-	N/A	- /		TOT	-		_=_	\$0	
incillary Structures	A.1										
Ancillary Structures		5111	6.5111		/		0			T . 11/1	
Total SF of Ancillary Structures		EUL	C-RUL	Cost			Quantity			Total Value	
Installed in		-	N/A	- /	-	for	-	-	=	\$0	
Secondary Ancillary Structures											
Total SF of Secondary Ancillary Structures	0	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	

Additional Comments

The Original Manson (old Hospital) building was built sometime in the 1860's It was converted to a Hospital in 1883 east wing burnt in the 1950's and was not

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: MAPLE RUN UNIFIED SD | BELLOWS FREE ACADEMY (ST ALBANS) | 71 SOUTH

MAIN STREET, ST ALBANS 5478 - High (9 thru 12) - Secondary Building 1

Explanation of Terms

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.

v2022-03-29 Page 5 of 5