




2022 School Facilities Inventory Report

MISSISQUOI VALLEY SCHOOL DISTRICT | HIGHGATE ELEMENTARY SCHOOL | 219 Facility Name: GORE ROAD, HIGHGATE CENTER 5459 - Combination (PreK thru 6) - Secondary

March 29, 2022








Value of Assets/GSF \$109.10

■ Hard Cost ■ 3% Annual Escalations




Site Plan - Google Earth





Facility Condition Index (FCI) Compared to Portfolio



Location Plan - Google Maps

(See Last Page for Explanation of Terms)

v2022-03-29 Page 1 of 5



AGENCY OF EDUCATION

2022 School Facilities Inventory Report

Facility Name: MISSISQUOI VALLEY SCHOOL DISTRICT | HIGHGATE ELEMENTARY SCHOOL | 219

GORE ROAD, HIGHGATE CENTER 5459 - Combination (PreK thru 6) - Secondary

Respondent Information

Date/Time Completed 2021-12-13 - 1:53 PM

Respondent Name Lora McAllister Respondent Title Business Manager

Respondent Email lora.mcallister@mvsdschools.org

Respondent Phone Number (802) 868-2436

Facility Information

School Type Combination (PreK thru 6)

Building Identification Secondary Building

Stories

Building Area 10000 (Gross Square Footage - GSF)

Year Constructed 1941 1992 Year of Last Major Renovation FCI (Depleted Value) 93.0%

Environmental & Safety Issues

Hazardous Materials No

Hazardous (HZD) Materials include

HZD Issues are -

HZD Issues include Indoor Air Quality (IAQ) Issues No

IAQ Issues include -

IAO Issues are -

IAQ Issues include

Fire or Life/Safety (FL/S) Issues Yes

FL/S Issues are No fire suppression system at this time.

Other Risk Factors Yes

Other Risk Factors include Extremely aged facility. Please see below.

Automated ground water pumping system in basement. 30ft roof absence of snow guards. Individual air conditioning units installed in windows seasonally to condition air. Windows are past useful life and unsafe. Door

Other Risk Factors are egresses are not ADA compliant. Entire building is not ADA compliant. Electrical undersized and struggles to handle

load. Roof has only been partially replaced. SD is investigating continued use due to level of necessary investments needed.

Utilities - Adequacy

Handicap Accessibility (ADA) Issues Handicap Accessibility (ADA) Issues Yes ADA Issues are Major All doors not compliant with ADA. There is an elevator system in place that functions fairly well. No outside ramps or access for ADA compliance. Water fountains are not compliant. Handles are not compliant. IT / Internet Service Inadequate Building Wi-Fi Coverage Marginal Cellular Reception Inadequate Water Service Pressure Adequate Natural Gas/Propane Pressure Adequate **Electrical Capacity Inadequate**

v2022-03-29 Page 2 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

| Facility Name: | MISSISQUOI | VALLEY SC | HOOL I | DISTRICT | HIGH | GATE | ELEMEN | NTARY | SCH | HOOL 219 | |
|-------------------------------------|-------------------|------------------|--------|---------------------------------------|------------|-------|-----------|---------|------|-------------|-------------|
| | GORE ROAD | HIGHGATI | CENT | ER 5459 - | Combin | ation | ı (PreK t | hru 6) | - Se | condary | |
| Building Envelope - Roof | | | | | | | (| , | | , | |
| | Asphalt Shingle | | | | | | | | | | |
| Covers | | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | 2020 | 30 | 28 | \$5.5 | 0 / SF | for | 833 | SF | = | \$4,583 | |
| Roof 2 is | Asphalt Shingle | I | | · · · · · · · · · · · · · · · · · · · | | | ı | | | | |
| Covers | 75% | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | 1992 | 30 | 0 | \$5.5 | 0 / SF | for | 2,500 | SF | = | \$13,750 | \wedge |
| Roof 3 is | - | <u> </u> | | | | | I | | | | |
| Covers | 0% | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | |
| Roof 4 is | - | • | | | | | | | | | |
| Covers | 0% | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | |
| Building Envelope - Windows | | | • | | | | • | | | | |
| Primary Window System | | rame | | | | | | | | | |
| % of Windows That are this Type | 100% | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | 1992 | 30 | 0 | \$60.0 | 0 / SF | for | 2,400 | SF | = | \$144,000 | \triangle |
| Secondary Window System | - | | | | | | | | | | |
| % of Windows That are this Type | 0% | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | |
| Services - Elevators | | | | | | | | | | | |
| Primary Conveyance/Elevators | | | | | | | | | | | |
| Quantity of Stops | 4 | EUL | C-RUL | Cos | • | | Quantity | Units | | Total Value | |
| Installed in | | 30 | 0 | \$25,000.0 | 0 / STOP | for | 4 | 1 STOP | = | \$100,000 | \triangle |
| Secondary Conveyance/Elevators | | | | | | | | | | | |
| Quantity of Stops | 0 | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | (|) - | = | \$0 | |
| Services - Plumbing | | | | | | | | | | | |
| Primary Plumbing System | | | | | | | | | _ | | |
| Area of building served | | EUL | C-RUL | Cos | | | Quantity | Units | | Total Value | |
| Installed in | | 40 | 10 | \$7.0 | 0 / GSF | for | 10,000 | GSF | = | \$70,000 | |
| Secondary Plumbing System | | | | | | | | | _ | | |
| Area of building served | | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | |
| Services - Cooling - Central System | | | | | | | | | | | |
| Primary Central Cooling System | | | C BLU | - 6- | | | 0 | I be to | | Tatal Malus | |
| Area of building served | | EUL | C-RUL | Cos | | | Quantity | Units | | Total Value | |
| Installed in | | - | N/A | | - / - | for | - | - | = | \$0 | |
| Secondary Plumbing System | | 5111 | 6 8111 | | . / | | | | | T . 11/ 1 | |
| Area of building served | | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | |
| Services - Heating - Central System | Deiler/e)/Costs | Coo | | | | | | | | | |
| Primary Heating System | | | C BUIL | | -+ / Lluit | | Quantit | l luite | | Total Value | |
| Area of building served | | EUL | C-RUL | Cos | • | | Quantity | Units | | Total Value | ٨ |
| Installed in | | 30 | 0 | \$62.0 | 0 / MBH | for | 286 | MBH | = | \$17,714 | <u> </u> |
| Secondary Heating System | | F1.44 | CDIH | -C | · | | Ougatit | Haite | | Tatal Value | |
| Area of building served | | EUL | C-RUL | Cos | st / Unit | | Quantity | Units | | Total Value | |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | |

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

| Facility Name: | MISSISQUOI VAL | LEY SC | HOOL | DISTRICT | HIGH | GATE | ELEMEN | ITARY | SCH | 100L 219 | |
|---|---------------------------|-------------|------------|-----------------|------------|-------------|---------------|-----------|------|---|----------------|
| | GORE ROAD, HIG | HGATI | E CENT | ER 5459 - | Combi | nation | (PreK t | hru 6) | - Se | condary | |
| Services - HVAC Distribution | , , | | | | | | , | / | | , | |
| Primary HVAC Distribution System | Forced Air System (AHU | s. Ductwo | ork. VAVs |). 2-Pipe Syste | em | | | | | | |
| Area of building served | | EUL | C-RUL | Co | | | Quantity | Units | | Total Value | |
| Installed in | 1992 | 30 | 0 | \$18.0 | 00 / GSF | for | 10,000 | GSF | = | \$180,000 | \wedge |
| Secondary HVAC Distribution System | | | | | • | | -, | | | ,, | <u> </u> |
| Area of building served | | EUL | C-RUL | Co | | | Quantity | Units | | Total Value | l |
| Installed in | | 30 | 0 | \$10.0 | | for | 10,000 | | = | \$100,000 | \wedge |
| Services - Package Systems | 1332 | | | \$20.0 | , 55. | 1.0. | 10,000 | | | ¥100)000 | |
| Primary HVAC Package Unit & Splits | Even Mix of Package Un | its & Split | Systems | | | | | | | | |
| Area of building served | | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | 1992 | 18 | -12 | \$1,900.0 | 00 / TON | for | | TON | = | \$76,000 | \wedge |
| Secondary HVAC Package Unit & Splits | | | | + =/000010 | , , , , , | 1.4. | | | | 7 · 3 /333 | <u> </u> |
| Area of building served | | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | | - | N/A | 331 | - / - | for | - | - | = | \$0 | l |
| Services - Fire Suppression | | | 14/74 | | | 1.0. | | | | , , , , , , , , , , , , , , , , , , , | |
| Primary Fire Suppression System | None | | | | | | | | | | |
| Area of building served | | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | | - | N/A | 20. | - / - | for | Quarterly | - 0111113 | = | \$0 | l |
| | | _ | IN/ A | | - / - | 101 | | | | ŞÜ | |
| Secondary Fire Suppression System | | | | | | | | | | | Ī |
| Area of building served | 0% | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | l |
| Services - Fire Alarm System | | | | | | | | | | | |
| Primary Fire Suppression System | Older type Zoned Syster | n | | | | | | | | | |
| Area of building served | 100% | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | ١. |
| Installed in | 1992 | 20 | -10 | \$1.5 | 0 / GSF | for | 10,000 | GSF | = | \$15,000 | \triangle |
| Secondary Fire Suppression System | - | | | | | | | | | | - |
| Area of building served | 0% | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | l |
| Services - Security Systems | | | | | | | | | | | |
| Primary Security & Low Volt System | Security & Low Voltage | Systems - | Average | | | | | | | | • |
| Area of building served | 100% | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | 1992 | 15 | -15 | \$4.0 | 00 / GSF | for | 10,000 | GSF | = | \$40,000 | \triangle |
| Secondary Security & Low Volt System | - | | | | | | | | | | |
| Area of building served | 0% | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | - | - | N/A | | -/- | for | - | - | = | \$0 | l |
| Services - Electrical Distribution/Infrastructure | | • | | | | • | | | • | | |
| Electrical Distribution/Infrastructure | Main Distribution Panel | w/Sub Pa | anels and | Generator/U | PS - Mediu | ım Dens | ity | | | | |
| Area of building served | 100% | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | 1992 | 40 | 10 | \$22.0 | 00 / GSF | for | 10,000 | GSF | = | \$220,000 | l |
| Services - Solar Power (PV) | | • | | | | • | | | | | |
| Solar (Electric Generation) Provided | None | | | | | | | | | | |
| Owned/Maintained by School | - | | | Value of Sola | ar PV Pane | ls: - | | | | | • |
| Quantity of Panels | 0 | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | - | - | N/A | | - / - | for | - | - | = | \$0 | l |
| Ancillary Structures | | | | | | | | | | | |
| | Relocatable Building - Cl | assroom, | Office - E | | | | | | | | |
| Total SF of Ancillary Structures | 1000 | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | 1994 | 15 | -13 | \$110.0 | 00 / SF | for | 1,000 | SF | = | \$110,000 | \triangle |
| Secondary Ancillary Structures | - | | | | | • | | | | ' | _ _ |
| Total SF of Secondary Ancillary Structures | 0 | EUL | C-RUL | Co | st / Unit | | Quantity | Units | | Total Value | l |
| Installed in | - | - | N/A | | - / - | for | - | _ | = | \$0 | l |
| Additional Comments | | | | 1 | - | | | | | , | |

Additional Comments

Window sills are rotted from water damage. Water has been getting into the building for years. Degree unknow until investigate further.

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: MISSISQUOI VALLEY SCHOOL DISTRICT | HIGHGATE ELEMENTARY SCHOOL | 219

GORE ROAD, HIGHGATE CENTER 5459 - Combination (PreK thru 6) - Secondary

Explanation of Terms

| Projected Capital Planning Cash Flow | The estimated replacement costs of systems as they expire annually. | | | | | | |
|--|---|--|--|--|--|--|--|
| Facility Condition Index (FCI) | The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service. | | | | | | |
| Total Value of Assets | The total estimated replacement cost of all the assets listed in the form. | | | | | | |
| Value of Assets per GSF | The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building. | | | | | | |
| Facility Condition Index (FCI) Compared to Portfolio | The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart. | | | | | | |
| Calculated Remaining Useful Life(C-RUL) | The current number of remaining years a system may be expected to perform in designed service. | | | | | | |
| Expected Useful Life (EUL) | The total number of years a system can be expected to perform in designed service when new. | | | | | | |
| Gross Square Footage (GSF) | The total square footage contained within the building for all floors/levels. | | | | | | |
| Cost per Unit | The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost. | | | | | | |
| Quantity | The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost. | | | | | | |
| Units | The expressed unit of measure for a given system (GSF, EACH, TON, etc). | | | | | | |
| Ancillary Structures | Buildings on site that are typically known as portables, relocatables or temporary buildings. | | | | | | |
| | | | | | | | |

v2022-03-29 Page 5 of 5