2012 DataMaster DMT APM and Software Update

Date	5/31/12	
Agency	Williston PD	
DMT Serial Number	104909	
Technician Name	ALB	
Software Updated	YES	NO
Lock Changed	YES	NO
DPS Property Tag Number	20127	
APM Protocol Performed	YES	NO
Other/Notes	Connections on tower loose will be fixed at APM, I did not have the necessary tools to do it today. Connections seal appropriately, they are just not tightened to the tower. ALB 5/31/12	

DMT UPDATE

DataMater DMT: 104909
Location: Williston PD

2D-Barcode.dll	PASSED
CdrvCEDlgs.dll	PASSED
cdrvcenet.dll	PASSED
CdrvHF32.dll	PASSED
cdrvlibnet.dll	PASSED
CdrvXF32.dll	PASSED
customcontrols.dll	PASSED
dmSecure.xml	PASSED
DMT.exe	PASSED
dmt_utils.dll	PASSED
DmtSecurityUserData.xml	PASSED
DmtUpdater.exe	PASSED
FTDI_SER.DLL	PASSED
ICSharpCode.SharpZipLib.dll	PASSED
interop.prenginecelib.dll	PASSED
MICRO.DLL	PASSED
MicroUtil.dll	PASSED
modem.dll	PASSED
PrintCE.dll	PASSED
state_seal.jpg	PASSED
stateutilities.dll	PASSED
SubClasser.dll	PASSED
TestTypes.xml	PASSED
VDHlogo.jpg	PASSED
VpnComm.dll	PASSED
xmlSettings.bak	PASSED
xmlSettings.xml	PASSED