VERMONT FORENSIC LABORATORY

PO BOX 47
WATERBURY, VERMONT 05676-0047
TEL: 802-244-8788
FAX: 802-241-5557
http://vfl.vermont.gov

DATAMASTER TECHNICAL SUPPORT INQUIRY

Agency/Site: _VPA_____ **DataMaster Serial #:** _103006_____

Date: ___6/1/2015_____ Requestor: _R. Driscoll_____

Instrument Supervisor: _R. Driscoll_____ Phone #: _(802) 241-5817_____

Taken By: _R. Driscoll_____

Problem: _Touch screen is unresponsive._____

Laboratory Response: __Alcohol program staff to bring the instrument back to the Lab for troubleshooting._____

Work Performed: ___Replaced touch screen with new spare. Calibrated new touch screen. Ready to be returned to VPA for installation.

☐ On Site ☒ In-house Attachments: ___0___ pages

Performed By: Robert Driscoll RD _____ Date: ___9/25/15___
Final Review: _____ Date: 9/30/15

Page 1 of 1 RD