at MM 141.30 NB

Culvert 96-3N is located General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems WHERE Year of Crash >= 2012 AND Year of Crash <= 2016

Reporting Agency/ Incident No.	City/Town	Mile Marker	Crash Date	Time	Weather	Contributing Circumstances	Direction of Collision	Number Of Injuries	Number Of Fatalities	Number Of Untimely Deaths	Direction	Road Grou
/TVSP0200/16B100498	Lyndon	140.75	02/16/2016	12:21	[No Weather]		[No Direction of Collision]	0	0	0		SH State Owned
/TVSP0200/12SJ00575	Lyndon	140.90	02/26/2012	21:46	Cloudy	No improper driving	Single Vehicle Crash	0	0	0	N	SH
/TVSP0200/16B104608	Lyndon	140.99	11/01/2016	17:00	Clear	No improper driving	Single Vehicle Crash	1	0	0	N	SH State Owne
VTVSP0200/15B100431	Lyndon	141.00	02/07/2015	08:25	Clear	Driving too fast for conditions	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/12B100806	Lyndon	141.05	03/18/2012	19:03	Clear	No improper driving	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/16B101133	Lyndon	141.10	04/11/2016	23:22	Clear	Fatigued, asleep, Failure to keep in proper lane	Single Vehicle Crash	0	0	0	S	SH State Owne
/TVSP0200/15B100918	Lyndon	141.60	03/28/2015	01:15	Clear	Fatigued, asleep	Single Vehicle Crash	1	0	0	S	SH
/TVSP0200/15B103578	Lyndon	141.78	11/21/2015	16:40	Clear	No improper driving	Single Vehicle Crash	0	0	0	S	SH
VTVSP0200/14B104048	Lyndon	142.00	12/11/2014	18:09	Snow	Driving too fast for conditions	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/14B103996	Lyndon	142.62	12/07/2014	09:22	Clear	Inattention, Failure to keep in proper lane	Single Vehicle Crash	0	0	0	S	SH
VTVSP0200/14B102036	Lyndon	142.65	06/30/2014	12:59	Clear	Failure to keep in proper lane	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/12B101236	Lyndon	UNK	04/22/2012	19:49	Rain	Driving too fast for conditions, Failure to keep in proper lane	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/12B103665	Lyndon	UNK	11/09/2012	00:59	Sleet, Hail (Freezing Rain or Drizzle)	Failure to keep in proper lane, Driving too fast for conditions	Single Vehicle Crash	0	0	0	S	SH
VTVSP0200/13B100036	Lyndon	UNK	01/03/2013	09:45	[No Weather]		[No Direction of Collision]	0	0	0		SH
/TVSP0200/13B100477	Lyndon	UNK	02/08/2013	17:49	[No Weather]		[No Direction of Collision]	0	0	0		SH
VTVSP0200/13B101411	Lyndon	UNK	04/29/2013	22:30	[No Weather]		[No Direction of Collision]	0	0	0		SH
VTVSP0200/13B104128	Lyndon	UNK	11/29/2013	00:30	[No Weather]		[No Direction of Collision]	0	0	0		SH
VTVSP0200/14B100454	Lyndon	UNK	02/10/2014	21:46	[No Weather]		[No Direction of Collision]	0	0	0		Ram pur
VTVSP0200/15B101073	Lyndon	UNK	04/12/2015	13:52	Clear	Failure to keep in proper lane, Fatigued, asleep	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/15B103957	Lyndon	UNK	12/20/2015	07:00	Clear		Single Vehicle Crash	0	0	0	S	SH
VTVSP0200/13B103833	Wheelock	143.00	11/03/2013	18:00	[No Weather]		[No Direction of Collision]	0	0	0		SH
VTVSP0200/13B103983	Wheelock	143.00	11/17/2013	00:03	[No Weather]		[No Direction of Collision]	0	0	0		SH
VTVSP0200/15B100090	Wheelock	143.00	01/09/2015	05:35	Snow	Failure to keep in proper lane	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/15B100247	Wheelock	143.00	01/23/2015	13:19	Cloudy	Driving too fast for conditions	Single Vehicle Crash	0	0	0	N	SH
VTVSP0200/15B101775	Wheelock	143.00	06/23/2015	13:46	[No Weather]		[No Direction of Collision]	0	0	0		SH
			08/22/2015		[No Weather]		[No Direction of Collision]	0	0	0		SH

^{*}Crash occurred prior to the last Highway Improvement Project. This data should not be used in a crash analysis. UNK indicates Mile Marker is Unknown.