



2022 School Facilities Inventory Report

BENNINGTON RUTLAND SU | DORSET SCHOOL | 130 SCHOOL DRIVE, DORSET Facility Name:


5251 - Combination - Main Building

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$4,248,114




-73.06565375864015



Value of Assets/GSF \$70.80




Site Plan - Google Earth





Location Plan - Google Maps

Facility Condition Index (FCI) Compared to Portfolio



(See Last Page for Explanation of Terms)

Page 1 of 5 v2022-03-29



BUREAU

AGENCY OF EDUCATION

2022 School Facilities Inventory Report

Facility Name: BENNINGTON RUTLAND SU | DORSET SCHOOL | 130 SCHOOL DRIVE, DORSET

5251 - Combination - Main Building

Respondent Information

Date/Time Completed 2021-12-17 - 11:18 AM

Respondent Name Derek Chalmers

Respondent Title Assistant to Operations Respondent Email dchalmers@brsu.org

Respondent Phone Number (802) 342-7763

Facility Information

School Type Combination

Building Identification Main Building

Stories

Building Area 60000 (Gross Square Footage - GSF)

Year Constructed 1959
Year of Last Major Renovation 1989
FCI (Depleted Value) 83.0%

Environmental & Safety Issues

Hazardous Materials Yes

Hazardous (HZD) Materials include Asbestos containing materials (ACM)

HZD Issues are Minor

HZD Issues include Asbestos Glue and Tile under the main hallway carpet upstairs.

Indoor Air Quality (IAQ) Issues No

IAQ Issues include -

IAQ Issues are -

IAQ Issues include -

Fire or Life/Safety (FL/S) Issues No

FL/S Issues are Other Risk Factors No

Other Risk Factors include

Other Risk Factors are

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Inadequate

Water Service Pressure Adequate
Natural Gas/Propane Pressure N/A

Electrical Capacity Adequate

Λ

v2022-03-29 Page 2 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

Facility Name:	BENNINGTON RU	JTLANI	SU	DORSET SCHO	00L	130	SCHOO	L DRIV	/E, I	DORSET	
	5251 - Combinati	ion - M	ain Bu	ilding							
Building Envelope - Roof											
Roof 1 is	Single-Ply EPDM/TPO/P	VC Memb	rane								
Covers	100%	EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in	2009	20	7	\$11.00 /	SF	for	30,000	SF	=	\$330,000	
Roof 2 is	-										
Covers	0%	EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Roof 3 is											
Covers		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		-	N/A	- /	-	for	-	-	=	\$0	
Roof 4 is											
Covers		EUL	C-RUL		Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Building Envelope - Windows	Minday, Mand France										
Primary Window System % of Windows That are this Type		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		30	-33	\$70.00 /		for	7.200		=		۸
Secondary Window System		30	-33	\$70.00 /	3F	101	7,200	3F		\$504,000	<u></u>
secondary window system % of Windows That are this Type		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		30	C-ROL	\$70.00 /		for	7,200		=	\$504,000	
Services - Elevators	1336	30	U	\$70.007	31	101	7,200	JI		\$304,000	
Primary Conveyance/Elevators	Elevator, Hydraulic, Mad	chine/Cor	troller/C	ab							
Quantity of Stops		EUL	C-RUL		Unit		Quantity	Units		Total Value	
Installed in		30	23	\$25,000.00 /	STOP	for		STOP	=	\$50,000	
Secondary Conveyance/Elevators	-	ı							-1	. ,	
Quantity of Stops		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	0	-	=	\$0	
Services - Plumbing		<u> </u>									
Primary Plumbing System	Supply & Sanitary, Low I	Density (I	ncludes F	ixtures)							
Area of building served	100%	EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		40	-23	\$7.00 /	GSF	for	60,000	GSF	=	\$420,000	\triangle
Secondary Plumbing System	-										
Area of building served		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	_=_	\$0	
Services - Cooling - Central System		el III /	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \								
Primary Central Cooling System					11-26		0	L Lucitor		Tatal Value	
Area of building served		EUL	C-RUL		Unit	C	Quantity	Units		Total Value	
Installed in		25	24	\$1,200.00 /	TON	for	12	TON	=	\$14,400	
Secondary Plumbing System Area of building served		EUL	C-RUL	Cost /	l loit		Quantity	Units		Total Value	
Installed in		EUL	N/A	- /		for	Qualitity	Ullits	=	\$0	
Services - Heating - Central System	-	_	IN/ A	- /	-	101		_		3 0	
	Boiler(s)/System - Fuel C	nil .									
Area of building served		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		30	18	\$60.00 /		for	1,714		=	\$102,857	
Secondary Heating System			10	Ç00.00 J		.01	2,714			Ų102,037	
Area of building served		EUL	C-RUL	Cost /	Unit		Quantity	Units		Total Value	
Installed in		30	-3	\$60.00 /		for	1,714		=	\$102,857	\bigwedge
mistanca m		- 50		700.00 /		. • '	2,7.27			Ţ102,007	۲:۷

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

Piped System to Unit Ven 50% 2000 HVAC System, Hydronic P	on - Months	ain Buil	ding							
Piped System to Unit Ven 50% 2000 HVAC System, Hydronic P	tilators/ EUL 30	Fan Coils, 2								
50% 2000 HVAC System, Hydronic P	EUL 30		2-Pipe System							
50% 2000 HVAC System, Hydronic P	EUL 30									
2000 HVAC System, Hydronic P	30		Cost	/ Unit		Quantity	Units		Total Value	
		8	\$10.00	•	for	30,000	•	=	\$300,000	
	iping, 2-	Pipe	, ,			,		1	, ,	
	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
1998	40	16	\$5.00		for	30,000		=	\$150,000	
			,		1.01				7 20 3/000	
Split Systems										
5%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
2021	15	14	\$2,000.00	/ TON	for	12	TON	=	\$24,000	
)%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
	-	N/A	-	/ -	for	-	_	=	\$0	
Sprinkler System, Mediur	n Densit	y/Complexi	ity							
2%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
1959	40	-23	\$5.00	/ GSF	for	1,200	GSF	=	\$6,000	Ţ
-	FIII	C-RIII	Cost	/ Unit		Quantity	Units		Total Value	
					for	Quartity	- 011113	-		
		14/74			101				70	
Modern Addressable Fire	Alarm S	vstem								
			Cost	/ Unit		Ouantity	Units		Total Value	
				<i>'</i>	for			=		\wedge
		_	φσ.σσ		1.0.	00,000			Ÿ 130)000	<u> </u>
	EUL	C-RUL	Cost	/ Unit		Ouantity	Units		Total Value	
	-			•	for	_	_	=		
		13/71			1.0.				Ÿ	
Security & Low Voltage Sy	vstems -	Average								
	EUL		Cost	/ Unit		Quantity	Units		Total Value	
2000	15	-7	\$4.00	/ GSF	for		GSF	=		\wedge
				<u>'</u>	-					2.5
)%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
	-	N/A	-	/ -	for	_	-	=		
				<u>'</u>						
Main Distribution Panel v	v/Sub Pa	nels and G	enerator/UPS	- Mediui	n Densi	ty				
100%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
1989	40	7	\$22.00	/ GSF	for	60,000	GSF	=	\$1,320,000	
						<u> </u>				
Solar Power, Photovoltaid	c (PV) Pa	nel								
No		V	alue of Solar P	V Panel	s: \$177,	353				
100	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
2014	20	12	\$85.00	/ SF	for	2,087	SF	=	\$0	
μ										
None										
	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
	-	N/A	- ,	/ -	for	-	-	=	\$0	
									'	
)	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
	-	N/A	- ,	/ -	for	-	-	=	\$0	
	prinkler System, Medium 198 Sprinkler System,	EUL 15 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	EUL C-RUL	EUL C-RUL Cost	EUL	EUL C-RUL Cost / Unit S2,000.00 / TON for	EUL C-RUL Cost Unit Quantity	EUL C-RUL Cost / Unit Quantity Units	EUL C-RUL Cost / Unit Quantity Units	EUL C-RUL Cost Unit Quantity Units Total Value

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: BENNINGTON RUTLAND SU | DORSET SCHOOL | 130 SCHOOL DRIVE, DORSET

5251 - Combination - Main Building

Explanation of Terms

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.

v2022-03-29 Page 5 of 5