




2022 School Facilities Inventory Report

MAPLE RUN UNIFIED SD | ST ALBANS TOWN EDUC CENTER | 169 SOUTH MAIN Facility Name: STREET, ST ALBANS 5478 - Combination (PreK thru 8) - Main Building

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$10,767,736



Relative Asset Values Roof Windows Elevators Plumbing = HVAC Fire Suppression/Alarm Electrical/Security/Solar Ancillary Structures

GPS: 44.80175402699248, -73.08626143096254

Value of Assets/GSF \$89.10






Site Plan - Google Earth



Facility Condition Index (FCI) Compared to Portfolio



Location Plan - Google Maps

(See Last Page for Explanation of Terms)

v2022-03-29 Page 1 of 5





2022 School Facilities Inventory Report

Facility Name: MAPLE RUN UNIFIED SD | ST ALBANS TOWN EDUC CENTER | 169 SOUTH MAIN

STREET, ST ALBANS 5478 - Combination (PreK thru 8) - Main Building

Respondent Information

Date/Time Completed 2021-12-09 - 11:11 AM

Respondent Name Derek Madden
Respondent Title Facilities Manager

Respondent Email dmadden@maplerun.org

Respondent Phone Number (802) 752-2704

Facility Information

School Type Combination (PreK thru 8)

Building Identification Main Building

Stories

Building Area 120850 (Gross Square Footage - GSF)

Year Constructed 1966
Year of Last Major Renovation 1996
FCI (Depleted Value) 80.2%

Environmental & Safety Issues

Hazardous Materials Maybe

Hazardous (HZD) Materials include Other toxic or hazardous substances/building materials (other than Mold)

HZD Issues are Minor

HZD Issues include Currently all known ACM has been abated, possible PCB but currently unknown

Indoor Air Quality (IAQ) Issues No

IAQ Issues include -

IAQ Issues are -

IAQ Issues include -

Fire or Life/Safety (FL/S) Issues No

FL/S Issues are

Other Risk Factors Maybe
Other Risk Factors include snow melt and ice build up on a few eves and sidewalks

Other Risk Factors are The 2 exits on either side of our Kiva have an issue wthsnow melting and forming large icesicles which also coat the exit ramp below. similar issue on the oppisite side of the building less the icesicles.

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Marginal

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

Electrical Capacity Adequate

v2022-03-29 Page 2 of 5

 Λ



AGENCY OF EDUCATION



\$0

2022 School Facilities Inventory Report

Installed in -

Facility Name:	MAPLE RUN UNII	FIED SI) ST A	ALBANS TOV	VN ED	UC C	ENTER	169 9	SOU	TH MAIN	
	STREET, ST ALBAI	NS 547	'8 - Con	nbination (P	reK th	nru 8) - Main	Buildi	ng		
Building Envelope - Roof	, ,			,			,		-		
Roof 1 is	Metal										
Covers		EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	1996	40	14	\$13.00 /	SF	for	60,425	SF	=	\$785,525	1
Roof 2 is	-						•			. ,	
Covers	0%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	l
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	l
Roof 3 is	-										
Covers	0%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Roof 4 is	-										
Covers	0%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	l
Installed in	-	_	N/A	- /	-	for	-	-	=	\$0	l
Building Envelope - Windows			,								
Primary Window System	Window, Metal-Frame										
% of Windows That are this Type	70%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	1996	30	4	\$60.00 /	SF	for	20,303	SF	=	\$1,218,168	1
Secondary Window System	Window, Metal-Frame										
% of Windows That are this Type	30%	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	l
Installed in	1966	30	-26	\$60.00 /	SF	for	8,701	SF	=	\$522,072	\triangle
Services - Elevators											
Primary Conveyance/Elevators		chine/Cor		ab							
Quantity of Stops	2	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	1
Installed in		30	4	\$25,000.00 /	STOP	for	2	STOP	=	\$50,000	l
Secondary Conveyance/Elevators											1
Quantity of Stops	1	EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	
Installed in	1996	25	-1	\$17,000.00 /	EA	for	1	EA	=	\$17,000	
Services - Plumbing											
Primary Plumbing System									_		ı
Area of building served		EUL	C-RUL	Cost /	/ Unit	-	Quantity	Units	4	Total Value	l
Installed in		40	14	\$7.00 /	GSF	for	120,850	GSF	=	\$845,950	J
Secondary Plumbing System									_		ı
Area of building served		EUL	C-RUL	Cost /			Quantity	Units		Total Value	1
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Services - Cooling - Central System											
Primary Central Cooling System		EI II	C DI II	Cook	/ 11:-		0	1 location	_	T-t-IV-b	l
Area of building served		EUL	C-RUL	Cost /	/ Unit		Quantity	Units		Total Value	1
Installed in		-	N/A	- /	-	for	_	_	=	\$0	I
Secondary Plumbing System		E111	C DIII	Cook	/ 11:-		0	1 location		T-t-IV-br-	l
Area of building served		EUL	C-RUL	Cost /			Quantity	Units		Total Value	l
Installed in	-		N/A	- /	-	for	-	-		\$0	
Services - Heating - Central System	Poilor(s)/Custom Callel	Fuel (M)	od/Dellet								
Primary Heating System Area of building served	Boiler(s)/System - Solid I			Cost /	/ Unit		Quantity	Units		Total Value	
<u> </u>		EUL	C-RUL	·		fc					۸
Installed in		25	-1	\$250.00 /	IVIBH	for	3,453	MBH	=	\$863,214	<u> </u>
Secondary Heating System		ELII.	C BLII	Cost	/ Ilnit -		Ouantitu	معنصا		Total Value	
Area of building served	U70	EUL	C-RUL	Cost /	-Unit		Quantity	Units		Total Value	l

v2022-03-29 Page 3 of 5

for



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

2022 School Facilities	s inventory kepor										
Facility Name:	MAPLE RUN UNIFIED SD ST ALBANS TOWN EDUC CENTER 169 SOUTH MAIN										
	STREET, ST ALBAN	NS 547	78 - Con	nbination (I	PreK t	hru 8) - Main	Buildi	ing		
Services - HVAC Distribution	,			,			<u>, </u>				
Primary HVAC Distribution System	Forced Air System (AHUs	, Ductwo	ork, VAVs)	, 2-Pipe System							
Area of building served	70%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	30	4	\$18.00	/ GSF	for	84,595	GSF	=	\$1,522,710	
Secondary HVAC Distribution System	Piped System to Unit Ver	ntilators	/Fan Coils,	2-Pipe System			Į.		-		
Area of building served	30%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	30	4	\$10.00	/ GSF	for	36,255	GSF	=	\$362,550	
Services - Package Systems											
Primary HVAC Package Unit & Splits	Even Mix of Package Uni	ts & Spli	t Systems								
Area of building served	70%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	18	-8	\$1,900.00	/ TON	for	338	TON	=	\$642,922	\triangle
Secondary HVAC Package Unit & Splits	-										
Area of building served	0%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	/ -	for	-	-	=	\$0	
Services - Fire Suppression											
Primary Fire Suppression System	Sprinkler System, Mediu	m Densit	ty/Comple	xity							
Area of building served	100%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	40	14	\$5.00	/ GSF	for	120,850	GSF	=	\$604,250	
Secondary Fire Suppression System	Kitchen Hood or Comput	er Cente	er Suppres	sion System							
Area of building served	•	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		20	-6	\$10,000.00		for	<i>'</i>	EA	=	\$10,000	\wedge
Services - Fire Alarm System	1330	20	U	\$10,000.00 J	LA	101		LA		710,000	<u> </u>
Primary Fire Suppression System	Older type Zoned System) 1									
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		20	-6	\$1.50		for	120,850		=	\$181,275	\bigwedge
Secondary Fire Suppression System			ŭ	Ψ1.50 /		1.0.	120,000			Ψ101)270	<u> </u>
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		_	N/A	- /	/ -	for	-	-	=	\$0	
Services - Security Systems				,		1.5.				, , , , , , , , , , , , , , , , , , , ,	
Primary Security & Low Volt System	Security & Low Voltage S	vstems -	Average								
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		15	-11	\$4.00	/ GSF	for	120,850	GSF	=	\$483,400	\wedge
Secondary Security & Low Volt System	-										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	_	-	N/A	- /		for	-	_	=	\$0	
Services - Electrical Distribution/Infrastructure	!										
Electrical Distribution/Infrastructure	Main Distribution Panel	w/Sub Pa	anels and	Generator/UPS	- Mediur	n Dens	ity				
Area of building served	100%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	40	14	\$22.00	/ GSF	for	120,850	GSF	=	\$2,658,700	
Services - Solar Power (PV)							L				
Solar (Electric Generation) Provided	Solar Power, Photovoltai	c (PV) Pa	anel								
Owned/Maintained by School	No			Value of Solar P	V Panels	s: \$106,	,412				
Quantity of Panels	60	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	2017	20	15	\$85.00	/ SF	for	1,252	SF	=	\$0	
Ancillary Structures											
Ancillary Structures											
Total SF of Ancillary Structures	-	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	<u>-</u>	-	N/A	- /	/ -	for		-	=	\$0	
Secondary Ancillary Structures	-										
Total SF of Secondary Ancillary Structures	0	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	/ -	for	-	-	=	\$0	
Additional Comments				<u>'</u>		-	1				

Additional Comments

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: MAPLE RUN UNIFIED SD | ST ALBANS TOWN EDUC CENTER | 169 SOUTH MAIN

STREET, ST ALBANS 5478 - Combination (PreK thru 8) - Main Building

Explanation of Terms

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.

v2022-03-29 Page 5 of 5