

AGENCY OF EDUCATION




2022 School Facilities Inventory Report


MILL RIVER UNIFIED UNION SD | TINMOUTH ELEMENTARY SCHOOL | 573 ROUTE Facility Name:

140, TINMOUTH 5773 - Combination - Main Building

March 29, 2022








Value of Assets/GSF \$125.51




Site Plan - Google Earth





Location Plan - Google Maps



(See Last Page for Explanation of Terms)

Page 1 of 5 v2022-03-29



BUREAU

AGENCY OF EDUCATION

2022 School Facilities Inventory Report

Facility Name: MILL RIVER UNIFIED UNION SD | TINMOUTH ELEMENTARY SCHOOL | 573 ROUTE

140, TINMOUTH 5773 - Combination - Main Building

Respondent Information

Date/Time Completed 2021-12-21 - 10:40 AM

Respondent Name Gary Marcy

Respondent Title Director of Operations
Respondent Email gmarcy@millriverschools.org

Respondent Phone Number (802) 779-1081

Facility Information

School Type Combination
Building Identification Main Building

Stories

Building Area 1900 (Gross Square Footage - GSF)

Year Constructed 1949
Year of Last Major Renovation 2019
FCI (Depleted Value) 80.3%

Environmental & Safety Issues

Hazardous Materials Yes

Hazardous (HZD) Materials include Asbestos containing materials (ACM), Lead paint

HZD Issues are Major

Suspected ACM throughout in ceiling tiles, floor mastic, floor tile, pipe joints. Suspected lead paint due to age of

facility

Indoor Air Quality (IAQ) Issues No

IAQ Issues include

IAQ Issues are -

IAQ Issues include -Fire or Life/Safety (FL/S) Issues No

FL/S Issues are -

Other Risk Factors No

Other Risk Factors include -

Other Risk Factors are -

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues Yes

ADA Issues are Major

ADA Issues include Bathrooms in this original section, along with hallway doorway width, are not considered to be in accordance with

requirements

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Adequate

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

Electrical Capacity Adequate

v2022-03-29 Page 2 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

		, .											
Facility Name:	MILL RI	VER UNIFIE	D UN	NION SI	D TINM	10U1	TH ELI	EME	NTARY S	SCHO	OL	573 ROUTE	
	140, TIN	MOUTH 5	773 -	Combi	ination -	Mai	n Buil	lding					
Building Envelope - Roof													
Roof 1 is	Slate												
Covers	100%		EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in	1949		75	2	\$70	.00 /	SF	for	1,900) SF	=	\$133,000	
Roof 2 is	-	•			•				l .			•	
Covers	0%		EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	
Roof 3 is	-							•	•		•		
Covers	0%		EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	
Roof 4 is	-	_											
Covers	0%		EUL	C-RUL	С	ost /	Unit		Quantity	Unit	s	Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	
Building Envelope - Windows													
Primary Window System		Vood-Frame			_	,		_					
% of Windows That are this Type			EUL	C-RUL		ost /	Unit		Quantity		S	Total Value	٨
Installed in			30	-43	\$70	.00 /	SF	for	456	SF	=	\$31,920	Ŵ
Secondary Window System		-				,		_					
% of Windows That are this Type			EUL	C-RUL	C	ost /	Unit		Quantity	Unit		Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	
Services - Elevators	Name												
Primary Conveyance/Elevators			FIII	C-RUL		ost /	llnit		Oughtitu	Unit	c	Total Value	
Quantity of Stops Installed in			EUL		l	ost /	Unit	for	Quantity		5	Total Value	
Secondary Conveyance/Elevators				N/A		- /	-	101		0 -		\$0	
Quantity of Stops			EUL	C-RUL		ost /	Unit		Quantity	Unit	c	Total Value	
Installed in			LUL	N/A		- /		for		0 -	э =	\$0	
Services - Plumbing				IN/A				1101		0 -		Ç	
Primary Plumbing System	Supply & S	anitary. Low De	ensity (I	ncludes F	ixtures)								
Area of building served			EUL	C-RUL		ost /	Unit		Quantity	Unit	s	Total Value	
Installed in			40	-33		.00 /	GSF	for		GSF	=	\$13,300	\bigwedge
Secondary Plumbing System		Ļ			Ψ,	,			2,500			\$10,000	<u> </u>
Area of building served			EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in			-	N/A		- ,	_	for	-	_	=	\$0	
Services - Cooling - Central System												1 -	
Primary Central Cooling System	None												
Area of building served	0%		EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	
Secondary Plumbing System	-							•	•		•		
Area of building served	0%		EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	
Services - Heating - Central System													
Primary Heating System		ystem - Fuel O <u>i</u> l											
Area of building served			EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in			30	27	\$60	.00 /	MBH	for	54	MBH	=	\$3,257	
Secondary Heating System		_											
Area of building served			EUL	C-RUL	С	ost /	Unit		Quantity	Unit	S	Total Value	
Installed in	-		-	N/A		- /	-	for	-	-	=	\$0	

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-								
Facility Name:	MILL RIVER UNIF	ED UI	NION SE	TINMOUT	TH ELEME	NTARY S	SCHOO	L	573 ROUTE	
	140, TINMOUTH	5773 -	Combi	nation - Mai	n Buildin	g				
Services - HVAC Distribution						0				
Primary HVAC Distribution System	HVAC System, Hydronic	Piping, 2	-Pipe							
Area of building served	100%	EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	1949	40	-33	\$5.00 /	SF for	1,900) SF	=	\$9,500	\triangle
Secondary HVAC Distribution System	-									
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	- for	-	-	=	\$0	
Services - Package Systems										
Primary HVAC Package Unit & Splits	None									
Area of building served	0%	EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	- for	-	-	=	\$0	
Secondary HVAC Package Unit & Splits	-	•			•	•				
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	- for	-	-	=	\$0	
Services - Fire Suppression										
Primary Fire Suppression System	Sprinkler System, Mediu	m Densi	ty/Comple:	kity						
Area of building served	10%	EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	1988	40	6	\$5.00 /	GSF for	190	GSF	=	\$950	
Secondary Fire Suppression System	-									
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in		-	N/A	- /		· ·	011103	=	\$0	
Services - Fire Alarm System			IN/A		- 101				ŞU	
Primary Fire Suppression System	Older type Zoned System	า								
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in		20	-14	\$1.50 /	GSF for		GSF		\$2,850	\triangle
Secondary Fire Suppression System		20	- '	71.50 /	101	1,500	- 001	ш	<i>\$2,030</i>	Z: <u>\</u>
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in		_	N/A	- /		· ·	-	=	\$0	
Services - Security Systems				<u>'</u>	1.4.			H	7.0	
Primary Security & Low Volt System	Security & Low Voltage S	systems -	- Average							
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	2020	15	13	\$4.00 /	GSF for	475	GSF	=	\$1,900	
Secondary Security & Low Volt System	-	!				+				
Area of building served		EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in		_	N/A	- /		_	-	=	\$0	
Services - Electrical Distribution/Infrastructure	1			•						
Electrical Distribution/Infrastructure		w/Sub P	anels and (Generator/UPS - I	Medium Den	sity				
Area of building served		EUL	C-RUL			Quantity	Units		Total Value	
Installed in	2019	40	37	\$22.00 /	GSF for	1,900	GSF	=	\$41,800	
Services - Solar Power (PV)				· · ·						
Solar (Electric Generation) Provided	None									
Owned/Maintained by School	-			Value of Solar PV	/ Panels: -					
Quantity of Panels	0	EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	- for	-	-	=	\$0	
Ancillary Structures						•				
Ancillary Structures	None									
Total SF of Ancillary Structures	-	EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	- for			=	\$0	
Secondary Ancillary Structures	-									
Total SF of Secondary Ancillary Structures	0	EUL	C-RUL	Cost /	Unit	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	- for	-	-		\$0	

Additional Comments

This form is for the original 1868 building and the 1949 addition, which are of similar construction. A separate form will be submitted associated with the 1988,

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: MILL RIVER UNIFIED UNION SD | TINMOUTH ELEMENTARY SCHOOL | 573 ROUTE

140, TINMOUTH 5773 - Combination - Main Building

Explanation of Terms

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.

v2022-03-29 Page 5 of 5