




**2022 School Facilities Inventory Report** 

MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | CAMELS HUMP MIDDLE Facility Name: SCHOOL | 173 SCHOOL STREET, RICHMOND 5477 - Middle (5 thru 8) - Main

March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) \$6,004,371




Relative Asset Values Roof Windows Elevators Plumbing = HVAC Fire Suppression/Alarm Electrical/Security/Solar Ancillary Structures


GPS: 44.41409418924223, -72.99476331388146

Value of Assets/GSF \$69.02






Site Plan - Google Earth



Facility Condition Index (FCI) Compared to Portfolio



Location Plan - Google Maps

(See Last Page for Explanation of Terms)

v2022-03-29 Page 1 of 5





# **2022 School Facilities Inventory Report**

Facility Name: MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | CAMELS HUMP MIDDLE

SCHOOL | 173 SCHOOL STREET, RICHMOND 5477 - Middle (5 thru 8) - Main

**Respondent Information** 

Date/Time Completed 2021-12-16 - 7:37 AM

Respondent Name Phil Graff

Respondent Title District Facilities Director Respondent Email phil.graff@mmuusd.org

Respondent Phone Number (802) 858-1635

**Facility Information** 

School Type Middle (5 thru 8)

**Building Identification Main Building** 

**Stories** 

**Building Area** 87000 (Gross Square Footage - GSF)

1970 Year Constructed Year of Last Major Renovation N/A 97.2%

FCI (Depleted Value)

**Environmental & Safety Issues** 

Hazardous Materials Yes

Hazardous (HZD) Materials include Asbestos containing materials (ACM)

HZD Issues are Minor

HZD Issues include 12x12 floor tiles

Indoor Air Quality (IAQ) Issues Yes

IAQ Issues include Insufficient Air Change Ratio, Humidity (Too Low or Too High)

IAQ Issues are Major

IAQ Issues include Humidity is a concern for many areas of the building. Proper air ventilation and air exchange rates are hard to verify for the age of equipment and the building.

Fire or Life/Safety (FL/S) Issues Maybe

FL/S Issues are

Other Risk Factors No

Other Risk Factors include -

Other Risk Factors are -

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

**Utilities - Adequacy** 

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Adequate

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

**Electrical Capacity Adequate** 

v2022-03-29 Page 2 of 5



# AGENCY OF EDUCATION



## **2022 School Facilities Inventory Report**

Facility Name:	MT MANSFIELD	UNIFIE	D UNIO	N SCHOOL I	DISTRI	CT	CAMELS	S HUM	IP N	/IIDDLE	
	SCHOOL   173 SC	CHOOL	STREET	, RICHMON	D 547	7 - N	liddle (5	thru 8	8) -	Main	
uilding Envelope - Roof				,			<u> </u>				
	Single-Ply EPDM/TPO/P	VC Memb	rane								
Covers	85%	EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in	2005	20	3	\$11.00 /	SF	for	36,975	SF	=	\$406,725	
Roof 2 is	Single-Ply EPDM/TPO/P	VC Memb	rane								
Covers	15%	EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in	1990	20	-12	\$11.00 /	SF	for	6,525	SF	=	\$71,775	/
Roof 3 is	-										
Covers	0%	EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Roof 4 is	-										
Covers	0%	EUL	C-RUL	Cost /	′ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Building Envelope - Windows											
Primary Window System											
% of Windows That are this Type	100%	EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in	1970	30	-22	\$60.00 /	SF	for	20,880	SF	=	\$1,252,800	
Secondary Window System											
% of Windows That are this Type	0%	EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	
Services - Elevators											
Primary Conveyance/Elevators											
Quantity of Stops		EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in		30	28	\$25,000.00 /	STOP	for	2	STOP	=	\$50,000	
Secondary Conveyance/Elevators									_		
Quantity of Stops		EUL	C-RUL	Cost /	' Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for		) -	=	\$0	
Services - Plumbing		- 1: (1									
Primary Plumbing System							ā .ii				
Area of building served		EUL	C-RUL	Cost /	' Unit		Quantity	Units	4	Total Value	,
Installed in		40	-12	\$7.00 /	GSF	for	87,000	GSF	=	\$609,000	Z!
Secondary Plumbing System							ā .ii	1			
Area of building served		EUL	C-RUL		' Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	-	for	-	-	=	\$0	_
Services - Cooling - Central System	Nana										
Primary Central Cooling System Area of building served		FIII	C-RUL	Cost	' Unit		Quantity	llnita		Total Value	
_		EUL		Cost /		fau	Quantity	Units		Total Value	
Installed in		-	N/A	- /	-	for	-	-	=	\$0	
Secondary Plumbing System		5111	C DIII	Cont	/ 11-24		0	Haite		Tatal Malas	
Area of building served		EUL	C-RUL	Cost /		C	Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	_	for		_	=	\$0	
ervices - Heating - Central System	Poilor(s)/Custom Co										
Primary Heating System		ELII.	СВШ	Cost	/ Ilnit -		Ouantit	مادادا		Total Value	
Area of building served		EUL	C-RUL	Cost /	Unit	£4	Quantity	Units	#	Total Value	,
Installed in		30	-2	\$62.00 /	MBH	for	1,243	MBH	=	\$77,057	Z
Secondary Heating System				Cont	/		Ougatit	Haita		Total Value	
Area of building served		EUL	C-RUL	Cost /		£ .	Quantity	Units		Total Value	,
Installed in	1993	25	-4	\$250.00 /	MBH	for	1,243	MBH	=	\$310,714	- /i

v2022-03-29 Page 3 of 5



# AGENCY OF EDUCATION



## **2022 School Facilities Inventory Report**

MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | CAMELS HUMP MIDDLE Facility Name: SCHOOL | 173 SCHOOL STREET, RICHMOND 5477 - Middle (5 thru 8) - Main **Services - HVAC Distribution** Primary HVAC Distribution System Piped System to Unit Ventilators/Fan Coils, 2-Pipe System Area of building served 80% EUL C-RUL Cost / Unit Quantity Units Installed in 1970 \$10.00 / GSF for 69,600 GSF \$696,000 Secondary HVAC Distribution System Forced Air System (AHUs, Ductwork, VAVs), 2-Pipe System Area of building served 20% C-RUL Cost / Unit Quantity Units Total Value Installed in 1993 30 \$18.00 / GSF for 17,400 GSF \$313,200 Services - Package Systems Primary HVAC Package Unit & Splits None Area of building served 0% Installed in for Secondary HVAC Package Unit & Splits -Area of building served 0% C-RUL Cost / Unit Quantity Units Installed in for **Services - Fire Suppression** Primary Fire Suppression System Sprinkler System, Medium Density/Complexity Area of building served 10% C-RUL Cost / Unit Quantity Units Installed in 1970 \$5.00 / GSF GSF \$43,500 for 8.700 Secondary Fire Suppression System Kitchen Hood or Computer Center Suppression System Area of building served 1 EA C-RUL Cost / Unit Quantity Units Total Value Installed in 2014 \$10,000.00 / EA \$10,000 **Services - Fire Alarm System** Primary Fire Suppression System Older type Zoned System Area of building served 100% C-RUL Cost / Unit Quantity Units Total Value Installed in 1970 \$1.50 / GSF 87.000 GSF \$130.500 Secondary Fire Suppression System Area of building served 0% C-RUL Cost / Unit Quantity Units Total Value Installed in -**Services - Security Systems** Primary Security & Low Volt System Security & Low Voltage Systems - Average Area of building served 20% Cost / Unit Quantity Units Installed in 2017 \$4.00 / GSF 17,400 GSF Secondary Security & Low Volt System C-RUL Area of building served 0% Installed in Services - Electrical Distribution/Infrastructure Electrical Distribution/Infrastructure Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density Area of building served 100% Installed in 1970 \$22.00 / GSF 87,000 GSF \$1,914,000 Services - Solar Power (PV) Solar (Electric Generation) Provided Solar Power, Photovoltaic (PV) Panel Owned/Maintained by School No Value of Solar PV Panels: \$611,866 Quantity of Panels 345 Cost / Unit Quantity Units Installed in 2009 \$85.00 / SF 20 7.198 **Ancillary Structures** Ancillary Structures Relocatable Building - Classroom/Office - Basic/Portable Total SF of Ancillary Structures 450 C-RUL Cost / Unit Quantity Units Installed in 1993 \$110.00 / SF 450 Secondary Ancillary Structures C-RUL Total SF of Secondary Ancillary Structures 0 Cost / Unit Quantity Units Installed in for **Additional Comments** 

v2022-03-29 Page 4 of 5





#### **2022 School Facilities Inventory Report**

Facility Name: MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | CAMELS HUMP MIDDLE

SCHOOL | 173 SCHOOL STREET, RICHMOND 5477 - Middle (5 thru 8) - Main

# **Explanation of Terms**

Explanation of Terms								
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.							
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.							
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.							
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.							
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.							
Calculated Remaining Useful Life( C-RUL)	The current number of remaining years a system may be expected to perform in designed service.							
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.							
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.							
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.							
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.							
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).							
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.							

v2022-03-29 Page 5 of 5