



2022 School Facilities Inventory Report


MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | MT MANSFIELD UHS | 211 Facility Name: BROWNS TRACE RD, JERICHO 5465 - High (9 thru 12) - Main Building

March 29, 2022






GPS: 44.48598771856627, -72.96142047216107



Value of Assets/GSF \$85.15




Site Plan - Google Earth





Location Plan - Google Maps



(See Last Page for Explanation of Terms)

v2022-03-29 Page 1 of 5





2022 School Facilities Inventory Report

Facility Name: MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | MT MANSFIELD UHS | 211

BROWNS TRACE RD, JERICHO 5465 - High (9 thru 12) - Main Building

Respondent Information

Date/Time Completed 2021-12-07 - 2:23 PM

Respondent Name Phil Graff

Respondent Title District Facilities Director Respondent Email Phil.Graff@mmuusd.org

Respondent Phone Number (802) 858-1635

Facility Information

School Type High (9 thru 12)

Building Identification Main Building

Stories

1

Building Area 165000 (Gross Square Footage - GSF)

Year Constructed 1967

Year of Last Major Renovation N/A
FCI (Depleted Value) 97.4%

Environmental & Safety Issues

Hazardous Materials Yes

 \wedge

Hazardous (HZD) Materials include Asbestos containing materials (ACM)

HZD Issues are Minor

HZD Issues include Asbestos is mainly in old plumbing insulation joint material

Indoor Air Quality (IAQ) Issues Yes

Λ

IAQ Issues include Insufficient Air Change Ratio, Perceptible Odors, Humidity (Too Low or Too High)

IAQ Issues are Major

The level of humidity in the building can reach very high levels. Slips and falls have occured due to wet flooring. The IAQ Issues include rate of air exchange can vary depending on the location and age of the building system. Work has been done to provide the necessary air exchanges for concerns. This may require manually opening dampers.

Fire or Life/Safety (FL/S) Issues Maybe

FL/S Issues are

Other Risk Factors No

Other Risk Factors include -

Other Risk Factors are

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Adequate

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

Electrical Capacity Adequate

v2022-03-29 Page 2 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

Facility Name:	MT MANSFIELD U	JNIFIE	D UNIO	N SCHOOL	DISTR	ICT	MT MA	NSFIE	LD (JHS 211	
	BROWNS TRACE									·	
Building Envelope - Roof				<u> </u>	•	<u> </u>			Ť		
	Single-Ply EPDM/TPO/PV	'C Memb	rane								
Covers	85%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	2000	20	-2	\$11.00	/ SF	for	140,250	SF	=	\$1,542,750	\triangle
Roof 2 is	Metal										
Covers	15%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	40	14	\$13.00	/ SF	for	24,750	SF	=	\$321,750	
Roof 3 is	-										
Covers	0%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	-	/ -	for	-	-	=	\$0	
Roof 4 is	-										
Covers		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	-	/ -	for	-	-	=	\$0	
Building Envelope - Windows											
Primary Window System						_					
% of Windows That are this Type		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	٨
Installed in		30	-26	\$60.00	/ SF	for	39,600	SF	=	\$2,376,000	<u></u>
Secondary Window System			0.5111		/	_					
% of Windows That are this Type		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	-	/ -	for	-	-	=	\$0	
Services - Elevators	Mana										
Primary Conveyance/Elevators		ELU.	C DIII	Cash	/ 11mit		O	l linita		Tatal Value	
Quantity of Stops		EUL	C-RUL	Cost	/ Unit	£	Quantity			Total Value	
Installed in		-	N/A		/ -	for	() -	=	\$0	
Secondary Conveyance/Elevators Quantity of Stops		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		EUL	N/A		<u> </u>	for) -	=	†0tal value \$0	
Services - Plumbing	<u>-</u>	_	N/A		/ -	101) -	=	\$0	
Primary Plumbing System	Supply & Sanitary Media	ım Dansi	ty (Includ	ac Fivturac)							
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		40	-16	\$15.00	•	for	165,000		1_	\$2,475,000	Λ
Secondary Plumbing System		40	-10	713.00	/ 031	101	103,000	031	J <u>-</u> J	\$2,473,000	<u> </u>
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A		/ -	for	-	-	=	\$0	
Services - Cooling - Central System			14/74		<u>, </u>	1101			_	ŢŪ.	
Primary Central Cooling System	None										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		_	N/A	-	/ -	for	_	_	=	\$0	
Secondary Plumbing System		l	,								
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A		/ -	for	-	-	=	\$0	
Services - Heating - Central System											
	Boiler(s)/System - Solid F	uel (Woo	od/Pellet)								
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1996	25	-1	\$250.00	/ MBH	for	4,714	MBH	=	\$1,178,571	\wedge
Secondary Heating System		il								<u> </u>	
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	1967	30	-25	\$60.00	/ MBH	for	4.714	MBH	=	\$282,857	\wedge

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | MT MANSFIELD UHS | 211 Facility Name: BROWNS TRACE RD, JERICHO 5465 - High (9 thru 12) - Main Building **Services - HVAC Distribution** Primary HVAC Distribution System Piped System to Unit Ventilators/Fan Coils, 2-Pipe System Area of building served 95% EUL C-RUL Cost / Unit Quantity Units Installed in 1967 \$10.00 / GSF for 156,750 GSF \$1,567,500 Secondary HVAC Distribution System HVAC System, Hydronic Piping, 2-Pipe Area of building served 5% C-RUL Cost / Unit Quantity Units Total Value Installed in 1967 40 \$5.00 / SF for 8,250 SF \$41,250 Services - Package Systems Primary HVAC Package Unit & Splits None Area of building served 0% Installed in for Secondary HVAC Package Unit & Splits -Area of building served 0% C-RUL Cost / Unit Quantity Units Total Value Installed in for **Services - Fire Suppression** Primary Fire Suppression System Sprinkler System, Medium Density/Complexity Area of building served 10% C-RUL Cost / Unit Quantity Units Installed in 1967 \$5.00 / GSF 16,500 GSF \$82,500 for Secondary Fire Suppression System Kitchen Hood or Computer Center Suppression System Area of building served 1 EA C-RUL Cost / Unit Quantity Units Total Value Installed in 2017 \$10,000.00 / EA \$10,000 **Services - Fire Alarm System** Primary Fire Suppression System Older type Zoned System Area of building served 100% FUI C-RUL Cost / Unit Quantity Units Total Value Installed in 2014 20 \$1.50 / GSF 165.000 GSF for Secondary Fire Suppression System C-RUL Area of building served 0% Cost / Unit Quantity Units Total Value Installed in -**Services - Security Systems** Primary Security & Low Volt System Security & Low Voltage Systems - Average Area of building served 20% C-RUL Cost / Unit Quantity Units Installed in 2018 15 \$4.00 / GSF 33,000 GSF \$132,000 Secondary Security & Low Volt System C-RUL Area of building served 0% Installed in Services - Electrical Distribution/Infrastructure Electrical Distribution/Infrastructure Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density Area of building served 100% Installed in 1967 \$22.00 / GSF 165,000 GSF \$3,630,000 Services - Solar Power (PV) Solar (Electric Generation) Provided None Owned/Maintained by School -Value of Solar PV Panels: C-RUL Quantity Units Quantity of Panels 0 Cost / Unit Installed in for **Ancillary Structures** Ancillary Structures Relocatable Building - Classroom/Office - Basic/Portable Total SF of Ancillary Structures 200 Cost / Unit Quantity Units Installed in 2001 \$110.00 / SF for 200 \$22,000 Secondary Ancillary Structures Relocatable Building - Classroom/Office - Basic/Portable Total SF of Secondary Ancillary Structures 1280 Quantity Units Installed in 2006 \$110.00 / 1,280 \$140,800

Additional Comments

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: MT MANSFIELD UNIFIED UNION SCHOOL DISTRICT | MT MANSFIELD UHS | 211

BROWNS TRACE RD, JERICHO 5465 - High (9 thru 12) - Main Building

Explanation of Terms

Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.						
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.						
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.						
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.						
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.						
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.						
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.						
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.						
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.						
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.						
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).						
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.						

v2022-03-29 Page 5 of 5