

# MILLER CONSTRUCTION, INC.

P.O. BOX 86 ASCUTNEY BLVD WINDSOR, VERMONT 05089-0086  
 TELEPHONE (802) 674-5525 / FAX (802) 674-5245

## TRANSMITTAL

TO: Jennifer Fitch, PE Project Manager Vermont Agency of Transportation	DATE	PROJECT NO.
	9/23/2014	Brookfield BRF FLBR (2)

XX WE ENCLOSE THE FOLLOWING: \_\_\_\_\_ UNDER SEPARATE COVER WE ARE SENDING THE FOLLOWING

COPIES	NUMBER	DESCRIPTION	CODE
1		FRP Fabrication NCR 9 - Pontoon 3 Tape Inclusion	H

CODE:

A FOR INITIAL APPROVAL

B FOR FINAL APPROVAL

C APPROVED AS NOTED-RESUBMISSION REQUIRED

D APPROVED AS NOTED-RESUBMISSION NOT REQUIRED

E DISAPPROVED-RESUBMIT

F QUOTATION REQUESTED

G APPROVED

H FOR APPROVAL

I AS REQUESTED OR REQUIRED


J FOR USE IN ERECTION

K LETTER FOLLOWS

L FOR FIELD CHECK

M FOR YOUR USE

BY: Paul J. Anthony



**KENWAY  
CORPORATION**

681 Riverside Drive  
Augusta, Maine  
04330-9714  
(207) 622-6229  
Fax (207) 622-6611  
info@kenway.com  
www.kenway.com

September 22, 2014


Mr. Paul Holloway  
Miller Construction, Inc  
PO Box 86  
Windsor, VT 05089

**Brookfield BRF FLBR (2)**

Dear Mr. Holloway:

Background

On September 18, Kenway identified an inclusion in the exterior of Pontoon 3 just behind the C-veil layer, which turned out to be a narrow strip of tape. The C-veil and tape were carefully removed from the laminate by cutting around the perimeter of the inclusion.



Summary

Kenway plans to clean the area and spread a layer of thickened resin over the structural fiber to restore the exterior surface and bring it flush to the surrounding mold surface.

Sincerely,

Jacob Marquis, P.E.  
Senior Project Engineer