



DMT Technical Support Inquiry

DMT Serial #: 100146
Date Initiated: 12/18/2025
Initiated By: BMS

Problem:

Checking on fuse that was secured by the DMT supervisor see TSI dated 11/03/2025.

Work Performed:

Fuse was resecured into place using electrical tape. VFL will continue to monitor.

Performed On-Site ☒
Performed In-House ☐

Performed By:	<u>Brittany Shumway</u> <i>Brittany Shumway</i>	Date:	<u>12/19/2025</u>
Technical Reviewer:	<u><i>[Signature]</i></u>	Date:	<u>12/19/2025</u>
Administrative Reviewer:	<u><i>[Signature]</i></u>	Date:	<u>12/26/25</u>
Director Reviewer:	<u><i>[Signature]</i></u>	Date:	<u>12/30/2025</u>