

DMT Software Upgrade *Request*  
November 10, 2008

1. Change the words "Internal Standard" to "Calibration Check" on all tests.
2. When running a stand-alone Accuracy and Precision check or Diagnostic check, fill in all date fields.
3. Add a Simulator Vapor check to the Annual Preventative Maintenance protocol during the sample acceptance test (after Internal standard, before "please blow" just like a regular breath test).
4. Print the solution lot number on the calibration report.
5. When performing a Multiple Breath Test sequence, the screen still displays Mouth Alcohol Test, it should display Multiple Breath Test.
6. A stand-alone Accuracy and Precision check should not change the reported simulator lot number or concentration.
7. Erasing data glitch. If you press RUN a second time and cancel out, the subject information is lost. This should not happen.
8. Sometimes a blank test will report a result of .001 or .002. Anything less than 0.003 should be reported as 0.000.
9. Add DMV and Fish & Wildlife to the Agency list.
10. On the DUI data entry screen change "stop time" to "Operation Time".
11. Concentration is misspelled on the screen during the accuracy and precision check of the installation protocol.
12. If a protocol has a mandatory 30 minute timer (APM, Install) and the protocol fails, have option to NOT redo 30 minutes.