

## Thomson, Sean

---

**From:** King, Peter G  
**Sent:** Saturday, March 31, 2012 8:07 PM  
**To:** Bolduc, Amanda  
**Cc:** Fortin, Allen  
**Subject:** Shelburne PD Datamaster Down

**Importance:** High

Hi Amanda,

Shelburne's Datsamaster will not operate. It appears that on the temperature probe disconnect's main wire to the sample bottle, is loose and not making a proper contact.

The Ambient Temp display shows varying temps while operating. 33.9 to 34.0 C

If you move the wire slightly, the temp reading disappears. I checked the connection for proper connecting, it appear to be properly connected.

Also, we are out of Datamaster solution & Blood Kits. Both types.

Peter King  
Shelburne Police  
985-8051