



VERMONT FORENSIC LABORATORY

PO BOX 47
WATERBURY, VERMONT 05676-0047
TEL: 802-244-8788
FAX: 802-241-5557
<http://vfl.vermont.gov>

DATAMASTER TECHNICAL SUPPORT INQUIRY

Agency/Site: <u>Colchester PD</u>	DataMaster Serial #: <u>100157</u>
Date: <u>12/22/2014</u>	Requestor: <u>Jack Lehneman</u>
Instrument Supervisor: <u>Jack Lehneman</u>	Phone #: <u>(802) 264-5555</u>
Taken By: <u>Robert Driscoll</u>	
Problem: Simulator paddle is broken.	
Laboratory Response: DMT Technician to replace simulator paddle.	
Work Performed: Replaced simulator paddle and performed simulator solution change protocol.	
<input checked="" type="checkbox"/> On Site <input type="checkbox"/> In-house	Attachments: <u>1</u> page(s)
Performed By: <u>Robert Driscoll RD</u>	Date: <u>12/23/2014</u>
Final Review: <u>[Signature]</u>	Date: <u>12/31/2014</u>

SOLUTION CHANGE

DataMaster DMT: 100157
Location: Colchester PD
Date: 12/23/2014
Performed by: ROBERT DRISCOLL



Accuracy and Precision Check

Concentration = 0.099 g/210L
Lot # = 14-14-100
Range = 0.094 - 0.104
Average = 0.097 g/210L
Std Dev = 0.0000

Simulator Temperature: 34°C

Performed by *Rob RD*

Date 12/23/2014