

**State of Vermont**  
**PDD/Structures Design Section**  
One National Life Drive  
Montpelier, VT 05633-5001  
[www.aot.state.vt.us](http://www.aot.state.vt.us)

[phone] 802-828-2621  
[fax] 802-828-3566  
[ttd] 800-253-019

*Agency of Transportation*

**September 30, 2014**

Paul Holloway  
Miller Construction, Inc.  
PO Box 86  
3103 US Route 5 South  
Windsor, VT 05089-0086

**Project Name: Brookfield BRFLBR(2)**  
**Structure Identification: VT 65 Bridge #2 over Sunset Lake**

**RE: Item 900.645, "Special Provision (Fiber Reinforced Polymer pontoons)"**  
**NCR 11 – FRP Pontoon Stiffener Plate Alignment**

Mr. Holloway –

As described in the attached letter, the corrective procedures proposed by Kenway for accommodating the misplaced top plate stiffener in part 7b has been reviewed by T.Y. Lin International (Design Engineer of Record) and is found to be acceptable. Please take note of recommended orientation of Pontoon 7 in the overall assembly of consecutive rafts.

Please feel free to contact me with any additional questions or clarifications.

Sincerely,



Jennifer M.V. Fitch, P.E.  
Project Manager

Attachments

cc:  Resident Engineer – Sandra Schmitt  
 Design Engineer – Josh Olund  
 File