



Photo 01: Looking west, view shows east elevation



Photo 02: Looking east (up)





Photo 03: Looking northwest



Photo 04: Looking east





Photo 05: Looking northeast, view shows center section in frame center



Photo 06: Looking northeast, view shows eyebrow dormer on west hip of center section





Photo 07: Looking east, view shows cupola on center section ridge, Pearson Hall at center background



Photo 08: Looking south, view shows stair hall overrun accessing the center section third floor





Photo 09: Looking west across Le Chateau Quadrangle toward Battell Hall



Photo 10: Looking north, Le Chateau building in the background center, Wright building at right





Photo 11: Looking west, view shows center section east elevation



Photo 12: Looking west, view shows center section main entrance



Photo 13: Looking west, view shows center section marble entrance stairs



Photo 14: Looking west, view shows center section entrance sidelights





Photo 15: Looking west, view shows south section east elevation



Photo 16: Looking northwest, view shows south section south and east elevations





Photo 17: Looking northwest, view shows south section connection to center section



Photo 18: Looking southwest, view shows perimeter concrete foundation





Photo 19: Looking west, view shows south section centered entrance projection



Photo 20: Looking west, vies shows south section marble entrance stairs





Photo 21: Looking west, view shows north section east elevation



Photo 22: Looking southwest, view shows south section east and north elevations





Photo23x: Looking west, view shows north section entrance projection



Photo 24: Looking west, view shows north section entrance





Photo 25: Looking south, view shows north section north elevation



Photo 26: Looking southeast, view shows north section north and west elevations





Photo 27: Looking south, view shows limestone cladding detail on north section upper wall and replacement vinyl windows



Photo 28: Looking south, view shows concrete foundation, limestone cladding detail on north section lower wall, and replacement vinyl windows





Photo 29: Looking southeast showing the blocks extending westward from the east blocks



Photo 30: Looking east, view shows west elevation of north section





Photo 31: Looking northeast, view shows west and south elevations of north section



Photo 32: Looking northeast, view shows south elevation of the north section





Photo 33: Looking north, view shows grade level entrance at the north section south elevation



Photo 34: Looking east into courtyard formed between north and center sections





Photo 35: Looking southeast, view shows connection of north and center sections in the courtyard



Photo 36: Looking southeast, view shows rear block of the center section





Photo 37: Looking east, view shows center section west elevation



Photo 38: Looking east, view shows the center section west elevation entrance





Photo 39: Looking northeast, view shows center section rear block



Photo 40: Looking east, view shows rear courtyard between the center and south sections





Photo 41: Looking southeast, view shows north and west elevations of the south section



Photo 42: Looking east, view shows the south section west elevation





Photo 43: Looking northeast, view shows west and south elevations of the south block



Photo 44: Looking north, views shows south elevation of the south section





Photo 45: View shows typical marble window sill detail



Photo 46: View shows typical connection at windows and wall cladding