

TO: VT Granite Museum		WORK PERFORMED AT: Barre VT
DATE: 9-24-16		YOUR WORK ORDER NO.
		OUR BID NO.

DESCRIPTION OF WORK PERFORMED

Remove Old wall save old Boards rebuild wall with 2X6 framing Plywood on outside and cladding Insulate inside and install ruff cut Boards. Install 9 Windows To match others in Building

windows	14,202
Framing	6189
Ruff cut Board	2500
labor	15,000
spray foam Ins	8,000

Total \$45,891

All Material is guaranteed to be as specified, and the above work was performed in accordance with the drawings and specifications provided for the above work and was completed in a substantial workmanlike manner for the agreed sum of _____ Dollars (\$_____).

This is a ☐ Partial ☐ Full invoice due and payable by: _____
 in accordance with our ☐ Agreement ☐ Proposal No. _____ Dated _____
 Month Day Year Month Day Year