## MAP OF BRATTLEBORO EROSION HAZARD AND AFFECTED PARCELS erosion exposed sewer line, bank was armored Bridge 11, minor erosion pavement taken out **HAYES COURT** Garfield Dr **GLEN PARK** Greenleaf St The force of the floodwater, and not just inundation, caused extensive damage at Melrose Terrace and Glen Park pre-existing erosion was made worse by Irene Bridge 58 had minor erosion, stone was added **MELROSE TERRACE** LEGEND floodwater path where water was flowing significantly outside the main brook channel Building affected by flooding: total loss destroyed, or damaged to the point of no use in the future new channel temporary new channel created by floodwater major, structural repairable, significant structural damage major, other repairable, damage primarily to building systems (utilities), with structural impact less signficant flood deposition on road mud, gravel, debris removed by town minor generally minor water damage, water in basement road damage

