



*Existing view  
Looking East*

## Wallingford ER STP 0138(11) VT Route 140

### PROJECT MILESTONES

**Design Complete**

Summer 2017

**Bid Advertisement**

September 27, 2017

**Contract Award**

November 28, 2017

**Begin Construction**

Spring 2018

**VT 140 Closure/Earthwork**

June-August 2018

### Wallingford ER STP 0138(11)

**Project Location: Town of Wallingford in Rutland County on VT Route 140 approximately 3.18 miles East of the US Route 7 intersection.**

Wallingford ER STP 0138(11) is a Tropical Storm Irene Recovery Project which caused heavy erosion and destabilization of VT Route 140 in this location. During the recovery period, roadways were constructed into working order, yet some areas were not fully stabilized requiring more detailed geotechnical review and design to insure future stability.

This project consists of installing a wire mesh on the eroded embankment along the North side of VT Route 140 and installing soil nails to secure this mesh on to the embankment to prevent future erosion. This project will also consist of full-depth reconstruction of approximately 500 feet of roadway, and stream bank stabilization on the South side of VT Route 140.

Due to site constraints, there is limited space complete the necessary construction with all equipment that is required; therefore VT Route 140 will be closed for approximately 28 days. Traffic will be detoured during the closure.



*Existing view  
Looking West*



**Wallingford ER STP 0138(11)**

**Contractor:** J.P. Sicard, Inc.

**VTrans Resident Engineer:** Christopher D. Williams

**VTrans Project Manager:** Bruce Martin, P.E.


**Detour of Traffic:** Traffic will be detoured utilizing VT Route 103 and US Route 7.



*View looking West  
At area of stream to be stabilized*



*View looking West  
At slope to be stabilized*



*Detour Map*



<https://twitter.com/511VT>