

2022 School Facilities Inventory Report


BARRE UNIFIED UNION SD | BARRE CITY ELEM/MIDDLE SCHOOL | 50 PARKSIDE Facility Name:

TERRACE, BARRE 5641 - Combination - Main Building

March 29, 2022








Value of Assets/GSF \$85.55







Location Plan - Google Maps

FCI = 76.1%100.0% 90.0% 80.0% 70.0% 60.0% 50.0% 40.0%

FCI Distribution

Facility Condition Index (FCI) Compared to Portfolio

(See Last Page for Explanation of Terms)

30.0% 20.0% 10.0% 0.0%

Page 1 of 5 v2022-03-29





2022 School Facilities Inventory Report

Facility Name: BARRE UNIFIED UNION SD | BARRE CITY ELEM/MIDDLE SCHOOL | 50 PARKSIDE

TERRACE, BARRE 5641 - Combination - Main Building

Respondent Information

Date/Time Completed 2021-12-13 - 12:03 PM

Respondent Name Jamie Evans

Respondent Title Director of Facilities Respondent Email jevanbsu@buusd.org

Respondent Phone Number (802) 476-8119

Facility Information

School Type Combination
Building Identification Main Building

Stories

Building Area 125000 (Gross Square Footage - GSF)

Year Constructed 1995
Year of Last Major Renovation N/A
FCI (Depleted Value) 76.1%

Environmental & Safety Issues

Hazardous Materials No

Hazardous (HZD) Materials include -

HZD Issues are -

HZD Issues include -

Indoor Air Quality (IAQ) Issues Yes

IAQ Issues include Insufficient Air Change Ratio, Humidity (Too Low or Too High)

IAQ Issues are Major

IAQ Issues include Indoor air exchanges probably don't meet today's standards. Humidity levels are low in the winter months.

Fire or Life/Safety (FL/S) Issues Yes

FL/S Issues are Many of the concrete sidewalks heave during the winter months.

Other Risk Factors No

Other Risk Factors include -

Other Risk Factors are -

Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues No

ADA Issues are N/A

ADA Issues include N/A

Utilities - Adequacy

IT / Internet Service Adequate

Building Wi-Fi Coverage Adequate

Cellular Reception Inadequate

Water Service Pressure Adequate

Natural Gas/Propane Pressure Adequate

Electrical Capacity Adequate

v2022-03-29 Page 2 of 5

 Λ



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

				_						_	
Facility Name:	BARRE UNIFIED U	JNION	SD B	ARRE CITY E	ELEM/	MIDI	DLE SCH	00L	50 I	PARKSIDE	
	TERRACE, BARRE	5641	- Combi	ination - Ma	ain Ru	ildin	7				
2 11 2 1	TEITHUTOE, BITTITE	3011	COIIIIO	macion ivi	uiii bu	Trum (
Building Envelope - Roof	Single Dly EDDM/TDO/D\	(C Mamb	arana								
	Single-Ply EPDM/TPO/PN		C-RUL	Cost	/ Unit		Quantity	Llnite		Total Value	
Covers		EUL			•	C	Quantity				٨
Installed in		20	-7	\$11.00	/ SF	for	33,333	SF	=	\$366,667	<u> </u>
	Asphalt Shingle	5111	6 8141		/					IV. I	
Covers		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	3	\$5.50	/ SF	for	8,333	SF	=	\$45,833	
Roof 3 is			0.5111		/						
Covers		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		-	N/A	- /	/ -	for	-	-	=	\$0	
Roof 4 is											
Covers		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	/ -	for	-	-	=	\$0	
Building Envelope - Windows											
Primary Window System											
% of Windows That are this Type		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	3	\$60.00	/ SF	for	30,000	SF	=	\$1,800,000	
Secondary Window System					,						
% of Windows That are this Type		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	/ -	for	-	-	=	\$0	
Services - Elevators											
Primary Conveyance/Elevators					,						
Quantity of Stops		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		30	3	\$25,000.00	/ STOP	for	3	3 STOP	=	\$75,000	
Secondary Conveyance/Elevators											
Quantity of Stops	0	EUL	C-RUL	Cost	/ Unit		Quantity			Total Value	
Installed in	-	-	N/A	- /	/ -	for	() -	=	\$0	
Services - Plumbing											
Primary Plumbing System											
Area of building served	100%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		40	13	\$7.00	/ GSF	for	125,000	GSF	=	\$875,000	
Secondary Plumbing System											
Area of building served	0%	EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	/ -	for	-	-	=	\$0	
Services - Cooling - Central System											
Primary Central Cooling System											
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units	-	Total Value	
Installed in		-	N/A	- /	/ -	for	-	-	=	\$0	
Secondary Plumbing System											
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in	-	-	N/A	- /	/ -	for	-	-	=	\$0	
Services - Heating - Central System											
	Boiler(s)/System - Solid F										
Area of building served		EUL	C-RUL	Cost	/ Unit		Quantity	Units		Total Value	
Installed in		25	20	\$250.00	/ MBH	for	3,571	MBH	=	\$892,857	
Secondary Heating System											
Area of building served		EUL	C-RUL	Cost			Quantity	Units		Total Value	
Installed in	1995	30	3	\$62.00	/ MBH	for	3,571	MBH	=	\$221,429	

v2022-03-29 Page 3 of 5



AGENCY OF EDUCATION



2022 School Facilities Inventory Report

2022 School Facilities	s inventory Repor	τ								
Facility Name:	BARRE UNIFIED UNION SD BARRE CITY ELEM/MIDDLE SCHOOL 50 PARKSIDE									
	TERRACE, BARRE 5641 - Combination - Main Building									
Services - HVAC Distribution										
Primary HVAC Distribution System	Forced Air System (AHUs	s, Ductwo	ork, VAVs)	, 2-Pipe System						
Area of building served	100%	EUL	C-RUL	Cost / Un	nit	Quantity	Units		Total Value	l
Installed in	1995	30	3	\$18.00 / GS	F for	125,000	GSF	=	\$2,250,000	1
Secondary HVAC Distribution System	-									
Area of building served	0%	EUL	C-RUL	Cost / Un	nit	Quantity	Units		Total Value	l
Installed in	-	_	N/A	-/-	for	-	-	=	\$0	l
Services - Package Systems		-								
Primary HVAC Package Unit & Splits	Even Mix of Package Uni	its & Split	t Systems							
Area of building served		EUL	C-RUL	Cost / Un	nit	Quantity	Units		Total Value	l
Installed in	2000	18	-4	\$1,900.00 / TO	N for	50	TON	1	\$95,000	\wedge
Secondary HVAC Package Unit & Splits	-				l .	L				. —
Area of building served		EUL	C-RUL	Cost / Un	nit	Quantity	Units		Total Value	l
Installed in	-	_	N/A	- / -	for	-	-	=	\$0	l
Services - Fire Suppression				·						
Primary Fire Suppression System	Sprinkler System, Mediu	m Densit	ty/Comple	exity						
Area of building served		EUL	C-RUL	Cost / Un	nit	Quantity	Units		Total Value	l
Installed in	1995	40	13	\$5.00 / GS	F for	125,000	GSF	=	\$625,000	l
Secondary Fire Suppression System	Kitchen Hood or Comput	ter Cente	r Sunnras		I	-,			1 = 7 = 1	I
					**	0	11 miles		T-+-11/-1	l
Area of building served		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	_
Installed in	1995	20	-7	\$10,000.00 / EA	for	1	EA	=	\$10,000	<u> </u>
Services - Fire Alarm System										
Primary Fire Suppression System				0 1 / 11		0			T . 11/ 1	ı
Area of building served		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	_
Installed in		20	-7	\$3.00 / SF	for	125,000	SF	=	\$375,000	\triangle
Secondary Fire Suppression System				2			1			ı
Area of building served		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	l
Installed in	-	-	N/A	- / -	for	-	-	=	\$0	1
Services - Security Systems										
Primary Security & Low Volt System							1			ı
Area of building served		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	_
Installed in		15	-12	\$3.00 / GS	F for	62,500	GSF	=	\$187,500	\triangle
Secondary Security & Low Volt System			Average							
Area of building served		EUL	C-RUL	Cost / Un		Quantity	•		Total Value	l
Installed in		15	3	\$4.00 / GS	F for	31,250	GSF	=	\$125,000	l
Services - Electrical Distribution/Infrastructure										
Electrical Distribution/Infrastructure										ı
Area of building served		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	l
Installed in	1995	40	13	\$22.00 / GS	F for	125,000	GSF	=	\$2,750,000	İ
Services - Solar Power (PV)										
Solar (Electric Generation) Provided										
Owned/Maintained by School				Value of Solar PV Par						
Quantity of Panels		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	1
Installed in	-	-	N/A	-/-	for	-	-	=	\$0	
Ancillary Structures										
Ancillary Structures										i
Total SF of Ancillary Structures		EUL	C-RUL	Cost / Un		Quantity	Units		Total Value	
Installed in	-	-	N/A	-/-	for		-	=	\$0	l
Secondary Ancillary Structures										
Total SF of Secondary Ancillary Structures	0	EUL	C-RUL	Cost / Un	nit	Quantity	Units		Total Value	l
Installed in	-	-	N/A	-/-	for	_	-	=	\$0	
Additional Comments			-	·	1 -	I			, , ,	1

Additional Comments

v2022-03-29 Page 4 of 5





2022 School Facilities Inventory Report

Facility Name: BARRE UNIFIED UNION SD | BARRE CITY ELEM/MIDDLE SCHOOL | 50 PARKSIDE

TERRACE, BARRE 5641 - Combination - Main Building

Explanation of Terms

Explanation of Terms	
Projected Capital Planning Cash Flow	The estimated replacement costs of systems as they expire annually.
Facility Condition Index (FCI)	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
Total Value of Assets	The total estimated replacement cost of all the assets listed in the form.
Value of Assets per GSF	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
Facility Condition Index (FCI) Compared to Portfolio	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
Calculated Remaining Useful Life(C-RUL)	The current number of remaining years a system may be expected to perform in designed service.
Expected Useful Life (EUL)	The total number of years a system can be expected to perform in designed service when new.
Gross Square Footage (GSF)	The total square footage contained within the building for all floors/levels.
Cost per Unit	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
Quantity	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
Units	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
Ancillary Structures	Buildings on site that are typically known as portables, relocatables or temporary buildings.

v2022-03-29 Page 5 of 5