

### 2022 School Facilities Inventory Report

Facility Name: **CENTRAL VERMONT SU | WILLIAMSTOWN ELEM SCHOOL | 100 BRUSH HILL ROAD, WILLIAMSTOWN 5679 - Combination (PreK thru 5) - Main Building**


March 29, 2022

Total Value of Assets (Does Not Include Site/Structure/Walls/Interiors) **\$3,880,000**



GPS: 44.12364254731682, -72.54607278247592

#### Relative Asset Values





Value of Assets/GSF **\$110.86**




Site Plan - Google Earth

#### Projected Capital Planning Cash Flow



Location Plan - Google Maps

#### Facility Condition Index (FCI) Compared to Portfolio



(See Last Page for Explanation of Terms)

### 2022 School Facilities Inventory Report

Facility Name: **CENTRAL VERMONT SU | WILLIAMSTOWN ELEM SCHOOL | 100 BRUSH HILL ROAD, WILLIAMSTOWN 5679 - Combination (PreK thru 5) - Main Building**

#### Respondent Information

Date/Time Completed **2022-02-21 - 3:59 PM**  
 Respondent Name **Chris Locarno**  
 Respondent Title **Director Finance and Operations**  
 Respondent Email **clocarno@cvsu.org**  
 Respondent Phone Number **(802) 433-5818**

#### Facility Information

School Type **Combination (PreK thru 5)**  
 Building Identification **Main Building**  
 Stories **1**  
 Building Area **35000 (Gross Square Footage - GSF)**  
 Year Constructed **1990**  
 Year of Last Major Renovation **N/A**  
 FCI (Depleted Value) **82.3%**

#### Environmental & Safety Issues

Hazardous Materials **No**  
 Hazardous (HZD) Materials include -  
 HZD Issues are -  
 HZD Issues include -

Indoor Air Quality (IAQ) Issues **No**  
 IAQ Issues include -  
 IAQ Issues are -  
 IAQ Issues include -

Fire or Life/Safety (FL/S) Issues **No**  
 FL/S Issues are -

Other Risk Factors **No**  
 Other Risk Factors include -  
 Other Risk Factors are -

#### Handicap Accessibility (ADA) Issues

Handicap Accessibility (ADA) Issues **No**  
 ADA Issues are **N/A**  
 ADA Issues include **N/A**

#### Utilities - Adequacy

IT / Internet Service **Adequate**  
 Building Wi-Fi Coverage **Adequate**  
 Cellular Reception **Adequate**  
 Water Service Pressure **Adequate**  
 Natural Gas/Propane Pressure **N/A**  
 Electrical Capacity **Adequate**

### 2022 School Facilities Inventory Report

Facility Name: **CENTRAL VERMONT SU | WILLIAMSTOWN ELEM SCHOOL | 100 BRUSH HILL ROAD, WILLIAMSTOWN 5679 - Combination (PreK thru 5) - Main Building**

#### Building Envelope - Roof

Roof 1 is	Single-Ply EPDM/TPO/PVC Membrane								
Covers	100%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	2006	20	4	\$11.00 / SF	for	35,000	SF	=	\$385,000
Roof 2 is	-								
Covers	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0
Roof 3 is	-								
Covers	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0
Roof 4 is	-								
Covers	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0

#### Building Envelope - Windows

Primary Window System	Window, Wood-Frame								
% of Windows That are this Type	100%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	1990	30	-2	\$70.00 / SF	for	8,400	SF	=	\$588,000
Secondary Window System	-								
% of Windows That are this Type	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0

#### Services - Elevators

Primary Conveyance/Elevators	Wheelchair Lift								
Quantity of Stops	1	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	1990	25	-7	\$17,000.00 / EA	for	1	EA	=	\$17,000
Secondary Conveyance/Elevators	-								
Quantity of Stops	0	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	0	-	=	\$0

#### Services - Plumbing

Primary Plumbing System	Supply & Sanitary, Low Density (Includes Fixtures)								
Area of building served	100%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	1990	40	8	\$7.00 / GSF	for	35,000	GSF	=	\$245,000
Secondary Plumbing System	-								
Area of building served	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0

#### Services - Cooling - Central System

Primary Central Cooling System	None								
Area of building served	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0
Secondary Plumbing System	-								
Area of building served	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0

#### Services - Heating - Central System

Primary Heating System	Boiler(s)/System - Fuel Oil								
Area of building served	100%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	1999	30	7	\$60.00 / MBH	for	1,000	MBH	=	\$60,000
Secondary Heating System	-								
Area of building served	0%	EUL	C-RUL	Cost / Unit		Quantity	Units	=	Total Value
Installed in	-	-	N/A	- / -	for	-	-	=	\$0

### 2022 School Facilities Inventory Report

Facility Name: **CENTRAL VERMONT SU | WILLIAMSTOWN ELEM SCHOOL | 100 BRUSH HILL ROAD, WILLIAMSTOWN 5679 - Combination (PreK thru 5) - Main Building**

#### Services - HVAC Distribution

Primary HVAC Distribution System **Forced Air System (AHUs, Ductwork, VAVs), 2-Pipe System**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2000	30	8	\$18.00 / GSF	35,000	GSF	\$630,000

Secondary HVAC Distribution System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

#### Services - Package Systems

Primary HVAC Package Unit & Splits **Split Systems**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2000	15	-7	\$2,000.00 / TON	140	TON	\$280,000

Secondary HVAC Package Unit & Splits -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

#### Services - Fire Suppression

Primary Fire Suppression System **Sprinkler System, Medium Density/Complexity**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2017	40	35	\$5.00 / GSF	35,000	GSF	\$175,000

Secondary Fire Suppression System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

#### Services - Fire Alarm System

Primary Fire Suppression System **Modern Addressable Fire Alarm System**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2016	20	14	\$3.00 / SF	35,000	SF	\$105,000

Secondary Fire Suppression System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

#### Services - Security Systems

Primary Security & Low Volt System **None**

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

Secondary Security & Low Volt System -

Area of building served	0%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	-	-	N/A	- / -	-	-	\$0

#### Services - Electrical Distribution/Infrastructure

Electrical Distribution/Infrastructure **Main Distribution Panel w/Sub Panels and Generator/UPS - Medium Density**

Area of building served	100%	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	1990	40	8	\$22.00 / GSF	35,000	GSF	\$770,000

#### Services - Solar Power (PV)

Solar (Electric Generation) Provided **None**

Owned/Maintained by School -

Quantity of Panels 0

Installed in -

Value of Solar PV Panels: -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

#### Ancillary Structures

Ancillary Structures **Relocatable Building - Classroom/Office - Standard/Portable**

Total SF of Ancillary Structures	5000	EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
Installed in	2005	15	-2	\$125.00 / SF	5,000	SF	\$625,000

Secondary Ancillary Structures -

Total SF of Secondary Ancillary Structures 0

Installed in -

EUL	C-RUL	Cost / Unit	Quantity	Units	Total Value
-	N/A	- / -	-	-	\$0

#### Additional Comments

**2022 School Facilities Inventory Report**

Facility Name: **CENTRAL VERMONT SU | WILLIAMSTOWN ELEM SCHOOL | 100 BRUSH HILL ROAD, WILLIAMSTOWN 5679 - Combination (PreK thru 5) - Main Building**

## Explanation of Terms

<b>Projected Capital Planning Cash Flow</b>	The estimated replacement costs of systems as they expire annually.
<b>Facility Condition Index (FCI)</b>	The cost -weighted depleted value of the building compared to the total value of all its systems; overall percent of building useful life consumed by years in service.
<b>Total Value of Assets</b>	The total estimated replacement cost of all the assets listed in the form.
<b>Value of Assets per GSF</b>	The Total Value of all Assets in the form divide by the Gross Square Footage (GSF) of the building.
<b>Facility Condition Index (FCI) Compared to Portfolio</b>	The Facility Condition Index (FCI) of the building overlayed on the chart of FCI's for all buildings in the portfolio. Indicated by a red line in the chart.
<b>Calculated Remaining Useful Life( C-RUL)</b>	The current number of remaining years a system may be expected to perform in designed service.
<b>Expected Useful Life (EUL)</b>	The total number of years a system can be expected to perform in designed service when new.
<b>Gross Square Footage (GSF)</b>	The total square footage contained within the building for all floors/levels.
<b>Cost per Unit</b>	The estimated base cost for a single unit of a system. When multiplied by Quantity results in the total system cost.
<b>Quantity</b>	The amount of a system present in a building. When multiplied by the Cost per Unit results in the total system cost.
<b>Units</b>	The expressed unit of measure for a given system (GSF, EACH, TON, etc).
<b>Ancillary Structures</b>	Buildings on site that are typically known as portables, relocatables or temporary buildings.